



## SAFETY ALERT BULLETIN



**On August 14, 2005, at 11:30 a.m. a section repairman broke his right arm while changing a feed jack on a dual boom roof bolting machine. The section repairman removed the hydraulic hose from the feed jack, then removed the support pin from the jack, causing the drill boom to fall. When the boom arm fell, the repairman's right arm was caught causing a fracture.**

**Hydraulic actuated booms and arms should be supported against accidental falling prior to removing hydraulic hoses, pins and hydraulic jacks.**

**All equipment must be secured against accidental movement or falling when in raised positions before any work is performed.**

**ACCIDENT REDUCTION PROGRAM**