9/25/12
IRO 4 23 Black - dk gray wackesn at base of Lincolnshire N 20E 21SE
9/26/12 IRO-4115
E-W GON N 37°11.8 17 W80 22 36
Prospect pit or old sink in upper Beekmantown LS W of Cedar Run
9/26/12 BBG-6310
el 2150 b (correction ——)
N 37 11 880 W 80° 22.558
Fine micro xline dol overlain by siliceous barroved dol/cast and molds
N40W 20 NE
9/26/12 BBG 6311
big deer stand w/ deck ~ 2000 b ——
N37°12.097 W 80 22.348
head of hollow
IRO 4116 Ellett Siltsn red clay s.lt w/ s and b cds in end of RR cut at N37°11.830'
Bedding is ± w/dol W 80° 22.318
N75W 10 NE

26 IRO 8716 redux
ra - qtz cobbles
el 2100 Ta
N 37 08 262
W 80 19 507

IRO 897 redux - Roanoke
Valley Fault Rome / Elbr
N 37 07.917 W 80 17.833
walking N to

IRO 8919 N 30 E 70 NW
behind double wide
at N 37 07 993
W 80 17.905
brecciated dol

IRO 8920 N 34 E 70 NW
thinbedded gray dol
cleavage N 50 E / 60 SE
drive of new house
N 37 08 033 W 80 17 983
Akers 2681 George

Run

Stop 5.
IRO
Look for flat pebble cgl
algal lam, breccias

IRO -727 A

N 37°. 16 610' W 80. 318405

S S E dip at E end

NE dip at W end

well stratified middle

elbrook

APRIL 26 2013

ESN - 1426 MP 127.5

IRO -

IRO - 8423 upside

down Conococheague

IRO -

April 25 2013

IRONTO PHOTOS - I81

N 37.229343 W 80.242490 Photos of scarp and NW plunge ESN - 1426 A&B fault

ERO - 3625 green breccia layer in Fold limb II to row dipping N
N 37.227601 W 80.246685

IRO-621 B green breccia at new overpass
N 37.196271 W 80.269543
Google earth view

IRO 648 Google earth view
OT Synclinal hinge at
N 37.188 766
W 80.280 516

IRO 596 open trough
37.177825 - 80.248706
Sagg between two tight hinges

IRO 597 - overturned syncline w/ epikarst clay seam to road level N 37.171 994
E 80.304564

Tree Farm Johnson Lease

Parcel 3 Map 124

Sept 25
Oxide TS N 37°14.622
Mi 11.0 W 80 14.375
Stop 1 at end of Park Mtn Road (Reece Farm) Helderberg
SS, Friable, sample site
N 37° 13.955 W 19.187
Mi 16.5 park continue
to Stream 16.6 House at 16.8
N 37° 14.062' W 80°19.322

Stop 2 Pavement exp Huntersv
N 37° 14.142 W°18.435
Mileage 17.9

STop 3 NS RR park off
Myrtle lane
N 37 14 550 W8015 467
go to right above shed
24.7

mile 30.7 narrow
bridge N37 11 .728 W80 19 52
Stop 4A Park in
Patt. Paddy driveway
to walk to Fayette Co

STOP I 10 Oe → 06
traverse dry creek
beginning at N 37°13.777'
W 80 21.897

Stromatolites Thrombolites
"Sandstones" ripples
Tabulates x beds
burrow fills, algal ls



press cracks, TP structures
Top Uphill limit

823 N 37 08 960
W 80 18 830
TRUCKS USE RIGHT LANE

STOP 9 Bays 55
at Den Hill / North Fork
park at Church
N N 37° 11·207
W 80 21 152
Flagged Several Lupine
zones

ST

9/27/12
STOP 11 Cr "SS"
on CEDAR RUN
N 37° 899 W 80 23.248
"Ellett Rd on Main St
in B'burg

STOP Yellow Sulphur
N 37° 10.697
W 80° 23.855

Oct 8 '12 Joe Aylor
Virginia Uranium
231 Woodlawn Heights Rd
Chatham Virginia 24531
434 432 1016

Chuck Barley
College of William and
Mary Department of Geology
McGlothlin-Street Hall 215
Williamsburg VA 23185
PO box 8795
Williamsburg, VA 23187-8795

IRO 5216 N85E 40SE Mafs
5' ledge coarse qtz
arenite ocs above
sag pond or Karst Feature
at head of clearing

IRO 5217 Reddish brn fg
arenaceous sand and siltstone
ledges in road N56E 30SE
om6? 1" tiny void breaks
in road 60' above

IRO 528 Blocky vuggy
weathed brown ss ledges
N80W 24° SW SP @ N37°12'23.28 W80°19'04.92"

IRO 281 olive slate w/
thin grn ss layers
N79E 50SE cl

IRO 282 Fresh water spring
in olive slate/siltst
N70E 20SE cl 2290T

IRO 283 green ss/siltst
ledge, thin bedded
slaty cleavage @ 2580
N10E 22SE (bedding) Qtzite ledge
visible on slope to N!

IRO 284 N 60 W 10 NE
Med bedded Fine yellowish
gray to creme colored
quartz ss w ◇ chitinous
Fragments (Uniguloids)
S . el 26006
IRO 284 on middle knob
running cedar in woods
old Co ?
IRO 285 el 2650 thick
ledge of gray to white
weathering pebbly qtzite
limonite breccia/cgl Float
below on unconformity
N
APRIL 2011 IRONTO QUAD
DUNCAN FARM IRO 224
N 12 W 12 NE tan to
white chert ledge pavement
just below Duncans Gate
WP 002 el 1691 N 37°14 294
W 80 18.502.
IRO 225 N 37°14.477' W80°18.605'
WP 003 N 14 W 12 NE white
friable qtz ss Float 1823
along road - ledges in crk

4/4/11
Duncan Farm
IRO 223 quarry on Paris Mtn ~ 50' of white qtz ss more or less Friable N 20 W 8 NE at WP 004 N 37° 14.529' W 80° 18.753' el 1819
N 38 E 20 SE OC RT int. of Little Cabin Road - Highland (Photo
IRO 226 OC below cabin along old quarry road N 60 W 9 NE White qtz ss CWP 005 N 37° 14.605 W 80° 18.776' el 1891'
IRO 227 ledge exposed at edge of high field white med qtz arenite N 40 W 10 NE bedding, brn weathered Frac N 40 E 30 NW WP 016 El 1952 N 37 14.605 W 80 18.914
IRO 228 el 1982 N 37 14.710 N 10 E 12 NW WP 007 W 80° 18.883
Photo of White ss ledge
IRO 229 in next drain West of field WP 008 20 42 N 37 14.358 W 80° 18.948
hummocks plunge S 40 E at 10 Top 6cd N 20 E 12 SE

4/4/11 cont'd

extensional f. w 60° strained ca
photos

IRO 2210 cl 21602 cl 21606 WP 909
N 37 14 915, W 80° 18 834
brn weathd SS ledges
at valley head / small
offs, sand. fill in
valley below ledges above

1' rippled ledge
N 10 W 20 NE

IRO 2211 brn weath SS
ledges in stream bed
N 60 E 16 SE @ WP 10
cl 22 fq N 37° 14 931 W 80 18 884

IRO 2212 WP 011 cl 2361 N 37 14 906 W 80 18 989
Photos of med bedded
gray pebbly qtz SS overlying
thin bedded hummocky
cross bedded SS

IRO 2213 WP 012 cl 2471
N 37 14 .979 W 80 19 060'
vuggy limon cemented arg SS

Float in karst like pitted dip slope landscape ledges above N45E 20SE med bedded rnded ledges med grn ss w/clear chert sand as well as vein qtz ledges just bdow clearing visible on photo

Photos of wet organic soil w/Last years turnips crop in Sag pond or karst like feature at WP 013 N 37° 15.008 W 80° 19.101 el 2519

McM 881 N 20W 10 NE quarry boom at 1:30 thin laminae interlayers with white qtz pebble beds dipping into hole

IRO 2214 wp 014 N 37 15 000 W 80 19.305 el 2600 top 2680 GPS, ledge form on dip slope is karst like here it is clearly Ca ρ rock, pebbly qtz arenite Massive w qtz veins ~ 20' ledge on edge of ridge (photo) N 20E 12SE

4/4/11

MCM 812 N54E 20SE bearing on basal 50 ledge of WP015 N37 15 042 W80 19.178 el 2580'

MCM821 N50E 10SE el 2410 WP 37 15 122 W80 8912 0.6 el 2434 Pebbly brn weath ss ledge on road.

IRO2215 White friable gtz ss ledge makes dip slope N40E 18SE WP017 N37 14 773 W80 18 647 2252

IRO 2215 Thin-med bedded white gtz ss N50E 22NW

IRO 2216 N40E 16 11W WP018 N37 14 896 W80 18.696 el 2031 2080 6

IRO 2218 EW 20 s big (10'x2 ledges cross creek at el 1259 N37 14.787 W80 18 647 WP19

IRO 2219 Stream cascades through large blocks el 1250 6 below big ledges WP20 N37 14.739 W80 18585

4/4/11

No big ledges below!

IRO 2220 E-W 3S

tht x bedded white gtz

55 ledges above ck

ck jammed w/ blocks

at WP 021 N37 14 635 W80 18 519

el 1655 at stream forks

16206

IRO 2221 gray to brn orange

mottled chert ocs in road

N 20 W 10 NE - at WP 022

N 37° 14.612' W 80° 13.432' el 1607

IRO 2222 gray to brn orange

chert ledge base 10'

above stream N 20W 5NE

WP 023 el 1574 16306

stream 25' below dir strike

N 37 14 559 W 80 19 365

4/11/11 Frances farm IRO 237

N 75 E 10 SE White x bedded

sandstone ledge below

big falls WP 024 el 1617

N 37 14 885 W 80 18.264

MCM 89/el 1916 gray

nodular bedded chert in

road bed N 40E 23 SE

4/11/11 MCM 882 N 60E 20SE
pebble / edge in pavement
exposure at fork in road
WP 026 brn to orange weath
ss + sh pbls & cgl
N 37° 15.039 W 80° 18.481 el 2057
MCM 883 Jim Duncans Tractor
shed and range WP 027
37° 15.093 W 80 18.45 el 2073
MCM 884 WP 028 N 37° 15.145
el 2095 ledges W 80° 18.488
of brn weath, fine qtz
gr ss
MCM 885 head of drain —
trickle of H_2O in 100'
wide block field WP 29
N 37° 15.261 W 80 18.461
el 2120
MCM 886 WP 30 el 2121 ledge N50E 12 SE
N 37 15 257 W 80 18 416
el 2050 spring Flow 5 gal/min
good branch now thick bedded
cross laminated ss
MCM 892 N 60E 20 SE 4'
cross lam ledge, white
qtz ss WP 31 el 1847 N 37 16187
W 80 18226

41 W 11 MCM 893

Shelter cave bencat

Water Fall "Isaacs Rock"

N40E 20SE Massive cross bedded ss water

Fall at WP 032 N 37 15 40"
40' exposure W 80 18 203"
el 1700 ±

MCM 894 Oriskany iron ore overlain by 6' chert gray to dark gray aphanitic

WP 033

N 37 15.118 W 80 18.066
N 20E 20 SE el 1660±

MCM 895 WP 034 N 37 15.031 W 80 17.885
Shale chips begin at break in slope (el 1552

IRO 338 WP 035 el 1667
N 37 14.926 W 80 18 102
low ridges in woods w flt of Foruginous cemented ss (Oriskany)

WP 036 N37 14 291 W80 18 165 el 1500

N50E 20SE Needmore or milboro blk sh

IRO 339 N20E 20SE 20' bank dark mdsn + sh beds

WP 037 N37 14 544 W80 18 115 el 1423

Hngs N80W plunge 58°W

ap N80W 45 SW

N80E 40 SE Beds N40E 27S

4/12/11

N81W 58°E plunge

IRO 2314 Shale 20 sap N40E 24SE

IRO 3714 Cemetary WP 038 el 1145 ft N37 12 767 W80 17 046

chert Qt in parking area N22E 16 SE closely jointed yellow orange ss 1 ch° some gray

IRO 0 1 0 = Ridgely E-W brn weath massive bedded

4/12/11

Boonesmill References

Bartholomew and Lewis, 1984

Sinha and Bartholomew 1984

Fokin 2003

Nelson 1962

Pebbly Sandstone E-W 295

WP 039 N37° 12. 526 W80° 17. 349' el 1453 Overlain by light gray fine qtzite or chert with thin beds of light gray green fissile clay shale

IRO 3715 WP 40 N37° 12. 578 W80° 17 24 N40E 20SE Massive dip slope held up by ledge of brown weathrd coarse pebbly ss el 1455

IRO 3716 WP 41 N37 12 604 W80 17 19 Massive fine grained white to pink qtz ss ledge 1446 N 10E 20SE

IRO 5323 WP 42 1531 N37 12 403 W80 17 784 N60E 24 SE slab on d.p slope above slate float

IRO 5224 bench in Millboro Sh
N 72 E 40 SE bench 25
650 m 8 m highwall @ WP
043 N 37 12 363 W 80 17 753
4/13/11
IRO 5219
N 76 E 38 SE bladed Shale
w/ slaty cp cleavage
WP 044 el 1452
N 37 12 151 W 80 18.717
IRO 5324 N 80 E 20 SE
Devonian Sh/Slt Sh Oc
on S side of N Fork
below house - tan Sh/=head
more or above?
IRO 5325 ledge N 48 E 56 SE
at top of Flat iron el 1610
WP 045 N 37 12 462 W 80 17.739'
el 1692
IRO 5326 el 1795 WP 046
N 37° 12.549' W 80 17 687
N 35 E 30 site below at top
of Flat iron, many blocks
Massive pebbly SS, Ferruginous
SS Float below ledge = DO

NE end of Callaway along Hales Cr
MSW 591 garnet gneiss at contact,





4/13/11 cl 1839

IRO 291 N80E 30SE
large flatiron ledges on break in dipslope at WP 47 N 37 12 600 W80 17.675'

Coarse pebbly ss, massive-thick bedded, X lamination karst like topography = landslide head walls?

IRO 292 N 50 E 30SE
brn weath qtz ss w/ pitted surface make pavement in road at WP 100' from gated 1872
48 N 37 12 637 W 80 17.643

IRO 293 orange-white weath qtz ss ledge makes pavement in road N 30W 16NE at WP 49 1903 N 37 12 870 W 80 17657 1903 b

IRO 294 orange white ss ledge in road bed at 1962 at turn up hill N 30 W 10 NE at WP 50 N37 12.971 W80° 17.743

IRO 295 big spring above cabin root zone at WP 51 N 37 12.954 W 80 17.897

4/13/11

orange mottled yellow clay soil where road cuts through colluvial deposit in cove above

IRO 296 N10W 20NE white qtz ss ledge below Road as turning uphill at WP 52 el 2103 N 37 13 017 W80 18 002

IRO 297 pebble ledge N10E 30SE at game clearing el 21806 WP 053 N 37 13 070 W 80 18 123 el 2141 What a beautiful View up the valley to Bare rocks

IRO 298 new house spring 1m Om6 WP 54 el 22 2235 N3713 056 N 20W 20 NE in shale, pebbly orang ss at turn ~ 30' from contact N40W 34 NE 60' wide alluvial fill along stream below spring

IRO 299 pebbly brn - light gray ss ledge in road N5 20E el 23606 2352 N37 12917 80 18247

4/13/11

IRO 587 shale and thn bedded orange weathrd graywacke float in field clearing at WP 057 2513 N37 12.848' W80 18.460' el 2475 topo 2580 b —

IRO 588 Massive (1-3') cgl beds interlayered with thin bedded white X/am ss N8E 10SE el 2591 at WP 058 N37 12.805 W80 18.379

IRO 2910 continuous 20' ledge of cgl ss along break in slope blocks on Omb bench below N18W 16NE at WP 059 N37 12.754 W80 18.299 el 2488 lithic cgl F/t on bench

IRO 2911 just above road ledge continues from above N28W 8NE WP 37° 12.707 80° 18.190' 2445 el 2360 b

IRO 2912 el 2180 N40E 18SE big ledge, white qtz arenite coarse, massive bedded WP 61 N37 12.577 W80 18.043 2201

IRO 2913 N60E 14 SE bg ledge makes Flat iron pavement on dip slope just above road at WP 62 N 37 12 583 W 80 17 948 - 2093 2000 6

IRO 2914 orange yellow weathered shale saprolite and wet Omb clay soils in hollows N 75E 20 SE slaty cleavage in road bank below bore site WP 63 N 37 12 553 el 2134 W 80 18 225 2140 6

IRO 5 2 20 N 76E 24 SE White Fg qtz arenite ledge WP 064 N 37 12 434 W 80 1963 80 18 406

IRO 52 21 N60E 30SE thk bedded brn lith ss lithic cgl flt above in top of Omb el 1950 6

IRO 5222 N60E 30SE ss + sh Omb in gorge Qtzite 200' ds el 1980 WP 06 1952 On narrow path 37 12 400 80 18 487 in gorge

IRO 5223 Ledge of qtz arenite crossing ck road switch back at WP 067
1650 N 37 12 346 W8018.492
1756 N 75 E 35 SE pebbly

IRO 5224 WP 068 el 1655
N 37 12 296 W 80 18 508
coase lithic cgl
in roand bank
3" clasts

in gravely matrix
orange brn weathered
N 60 E 55 SE orfoliation
surface — no bedding

IRO 5225 N 70E 60SE contact between huntersville and Needmore
huntersville contains green ( ) shale/ss nodular weathering cgl beds and grey chert WP — Needmore
ochreous saprolite w/slaty clean
WP 069 N 37 12 274 W 80 18553
el 1607 17006

IRO 5226 N 60 E 20 SE strong NW jointed black slaty arg

upper part of stm 15 block
Field - rock Fall area

IRO 5227 hinges in blk slaty argillite f-w 36 ↳ sinistral folds

IRO 5228 spl of ls concretion in Millboro Shale
WP 70 cl 1447 N 37 12 .154 W 80 17.947
finc, pyrite rich ls w calcite Vein N 70E 22 SE

4/15/11

WP 71 cl 1525
N37 13 888 W 80 18 360
IRO 255
N S 10 E thick X bedded ss ledges at creek

IRO 256 N 20W 10 NE 30'
Exposure cross bedded gray ss in Confed camp site el 1580 ± some Fe cement FH
IRO 257 N 10E 14° SE 40' sect
Massive to med bedded thin X laminated gray quartz ss el 1700
WP 72 1769 N37 13 758 W 80 18 604

Check Faults along strike
Check sym bols
4/15/11 WP 73 el 1800
IRO 258 N 37 13 809 80 18.657
Shelter cave / dead calf
Coyote den? 1730 h
20' exposure gray thk
bedded qtz ss, 100' wide
alluvial belt w/ blocks
up to 10' long
IRO 259 Boulder stream issues
from SW stream
two rock foundations
12 x 12 huts? Campsite?
WP
all strike to N wall (30' exposure)
WP 074 N37° 13.785' 80 18.836' 1841
IRO 260 N 12 W 10 NE 4'
bn weath ss sc dip
WP 075 < VS upstream
N37 13.784 W 80 18.833
1900. (1820) b Knick point
IRO 261 big block field
800 - 1000 long 300 wide
blocks up to 15' long 3' thk
bench above on spur - cross flt?

IRO 2512 el 1940 6
beds in stream bottom
NS 10 E prominant
fracture in stream bottom
pavement look "Fresh"
NS vertical circular 3'+/-
or slump above at WP 76
50 year old poplars on 2006
slump N 37 13 204 W 80 18 997
IRO 2420 ledge of cross bed
white friable pebbly ss
w/ blueish quartz granules
@ in med to fine qtz
mtx above cabin site (stone
pile + flower beds along
old trail at WP 077 N37 13 5-7
W 80° 19.164' el 2228 3' ledge
N 10 E 10 SE
IRO 2513 contour road is
in white sand soil w/ ss
float next to clearcut
at WP 78 N37 13459 W80 18 979
el 2235
IRO 2514 N 50 W 20 NE 3'
pebble qtzite ledge overlo
-lor orange weathered
thic cgl thru across

ss/sh ychips, in road
at WP 79 N 37°13.352' W el 2279
W 80° 19.017'.
IRO 289 N 56 W 20 NE
yellow orange shly sap
in roadbed at WP 80
N 37 13292 W 80 19 064 verg steep
Topography Omb el 2212

IRO 2516 N80W 30NE 6'
pebbly qtzite overlies
bleached fossiliferous
muddss w finely ribbed
brach shells WP 80 81
inferred molds el 2133
N37 13403 W80 8.682

IRO 2517 gray to orange
brn weathered chert
in road, nodular text
verg fg
N 20 W 1 E NE
Big Island Log & Lumber
Co. Bedford, VA

IRO 2518 N80E 18 NW
pavement wh friable gtz ss
in road el 2003 6

IRO 2519 Chert ledge
in road at 1650'
N 5W 10 NE
100' above fence

4/26/11

IRO 2440 N28E 12 SE
grn sh/ss contact in drive
to p83 el 1421 N37 11 611
Knows Fred Read W80 19 996

IRO 2441 N35E 14 SE os
Owr WP 084 el 1628
N37 11 732 W80 19965

IRO 517 redux on lipsey Fm
@ WP85 el 1677 N37°12.011
Ledge of qtz ss W80°13.247
in drainage green brn ss sap
below on road bed

IRO 5117 redux WP 086 el 1717
N37 11 956 W80 19 390
chert Float in drain
above switch back drive
to trailer house 1660'

IRO 528 redux @ WP 087
N.37 12.003 W80 19426 el 1785 m40'
Ledge of: hematite stained
fine qtz ss (Omb or Lunetta)
or Srh or Dor ? Position
on hill above semi karst area
w/ abd Chf flt down slope
suggests Helderburg

4/26/11

IRO 5142 N 24E 20 SE ledge ~
Forms spur ridge approx
strike based on topo exp.
WP 88 cl 1809 el 1750 ft
N 37° 11.953 W 80° 19.512
Conglomeratic qtz arenite
massive bedded Sh chips
in soil to west blks in drain

IRO 5143 N 20E 15 SE photo
qtz pbl cgl ledge in stream
at WP 89 N37 11 954 W 80 19 557
Photo of ledge to SE cl 1856
1750 ft Sag just Fell above!

IRO 5144 Gnarly chert ledge
SS below N 44E 15 SE
6' thick WP 90 N 37° 11 895
1838, 1780 ft W 80° 19 665
Ledge traceable 100 m
blocks in valley

IRO 5145 SS ledges below
chert road wraps around



cl 1845

N 37° 11.917 cl 1750 ft
W 80° 19 702

4/26/11 cl 1800 b Photos
IRO 5146 WP 91 el 1879
brn weath slaty arg in
stream bank N60E 40SE
N37 11 991 W80 19 593
IRO 5147 pht. of weath
fe cemented Helderberg
ss in road at WP
93 el 1605 N37 12.012 W80° 19.226' 15956
ss interval 35' wide
on road then chert flt
4/27/11 el 2200 lg blks 48
qtz pbl cgl on spur
at switch back
IRO 5149 N45E 15SE
orange yellow ss f
sh sap in road
cut (0 mb at 2260 b
2300 Topo (40' correction)
IRO 5150 el 2100 b sh sap
in embankment, qtz blocks along
ridge line to west and
nose to east
IRO 5151 4' qtz ss ledge
on flat icon at el 2030 b (on
Tipsey Ridge) N30E 28SE

4127 /11

IRO 5145 redux
black slate in
drive below house
SS N36E 20SE
photo of 2 ledges
on road side el 1850
IRO 5152 el 1700 6 Otz
SS overlies weathered
Shale N40E 30SE
to bend by power line

IRO 5153 el 15006 ledges
Omb SS/sh 300'
Cut 20' high N34E20SE
Normal Fit N40E 60 NW
check ✓ photo
el 14806

Todd Walters —
9:30 pm —
Leon — B, bbq

IRO 459 Photo of kilns at old lime plat across cedar Run

BBG 661 N40E 50SE sheared gray and lt gray algal boundst in upper Beekmantown micritic ls beds in quarry openings along RR

IRO 411 Photo of Oc of fine, lt gy lam dol in upper Beekmantown N64E 72 SE

IRO 412 at E end of cut Photo from above N14W 20NE

IRO413 at quarry N18E 22SE

IRO414 on trail NW of cut, nodular upper beek grey ls N60E 64 NW

IRO 415 N40E 28 SE
Massive bound stone, and micrite with tan dolom. partings large spring at corner
Grannie Walters

IRO 416 N 50 E 20 SE
burrowed argillitic gray micrite across From Bobs Woolgrine pasture

IRO 417 N S 20 E low lying pavement /s exposures in Gen M, lawn at corner of Deercroft and Lusters Gate

IRO 418 N10E 20SE
Massive Med gray grainstone photo w/white calcite veins

IRO 171 N4E 28 SE
black argillaceous lst slaty argillite w/ pencil fine

IRO 7430 EW 605
cryptoalgal laminite dol
creme to light gray
WP 583 N37 08 618 W80 22.248

IRO 7431 gray lam dol
thk bed oc on crest
N78E 80NW WP 584 el 2087
N37° 08.791 W80° 22.398

IRO 7417 redu E-W 80 s
photo of X bedded sand
WP 584 N37°08 796 clo dol
el 2095 W80° 22 053

IRO 7432 N80E 65SE
Laminated gray ls and
ribbony bedded dol ls
(blue and tan) WP 585
N37 08 745 W80 22 305
el 2121

IRO 0312 Red and grn slaty arg. ledges
Form Knob on pipe line WP 139
N37° 12.454 W 80° 15.347 el 2008
N22W 50SW

IRO 6313 Red and Grn arg ocs
on road in Pedlar Hills Preserve
at WP 139 N 37° 12.442 W 80 15 148
el 1652 N 30 W 20 NE

IRO 399 WP 140 N 37° 12.544 W 80° 15.191
el 1697 in hollow on road oc of
grn slaty argillite N55E 60SE
slaty cleavage ~~N 30W 20 NE~~ arg ledge
IRO 3910 N38E ~~46~~ 5E grn arg dol
and grn arg ocs along roadside
WP 141 N37° 12.533 W 80° 15.135
ESN 1710 WP 142 N37° 12.606' W 80° 14.963'
el 1536 Dol ledge on hill to E N20E 40E
Karst spring from cave (1' hole) Photo
in Stream bank below ledge (Ecl?)

ESN 1711 WP 143 N 37° 12.722 W 80° 14.79
el 1436 ledge of frac dol N12E 42SE
on steep slope SE of stream ~ 100' NE of Pt.

ESN 1712 WP 144 N37 12 805 W 80 14.654
el 1365 N22E 24 SE
2' ledge chrty dol

ESN 1713 gray dol ledges behind
ruins N 20W 24 NE 2' ledges on
hillside Red tail hawk soaring over
site

IRO 0313 on logging road into
PHP Maroon and green argillite ledges
in cut N30W 20NE WP 145
N 37° 12.403' W 80° 15.047'

ESN 4114 WP 146 Y/W weath. platy dol
N 37 12.186 W 80° 14.507 el 1359
N 10 W 14 NE, Karst at turn

ESN 4115 WP 147 N 37 12.037 W 80° 14 452'
el 1328 N 35E 14 SE Cross jointed
thick bedded gry x/line do(
ESN 4116 massive bedded gray do/
then shaley weath yellow gry
dolomite (N64E 14 SE w
pods of polymict breccia. WP 148
N 37° 12.120 W 80 14 385 el 1320

ESN 4117 Massive Rusty weath
x/line dol w/ platy inter beds
N 70 W 40 NE WP 149 N 37 12 237 W
el 1279 W 80 14.353

ESN 4118 Matrix Fam Cem
WP 150 N 37 12.409 W 80 14 35 7

IRO 514 Rock Fall site
N 70 E 24 NW ledge Photo
u/ shale below 15' thk
qfzite N 37°11.762 W80 19.333
el 1413 WP 234
IRO 515 Fagg Cgl site
N20W 3 NE gl ledge crosses
North Fork at WP 235
N 37° 11.721 W 80° 19.453
14.09 Faults trend N30E
down to SE 80° dip
3/17/10 Falls Ridge Preserve
IRO 543 1st 5' travertine bank
at WP 236 N37°11.522 W080°19.231
el 1507 (1340) 1460 T
IRO 544 WP237 N37°11.454 W80°19.168
WP 237 el 1493 3' travertine bank above
grn Fine gr ss + argillite (Ort) Photo
beds steepen up stream
IRO 545 Photos of kiln and OC
on SE bank, 60' cliff of tufa
on W side below? Fault - WP 238
N37°11.418 W80°19.144 el 1551 (Top)
15' □ square ∩ 30 IRO 5510
Ort thk arg m sltst ss - slaty arg
grn wt Mica fetal folds hinges plunging

IRO 5521 Massive burrowed gray x line dolomite lt-dk gy N44W 5° NE WP 251 N37 11 132 W80 18.671 cl 1853

IRO 5522 Breccia core of Fold or ancient sink fill

A N35E 20 NW B N80W 8 SW

WP 252
N37 11 031
W80 18 863
1620

IRO 5523 N34E 52SE gray vuggy dol w brecciated argillite beds WP 253 N37 11 064 W80 18.987 cl 1613

IRO5524 N45E 36SE gry. Fluggy dol N37 11 143 W8019.011 cl 1584 WP 254

IRO5525 N86W 40 NE tk bded gry dolomite across from spring may show back thrust bedding dip shift From 40 NW to 20 NW

IRO 5526 Eren N20W 10NE thin laminated dol w/ relief on lam looks like fco N84W 1C NE

IRO 646 N 70E 20SE
thin bedded gray dol
IRO 647 N 30E 50SE, dol
Max meadows breccia sap
on hilltop to E & W
IRO 648 N 10E 20NW
thn bedded gray lam
dol + phyllite w MMb
pods tight folds
~ S Z

N↑S
plunging NW
N 30W 5 NW plunge
AP N 20W 40 NE
IRO 564 N 40E 20SE
thk bedded gray dol
IRO 565 N 20W 24SW
Thin bedded gray dol.
New Cem to N W
Pond between road and
IRO
IRO 591
N 20E 40SE platy thin
bedded dol, breccia
block across road

IRO 581 brecciated gray dol, some thin bedded N50W 65 SW orange ocheous sap 2 photos one of open vuggy text one of chert clasts in fine dol mtx

IRO 582 highly fract dol f/s NS vertical in road

IRO 593 N48E 40 SE thk bedded gray dol ledge, breccia below

IRO 594 N60W 5° NE thin bedded dol above road to E

IRO 595 N40W 50 NE thick bedded brecciated dol on road embankment

IRO 596 N74° W 60NE thin bedded platy dol in road bank. Dol in stream bed below Massive algal f/s + dol in tight turn below

IRO 7320 5/5/11

not on map because of corner effects EW 30N ribbony dol bed over lys algal bed 1

IRO Landslide 453

Rob Carman 5/28/11

37° 11' 03.53 N

80° 20' 49.47" W

photos on 5/30/11

IRO 454 N8E 30 SE red grn thk bedded ss w/ carg interbeds Obz

~~IRO 455~~ in drive cut at el 14606

olive grn to yellow argillite and fine ss (omb)

bedding N8E 32 SE

cleavage N10E 60 SE

mn strong green veining N20E 80 SE box work

breccia bed cuts red and yellow arg in Obz

conjugate joint

5/30/0

N 05 E 80 NW (broad) Conjugate

N 20 E 75 SE Fract

IRO 456 Greenish gray to tan weath slaty argillite cleavage in Wilson Ck below bridge N 10 E 30 SE

IRO 457 similar arg cleavage in Cedar Run above bridge N 40 E 82 NW on 2" ls or ss bed projects above water

IRO 457 Tan weathered slaty argillite (Oe N 20 E 18 SE

IRO 458 Massive bedded Beekmantown dol below road in RR cut N 4 E 26 SE

IRO 459 N 2 E 15 SE Massive gry dol w/ 1' thick thrombolite bed in upper Beekm.

5/5/11 IRO 5526 on 1900' Knob platy dol ledge to SW N50E 40 NW of 1910 ft N52E 60 NW mottled burrowed dol. on NE Nose

IRO 5527 Light grey argillite Float to Knob up Knob N60E 20 NW Massive dol ledge on NE Nose sinks all around 3-6' wide 8' high cave passage on joint N80W vert. bed in thin bedded dol + arg N60E 10 NW

IRO 561 platy + thin bedded dol on nose in old overgrown Field clearing N70W 20 SW

IRO 562 orange weathering silic dol breccia on old road at el 1620 ft

5/5/11 9miles to Falls Ridge

IRO 5338 N70E 30° NW
dk gry argillaceous
limestone (Oc) low
OCS on trail below
Max Meadows type brec.

IRO 5339 sh + gtz ss (brn tgy
Float) Oba on ridge above
saddle to NE of road
intersection el 1580'

IRO 562 N20W 50SW
platy gray to brn weath
do/ ledges on trail
at el 1810'

5/6/11 IRO 5340
N54W 60 NE Mass lam
brec do/ by garage
20° NE ledges to right

IRO 644 N60E 40
SE limb of anticline in
thin bedded elGroot
E-W 20 NW NW limb
Photos N40W 80 NE gray
algal dol/ls

IRO 645 N80W 50 NE
massive gray brecciated do.

IRO 5435

IRO 5436 Trail crosses ls el 1925
beds / blue gray and yellow brn
N 60E 40 SE WP 573 N37° 11.124 W80 19.802

IRO 5437 gray frac dol ledge
Cross Frac N8W 80 NE
bed N80E 70SE WP 574 N37° 11.169 W80° 19.798
el 1930 near top of knob

IRO 5438 Folded thin bedded
brecciated dolomite ledge
N 10W 50 SW ↑↑ 5 folds S10W S
WP 575 N37° 11 208 W80° 19. 791
el 1831

IRO 5439 red and brown ss
cobbles hang in shale rich
regolith below chorty dol ledges
WP 576 N37 11 304 W80 19 704 el 1942

IRO 5424 b at base of 65 seq
photo of ore bed (in)
cgl. ·5F+ thk E-W 12 N el 1482

WP 577 N37 11 029 W80 19.573

IRD 7425 N80E 80° SE
gray chert layer in soil
2' thick at WP 578
N 37 08 483 W 80° 22.249
IRD 7426 N10W vert chert
stringer in road
IRD 747 redux ~~NW~~ 70N
Thn to thk bedded dol.
dk grey weathes light
thin siliceous silt lam
WP 579 N 37 08638 W80 22 232
el 2072
IRD 7427 spring at
WP 580 N 37 08 596 W80 22.265
el 2073
IRD 7428 big flowing spring
with spring box and house
WP 581 N 37 08 565
W 80 22.236
IRD 7429 black limestone
with coarse blocks of
chert (Chepultepec)
N40E 20NW on pond
bank at WP 582 N37°08.594
W80°22.348

BBG 333 blue gray micritic limestone el 1855 N70W 15 NE

BBG 334 is at el 1750 & N10W 20 NE stylolite along bedding

IRO 115 N20W 10 NE el 1720-30 & dk gray dol. thk bedded chts

IRO 116 above spring (septic) There is gently dipping outcrop of thin bedded argillaceous ls and dk gray slaty argillite el 16006 N20W 10 NE

IRO 121 el 15776 cobbles and pebbles as well (ss) as shaly clasts in road embankment

IRO 122 ledge of coarse grained ls in creek below bridge

IRO 123 EW 30S sh/arg ls in roadcut

IRO 124 N10E 20 De shly ls sap el 16001

shale chips = Omb
N 37° 14 207 W 80 20 012
IRO 132 el 2140 b
olive green slf sh & ss float
el 2130 red to pale pink
slft mdsn float at IRO 133
N 37° 14.317 W 80° 20.605'
IRO 134 N15E 22SE bpo
in hole cut on embankment of farm road at el 2080 T
N 37°14.365' W 80° 20.830'
IRO 135 N60E 16 SE el 2220
N 37° 14, 208 W 80° 20.723
IRO 166 el 2375 + 2377 b
blocks of wh/lt gry.
cg cgl ss on flat
top erosional surface
N 37° 14.088 W 80° 20.615'
105 pm lunch Possible sinkh.
deposits? Ochreous sh wreath
on top of round knob
IRO 167 el 2500 b Fenceline
in cut across steep spur
olive weathered Omb sand, arg
ls, sh + grainstone (spl)

11/3/11

IRO-1-6-7 contd N20W16NE
N 37° 14.102' W 80 20 467
photos and rocks pls

IRO 168 coarse cgl blks
in debris flow deposit
el 2150+ (2200?)

IRO 156 el 1850T on
old wagon road large blks
of Conglomerate (Dr
N 37° 13.932 W 80° 20.882

IRO-157 N 20W 20 NE sh
bank across from cabin
site on side of debris flow
deposit el 1780? N 37 14 002 W 80 21.054

IRO-158 N10E 16 SE on
side of debris as above

IRO 158 N 10W 18 NE
N 37 14.212 W 80° 21.458

IRO 159 N20W 5 NE
black shly ls in RR

IRO 1510 N20W 16 NE
thin bedded argillite,
tuffaceous ls in road
N 37° 13.393 W 80° 21.48
~10-20' ls, thin bedded
blkish clay

IRO 1511 Fossiliferous massive bedded ss/s outcrop s.r. road at N37 13.390 W80°21.402 N10W 20 NE

IRO 1512 ocherous weath calc argillite in road cut N18°W 12 NE N37 13 385W 80°21.173

IRO 1513 N20E 18SE hill cap w/ blocks ocherous calc argillite at N37 13.417 W 21.023

IRO 1514 Bays SS at el 1900 ~ 20' SS/ledge above Orchers brown sh soap (calc) N37 13.490 W80° 20.872' N20W 16 NE

IRO 169 el 20606 at feeding sta cut in Omb, m-f bedded fossil hash. beds N20W 28 NE, N37 13.513 W 80° 20.033'

IRO 192 el 20506 at end of ridge on TMH fence N10W 4 NE ocherous and gray weath ss=(Ob

N 37° 13.296 N 80 20.857

1 Outcrop on Pence Farm
IRO 172 Black argillite w/ slaty cleavage thin (1") Limestone beds N 20W 65W
IRO 183 Same as above N50E 40SE in grassy yard on North Fork
IRO 173 by creek irregularly fossiliferous med gray Wackestone lt gry argillaceous ptings Limestone w/o chert N 20E 16SE photo
IRO 174 in curve First cherty beds exposed massive med grained gray wackestone w/ black chert nodules that weather yellow brn, nodular beddings N 16W 20NE
IRO 175 just below Oe contact (black arg) above is Wacke N 30E 16SE as above & giant ceph

IRO 176 ls tan bedded at top N60W 20NE arr strike N70W

IRO 177 N40E 10SE cephalopod hash wacke grey to brn weath

IRO 178 Massive rnded N10E 6SE grey ocs of fossil hash wacke sh (on corner) below on NC road ocs of gray micrite, thick bedded (photos) ~ 6' bed then arg ls below N22E 6°SE. probably Not

IRO 179 el 16506 dolomite ledge in road ditch N18E 30SE Tan to gray



some sed breccia some burrowed = upper Peak mantown

IRO 180 N12W 8NE Mottled gy + brn-tan ls

NOTES 1/13/12

IRO 1420 20' cliff massive gray irregularly bunded wackstn (Photo) N37 13.878 W80 22.000 N5 15E

IRO 1421 ledges on hill slope N8E 15SE blue gray micritic ls massive ledges just above fenceline bend in road N3713.853 W80 22.045

IRO 1422 thn bedded reddish coarse/fine Ls overlies fine gray dol N5 18E top Ole N37°13.895 W80°22.022

IRO 1423 Cemetary on E rim of 50' dia doline in Ol at N 37 13 767 W 80 21 933 Jesse Trussel 1919-1957

Jan 16 IRO' water L 1728 Ed N BS shale o.t Crop Bridge Abutment N 8 W 10 SE Clev EW Dip 50° S Loc N 37° 12.725 W80° 21.675

1729 Fold N26W INC 24 NE Boudon ~~plan~~ N 70 E (PIC) plu N 10 E parall to pencil clev N 37 13.022 W 80 21.737

IRO 185 Ed Sh Bed N 50 W 20 NE (PIC) N 37° 12.092 W 80° 21.557'

photo

Day Runners

NOTES

Cleav PIN interv.
Plong Due E at 12
Fracts stop down E on bed



180 186 Lt yr Lam arg ooz
Lime or Calc argu
N 39° 13.075' W 80° 21.327'
Bed Str N 20W Dip 20E
Bed Cl parallel

Item # 033-3

gray micrite below in front yard at el 1585

IRO 171 l el 1700 b dol, gry, burrow mottled w/ chert in ditch N10E 20SE / grades orange clay sap with tan partings

IRO 141 Mass bedded algal laminate w wavy-wvd aspect gray xline dol/mtx N 20 E 18 SE

IRO 142 N30E 16SE inter bedded ls + dol some pebbly, bone, burrowed beds el 1630 some tan laminates

IRO 143, just past Hickory Hill drive blue gray micrite ls ~ 10' thk overlies dol, overlain by thk bedded dol N10E 16SE Very cherty soils in woods below

IRO 144
Blue gray ls, N12W 14NE
micritic texture with
calcite "eyes" On
IRO 145 dol, lt gy rexline
chrty regolith blocks
in roadcut ~ 50' above ls
IRO 146 of 1560 gray
wakestone w/ irreglar
bur. bedding (massive)
dk gry chert, N14W 16NE
photos
IRO 147 top ls in creek
bed photo N 10 E 18 SE
IRO 148 photo of Edinburg
slaty clean argillite
N30W 50 SW prominent Frac
N10 20 SE. upper sl dep
comes to road at Hahns drive
IRO 149 soft sed def
in Oe (bedding) N30E 20SE
S60E Df ~~~ lineation (hinges
plunge E 10
IRO 111 argillite Oc at grap loc
is bound ~~~ bk slaty arg below
N 2W 12 NE
SAMPLE FOR PALEO

May 30 2011

E trailer, Com

800 298 8924

12 - 6 pm Sunday

#23210" brake assembly (Dexter

Left & Right 10 x 2¼ 37.65

16 nuts 0.25 = 4.00 (#6-17)

16 lock washe 0.15 = 2.40 (#5-8)

Brake assembly 84556UC3

Drum

4 drums at 62.95

84556403 5 on 5 (3500)

#4763 ground wires

ring terminal w/ stock

290-991 dust cap

adjust to tight

back off 10 clicks

Wire 10 g F to b

jumpers

Scotch lock For 10

Gauge on Jumper

tape connections

loom clamps

T pole brakes

blue to blue brakes

white ground

IRO 1410 massive bedded gray wackestn w. dk fossil hash layers white calc veins along stratificat. N24E 18SE

IRO 112 N4ZE 18SE gry mottled wäcke stone in sinkhole next to Gateway Baptist

IRO 113 massive gray micrite beds outcrop on corner of Bunny Trail, chert debris above N15E 18°SE pavement OC on Bunny Trail N4E 18SE in front of 2167 Harding looks dolomitic

IRO 114 on Mill Point Mar lo/ blocks copper Peak, cht gravel soil

BBG 331 at turnaround el 1920 6 N64W 20NE Lot 18 on Platt, frn weathered massive bedded Peakmantown Dolomite

BBG 332 N30W 10NE mass crypto algal laminite Beak

NOV 2

BBG - 3619 bedding
in dol a60Ve treatment
plant N 4W 10 NE
at N 37° 13.300W 80° 23.252

NOV 3 Hockorg Hill Farm
el
IRO 151 N 5E 16 SE
paperville type shale in
bank at N 37 14.072 W80°21.480
IRO 152 N40E 14SE (bd)
very dk gry argillaceous
ls w/ slaty cleavage.
Fractures N 20W 45 SW
photos N 60E 80 SE
N 37° 14.057 W 80 21.388
IRO 124 N14E 14SE
argillaceous ls
N37 14 222 W80 21, 340
IRO 125 N 18W 30NE
bedding on lgt gy
weath dk argillaceous ls
on ridge el 1670-80
N 37 14.218 W80°21.250
IRO 126 N 60E 45 SE
el 1780ft N 37°14.168
olive weath arg W80 21.103
ochrous yellow soil

IRO-153 el 1850 ft grn-brn-red
fine ss or siltsn w/
finely ribbed brachiopod imp.
N 14° W 12° NE (06?)
N 37° 14.135 W 80 21.007

IRO-154 el 1960 ft white
weathered medium grained
qtz ss N 37° 14.123' W 80 21.045'
distinct break in slope
= Obr. Walker Mtn ss

1960

IRO-155 white weathering lithic
[feldspar rich medium
ss ledge at el 2020-30 ft
N 37° 14.115' W 80° 21.012
bedding N 30 W 12° NE
ledge crops out above on
nose of hill pt? Mined
for building stone?

IRO-127 sh chips no Q
Gard correction 40 on
2084 knob

IRO-131 el 2090 ft
Grnd olive-brn [illegible]
sand/ ls blocks olive

March 3 2011 Paris Mtn

IRO 161 el 2921 (T+b) NS 12E
4' thk ledge thk bedded pebbly white qtz ss on ridge top by cottage

IRO 162 el 2850 on Hahns Fence line boulders of Ferruginous cemeted ss or limonite ore (Fagg Cgl) no tuscarora on this spur

IRO 163 at old Fence line on TMH property el 2790 greenish gray silty sh chips w/ fine thin bedded graywacke Ort Conn

IRO 164 air strike on sh - med bedded ss in martinsburg on next spur 8° aparent dip N30W from here est strike N 30 W 8° dip NE

IRO 165 on base Devonian ss unit photos at el 28206 beds N 20 W 18 NE bench on sh below cover W 21 Ks

IRO 2515 N 10 E 16 SE
4' ledge of White X bedded
quartz ss above bench
el 26906 pos. Tusc below

IRO 2516 el 2700 pit / limonite
on nose ~ 15' dia photo
IRO 2517 orange-yellow ocher
cemented sand float
looks like Helderberg
IRO 2518 Photo of Tower
strong bubbler stream above road
el 2490
IRO 2519 OC parchment on
ad of switch back el 24106
N 4 W 16 NE Spring at road
50 M N
March 7 2011 Cool clear IRO 5116
E-W 44 S ledge of
eg gray qtzite at IRO-
5116
IRO 5215 above new house
ledge breaks across ck
" 58-60 E 18 SE coarse
pebbly qtzite float ~ feet

Nov 29 2010 IRO-Reosdale

Talked w/ Mr. Sheppard (IRO 222) owner of property very friendly says old quarry was sand quarry (friable sand) crushed for construction. Belongs to Russell Duncan, Ditch Witch of Salem, (IRO 223) ~ law Lyn Reese, his brother in law owns upper house (IRO 241). Talked w/ Reese made trav. gate was locked.

IRO 242 massive bedded med-coarse impure (calc?) sand w pits on bedding = 5 ft thick burrows N10E 6SE = keefer? el 2158 spot el on map

IRO 241 Hummocky bedded Egem thick bedded light gray to white sandstone w 0.5" pebble zones N4E 18SE 2200 ft

IRO 243 coarse massive sand ledge N 10 E 14 SE overlies thin white sand beds (Photo el 2260

IRO 244, Freeable white med/thk bedded qtz ss el 2375 N10E 10SE

IRO 245 el 2480 b ledge at head of hollow N12E 14SE massive pebbly white SS

IRO 246 el 2680 b ledge between Karst depression N8E 12SE Pebbly ss, cg lt grey—w/ red brn weathering

IRO 247 Dip slope in mass bedded grg pebbly ss. el 2775 N12E 16SE Dip slope above to top summit

IRO 248 doline el 2700 b ~50' across 10' deep

11/29/2010 21 miles Mazda B2300

IRO 5117 chert Float
below rose hill
ledge in switch back
by house at el 1750 6

March 2 2011
IRO 251 Huntersville Chrt
from road pavement Cdip
slope N 37° 14' 08.68"
W 80° 18' 25.30"
Spls For Chem

IRO 241 Ridgely SS Oc
37° 14' 00.46N 80° 19' 15.9"
IRO 242 Ridgely Core
37° 13' 57.73 N 80° 19' 10.84"W

March 3
IRO 248 trail crossing
stream large blocks Field
by cabin at 2250 ledge N2E12St
IRO 249 trail Veers to left
below nearly Flat ledges
of cg pebbly qtz SS
N 10W 18 NE CKeefer? cl2300
Following drain

IRO 2410 N S 16 E
Photos of thk (6'
pebbly ledge w/ qtz
cgl layers x beds
el 24306'

IRO 2411 at head of
hollow 10-20' by 3- blocks
as valley fill some coarse brn
ss/w orange oceous replacement
cement between cg qtz sand
grains - looks like oriskany
or martinsburg - el 2500± 80'
bare error el 2520 - Spring
emergant From Colluvium including
orange ochreous ss + sh + coarse
limonite goethite cobble size f Fit

IRO 2412 photos and spl
of limonite from ore pit
20' dia 8' deep 40' French
below el 2600' photos
N 37° 13' 42.03" / W 80° 19' 41.73"

IRO 2413 el 2650 on road pavement
outcrop White friable ss
N 10 E 10 S E bedding

IRO 2414 el 2720 pavement
White Friable ss N S 6 W 10 NE

IRO253 coarse cgl qtz sand overlain by gray slaty argillite N22E 10 SE cf qt ccm 2158 Photos

IRO 254 Fine white friable ss w/ limonite layers grading to brn red sandy clay sap (Helderberg Dr) E 1950 b N 5E 15 SE

IRO263 N 40E 10°SE ledge between pig wallow and barn chert or qtzite?

11-15-2010 :

IRO239 Large sh oc on stream bank N40 E 18 SE Dm

IRO 264 Air shot white-tan sand soil looks like Db

IRO 319 New house on nose drive way exposes orange to olive weathed shale and thin medium bedded siliceous argillite / fine ss beds, Extensive qtz ss clasts on road above curve and around buildings

April Danner

Terry Nicholson

Civil war trails grant

On campus tour for sesquicentennial

Overview Black Family Cemetery

Jane Alexander Black 1832 Blacks woods

is 20 years ago African american law

Mtn R. Fleman

Col Ronald – Cumbria originally

named for him

Wm Sarvey – worked at White

Sulfur springs Hospital

Cemetery black (1) Cro black BBG 347

BBG 348 sinkhole?

IRO 2 3 10 20' sh bank Dm

dk gry slaty argillite BPC

cleavage N30E 20°SE

just below gate

IRO 3 1 10 slaty argillite

w/ 1 – 2" mass silt

or ls beds Dm

IRO 2 6 5 1' sh mush wad

slaty cleaved bk

N

argillite at 35° hinge plunge NW N50E

IRO 267 N 74 W 20 NE Massive qtzite ledge/ spring with arrowheads

IRO 268 dk gry slaty argillite outcrops in roadbed, N76W 50NE

IRO 3413 Black slaty arg Exposed in driveway to new house N80E 50NW

IRO 3411 N80W 50NE Black slaty ar

IRO 3412 DK gry slty arg N56W 40NE BPC

IRO 3413 N40E 20NE Black slaty argillite some thinS beds

11/18/10 MCM 988

Bob Lowells Lot 3950

NCOE 18SE gry weathed argillite w/ slaty cleavage very black well cuttings.

MCM 989 Orange weath black micrite beds (nodules) weat out of ridgeline N80E 20SE on ridge

black slaty argillite clean

MCM 9810 N50E 20SE

Gray blk argillite in spillway Hickory Knob Pond

slaty pavement on road to pond, cht and qtzite cobbles and pebbles scattered on upland surface

MCM 9811 Shale bank on lot 7 blk 5 slaty argillite cleavage N60E 18 SE

11/5/10 cool, partly cloudy

IRO 338 Db/Dm contact 50' above tracks on road up drainage above house el 1800 N 44 W 18 NE med bedded rusty weathered fine ss

IRO 339 N 70 W 18 NE el 1660 Tm (fg Fogs ss flt on NW slope at 1630' bench

IRO 3310 fg white - creme weathered ss flt 1630-60 bench on top not fossil rich

IRO 3311 el 1760 B N 70 E 20 SE lt gray to brn weathered slt sn and fine muscovite rich ss OCs on steep trail below power line

IRO 3312 N 8° E 25 E olive grn clay sh w/ flaty cleavage at el 1760

IRO 3313 N 80 E 20 NW el 14406 Db at head of valley

Cold 1" snow on ground

11 15/10 Mountain Lake (Eggleston)
37 21 832 80 31 808 4099

Fed
(1) N40E 16-17 SE el 3500
Joint N80E vert 80N
Joint N48W 80SW
Location N 37 32.114
W 80 34 467

(2) Water spl in spring branch 3900

3) Spring revisited 3980

(3) Outcrop of tassarora - 8' le 1 ft
Flat to slightly dipping
ethead of rock glacier
in Sartain Brach

(4)

(4) Begin red 55 Float Sm

11/08/10

IRO 324 A Fault N80 80 E

bcd s(FW) FW 5N

(HW) N80W 20 SW

B Thrust

N50E 15° SE

bcd N70E 10SE

Begin 11/9/10

N 72 E 18

light gry

sh/slaty

Cen

IRO 327

massive

weathered

gry Lomath

IRO 327A Truncating

just NW of

327 B N8W vert

Fault

Cem N 20W 80SW

another fo E fault

(photo

N80E

11/09/10

IRO 325 thk ss bds. in fg

shale Db photo N72E 26 SE

IRO 326 N40E 3 SE

thn ls/slt interbeds in gray sh

IRO 328 photo of
Gently dipping Db/Dm
contact. Beds N60W 20NE
Milboro dk gry thn bedded
to massive slaty (bpc).
mdsn
Brallier, gry-olive gry tan weath
Mudsn w med-thin fine
sand and silt beds
Photo
IRO 329 N20E 20SE Milboro
/edge on S. bank of stream
IRO 3210 water line in stream
bottom N40W 3° NE
IRO 311 N40W 20SW Dm in bank
just above 622 bridge
IRO 312 N40E 15SE Dm
on road bank
MeM 971 oc of gray shale, Fissile
on road bank at Taylor house
314 half Acre of Rocks Road
N40E 30SE
IRO 313 large blocks of
white qtz arenite along
stream and in yds = Of

11/08/10 Sunny cool, Bradshaw Road
MCM 994 N20E 17 SE gray slaty
cleaved mudsn w/ burrows
thin ss/sltsn clasts in soil
MCM 995 N20E 18 SE gray
weath sh w/ rusty weathered
fine ss beds ~ 2-4" thick
IRO 3314 N10E 14 SE
30' high bank in gray to
greenish gray mudsn w/ ls
concretions at top of lower
1/3 SE dipping cleavage
breaks across massive
Mudsn CPhotal N30E 30SE
IRO 3315 N66E 4SE gray
to pale pink orange
weathered clay shale
w/ bedding plane cleavage
in ditch, very bleached
soils chips no ss or sltsn
float on slope = DM
at el 1380 ft
IRO 3316 N70E 4SE
total saprolite lt gry
pink sandy clay from

Mgwy, ss and siltstone clasts in soil. Old td? at new house

IRO 321 sh + fg ss float Lot brailler sap, some rounded cobbles of Td

IRO 322 sh + fg ss float wet - smelly sap on road bank = septic failure N40E 10 SE in cut bank on Lindsy road (SR 1054)

IRO 323 Lot 47A 2920 Taylor Lane, yellow orange shale saprolite on road side Dbr. 16" p.t N40E 10°SE

IRO 324 almost SS OC in Brenda Masons yard

IRO 325 N70W 20 NE clearage in lt grey to pink orange slaty saprolite very little ss at all Brenda Mason

IRO 335 11/1/10

N 40 E 15° SE dk grg to black mdsn w/ slaty cleavage forms 30' cliff below RR

MCM991 N 50E 30 SE Thn/med qtz ss beds in gray shale sap

Db in 2 bench 60' cut

IRO 334 11/5/10



at edge of woods below

Syncline between 2 drains

IRO 333 cliff above creek

N 50 E 15 SE dk gry mdsn w/ slaty cleavage

some limestone concretions, 41' is bed? Om

IRO 337 ss flt at edge of Td

IRO 336 " edge of field above tracks

GOOGLE EARTH view side bar (remove) ctrl alt print screen, edit paste Scale 70%

Scale, hold shift to maintain aspect ratio

Elliston Coordinates

UL 37° 15" 80° 15"
UR 37° 15' 80° 7' 30"
LL 37 07 30 80° 15"
LR 37 07 30 80 7' 30"



export PDF
adobe
make .jpg

add image overly
Loc
First Loc (1.1.

Ironto 600 Pdf
LL

LL 37.15 80 22.30
UR 37 15 80.15

ESN 1714 qband. quarry thk bedded dol
N 25 E 40 SE strike
N 66 W 80 SW joint
WP 152 N 37 12.583 W 80 14.296 el 1238
on bench above Flood plain ~100 m
ESN 4118 Rusty brn weathered dol
in lower elbrook Massive to
thin bedded N 6 W 20 NE plunging
anticlinal nose (pix)
Jan 29 2010 Ironto Coord & loads
IRO 362 olive grn to tan sh
N 80 W 20 NE WP 152 N 37 13 931 el 1245
Braillier fm w/ slt & W 80 15 431
partings
IRO 363 N 45 E 18 SE 2' slt sh
beds w/ grn shly interbeds
WP 153 N 37° 13.827' W 80° 15.544' 1215
IRO 364 Photo of Braillier / Millboro
contact in rail cut WP 154
N 37 13.780 W 80 15.807
N 46 E 18 SE Photo of Of synform
N 80 E 5 NE
Braillier in cut to SW
IRO 365 olive gray wood sh shale
with mod (1") (6") discontin

1/29/10 IRO 351
silt beds N 56 E 50 SE
at WP 154 N37° 13.683 W 80° 15.841
IRO 365 el 1387. Section of steeper
dipping reg bedded 2" ss rust red
IRO 365 weathered forms 100' cliff
above river
IRO 366 el 1599 WP 155 N37° 13.619
shaley float changes to W80° 15.678
tan phyll or platy arg. W
cobble sized gry crystalline dol or ss.
IRO 367 ylw brn sh + gray and
red ss (qtz) Float on semi
bench at WP 156 N37 13 577 W 80 15 0 12
el 1730 (Ord bays Fm?) Dolomite
on bench above
IRO 368 Oc thk bedded gocar
chty dol N 78E 20SE
IRO WP 157 el 1812 N 37 13.555 W 80 15.551
IRO 369 soil type changes
from choc brn clay carb to
thn tan and red phyllite chips
N37 13.509 W80 15.511 el 1979
(2021)
IRO 3610 Ribbon banded and
laminated s.l. dol N 76W 30NE

IRO 3618 Needmore shale
Olive grn thn bedded mdstn
rust red weathering
strong joints of faults
N44E 74 NW // 26 E 6 SE

IRO 3619 N60E 30SE bedding in green thin bedded mudstone - Needmore

IRO 3620 N80E 4NE
assymetric anticlinal hinge
in green sh and mudstn

IRO 3621 N76E 40 SE green-gray lustrous mdstn w/ slaty cleavage at private crossing

IRO 3622 10' at least yellow sandy td w 2' white qtzite bldrs at top of cut Fine sandy soil washed over gray sh in RR cuts

IRO 3623 Fault Scarp??



in terrace dep.
Fault trends N 30 E 70 SE
beds trend N50E 20 SE
(medium bedded fine ss + sh = Db

IRO 331 FW 40 40 crenulated 'chevron' folding in upper millboro then overturned sands in Bralier, Contact well exposed here

N70E 80 SE DT limbs →



IRO 332 Flat lying Dm w/ regular thin to med beds of fine rusty sand

Main brailler Contact ~ 30' above at 1st bench large dark section above 2nd bench ~ 100' cut

IRO 333 Flat lying Dm or Db w/ old channel N60W 4

IRO 334 Sap of Brailler thin bedded ss clasts in Fold

ESN NOV 1 2010

Bowers Farm at "Bradshaw"

sign on NW switch for trash train 06 Brallier, gray fg ss thn - med bedded (10-20cm) ss in gray shale mtx N60E 15SE weathers olive-brown



IRD 3615 Bowers' Trash Train

Brallier at Breast height N80E 15SE. greenish gray ss in gray shale thicker rusty beds above fault N10E 75SE



IRO 3616



Wedge block cuts folded Brallier

above



10m

hinge plunging EW at 5°r appears to break into reverse (back thrust) fault in hinge, does not penetrate lower bench except as Flowen structure



prod marks current indicators on bed bottoms = Turbidite flow

IRO 3617 NW dipping Normal faults N35E 60NW offset limy strata in upper Millboro



MCM 981 N40E 18SE Db sandstone bed in saprolite along ridge road (inc) white ss / tan sh extremely leached silty soil

MCM 982 tan to reddish weathered argillite w slaty cleavage on power line N66E 45SE

MCM 996 0-4" ang qtz ss clasts in sandy soil along power line ± Db

MCM 983 tan weathered argillite w/ slaty cleavage N60E 60SE on trail elevation 1430 ft

MCM 984 in curve on trail at 1480-90 thin bedded silty argillite w/ qtz sandbeds N40E 30SE

MCM 985 white sandy soil angular ss + sltst clasts two photos of typical Dm regolith

McM 986

Photos of Shale Cut
200 x 40 x 40 presumably
a road under construction
N60E 15SE massive
gray weathy argillite
W(bpc) Dm? el 1500
McM987 thin bedded silt/ss
layers above pit in
curve on old road bed
N30E 30SE D6??
11/10/10 IRO 314 el 1550
topo high w white weath ss
clasts in bleached silty soil
IRO 3213 el 13006 at
stream level bed and banks
contain slaty argillite, dk
gry massive OCS N40E 20SE
IRO 3214 1' fine grag ls?
beds in dk gry slaty cleaved
mdsn (Spl) ledge N60E 20SE
IRO 3215 50 x 2' depression
(doline) in stream
course Fill = ls unit in Sub
el 13506 N40E 20SE thin beds
on stream bank slate in ark

11/10/10 IRO 3710 Reesedale Rd
gray slaty cleaved argillite
N 40 E 48 SE
IRO 341. N 60 E 20 SE
black slate with tiny
triangular shell fossils
▽ with a biaxial
symmetry Stylolina sp?
IRO 342 dk gry slaty arg
ox on road bank, sh soil to
slope below house N 30 E 26 SE
thin bedding or bpc
in driveway cut
IRO 261 borrow pit in
blk slaty argillite
N 60 E 25 SE
IRO 3216 1-2' dia qtzite bldrs
in drain on old river terrace
break in slope at 1310
shot on Irene Leech house
IRO 3217 2nd break in slope 100' above
~ 1380
IRO 355 on flat below barn
site, white leached sandy soil
fine SS clasts at 1380-1400

11/09/10

IRO 320 in gorge w/slate bottom 1st good SS ~1' thk about 30' above on bluff, N40E 10SE slaty clevage

IRO 321 in Gorge, a def. bench decends on SW bank at el 1320' beds in ck bank N40E 15 SE Db

IRO 322 On top sandy white top soil Fine ss clasts at el 1480. Good hard wood stand on top big [illegible] on NE slope - Nice land

11/10/10 IRO 343 on 2nd knob behind double wide white qtz sandstone float

IRO 344 N 65 W 34 NE SS, lite grey weath white and tan, med bedded, thin Db. shale, pale green weath tan, burrowed

IRO 345 bypassed house w/dog sta at intersection of forest road SS Flt, Fg, mica, qtz rich

11/10/10 Ctd IRO 345 white leached silty sand topsoil some orange slaty chips (Db)

IRO 346 4" ss clasts along road bleached micaceous sandy top soil el 1540 - 1550 b

IRO 347 abandoned well in saddle

IRO 348 Building on blocks OC in cut bench, gray and red slaty mudstone in cut N75W 26NE el 14806

IRO 349 N 75E 40SE gray slaty argillite in road cut

IRO 3510 another house on ridge to SE white fine sandstone chips in the saddle

IRO 3511 N40E 42SE White Wh Crem gray slaty argillite overturned beds?

IRO 3512 at limb crch N80 14NE photo envelope surface

14

N50E 60SE

IRO 356 N60W 40NE Gry Sh W 3" - 6" Is?

IRO 357 Dm slaty arg
N70E 36 NW in bank at
el 1300'

IRO 358 photo of Fold hinge
in dark greenish gray arg
N80E 5NE

IRO 359 photo of terrace
bleached soil. thk 55 tcht
blds on & cobbles along
road

IRO 3218 (in front of Leech's)
N54W 30NE med thin avg or
silt beds in dk grg arg

11/12/10 Flatwoods Road
IRO 315 outcrops on road
above hunters burden
N 40 E 16 SE orange-tan
weathered slaty argillite
(Dm)
IRO 316 outcrops of argill
and is poss. sltstn N 70W
15 NE at end of Bridge

11/12/10 IRO 317
N 70 W 16 NE gry tan
weathered argillite N40W vert
slaty clearage joints N10E 80NW

IRO 318 dk gray slaty N78W 80SW
Dm argillite N 14 E 10 SE joint N70W 60SW
N74E 80NW

IRO 231 roadside OCs black joints N40W 80SW
slaty argillite N 60 12 SE N60E 80NW

IRO 232 " " N70E 24SE
IRO 233 N80E 20SE blk
slaty argillite beneath sandy
regolith containing round
qtz cobbles gray and white
chert. Intersection 689 Sarver Rd.
IRO 234 S60W 20 plunging antiform
IRO 235 N25E 20 SE thin
bedded gray argillite Dm
IRO 236 gray slaty argillite bank
N 80 E 30 SE Crenulation
plunging S&W 20, graphite?
and chlorite sheen on
Folded Clearage

11/12/10

IRO 250 dark gray - blk slaty argillite chips on road bank, light colored sandy leached soil on top

IRO 251 light gray to white nodular bedded chert pavement on turn N-S 15 E IRO 22/ Tan to light brown, and brown to red limonitic SS in drive way N 40 E 30 SE White qtz arenitic ledges below N 55 E 10 SE sp/ of impure lt brn SS.

IRO 252 N 20 E 8 SE Med gry to brown weathered qtz SS w/ some limonitic cement (Dr) N 35 E + 5 E ledges of light gry nodular chert form pavement above N 45 E 4 SE thin limonitic layer at base of chert overlies reddish clay sap (LS??)

Jan 27 '10 IRONTO QUAD Pedlar Hills

Met Mr. Wells on road at
IRO 391 N37 13 049 W80 15. 184
WP120 1782 Rd + brn slaty argillite
N48E 28SE across creek on road
IRO 392 N37 12 915 W80 15 251
el 1507 121 Rd slaty argillite
w/ bpc N20E 20SE spring box
below old house on map
IRO 393 N37 12.768 W80 15.277
el 1730 (1715B) lt grn-y/wish
gray phyllite or slaty arg in
ledge across road. Dol
gray thk bedd Occ in
strm across from Mr Wells's
N12E 20SE (at 122)
IRO 394 el 1830f N37 12 723 W80 15223
el 1838 grn gry, y/g slaty arg
chips, slt and weath ss
float ~20' dol below
bpc N20W 20NE N26E 40SE 6' dol
dk brg Frost on other side of hollow
IRO 395 N18E 40SE dk gry
thn, irreg bedded Dol or arg dol
w slaty clay. N37 12.663 W80 15 244
el 1809 in saddle - Fold? WP124

IRO 395 on 2nd knob in saddle
Mod bedded arg do' N 12 W 32 NE
FC N60E across beds at BBSEB
IRO 316 on knob at NH boundary
WP 125 N37 12 .615 W 80° 15.432 el 1935
ledge of grn slaty argillite N10E 45°
black chert. Float in saddle to N
IRO 631 grn. and rd slaty argillite ledge
and chips on ridge top N12W 46NE
WP 126 N37 12.412 W80° 15.426 el 2058
2040 T
IRO632 2' dol interbed in argillite
N14W 40 NE @ wp 127 N37° 12.339 W 80° 15.428
el 2078 - 2010 b
IRO633 blue gray dol ls, thin bedded
w/ algal strom N6W 18 NE Elbrook lite
WP 128 N 37° 12.241 W 80° 15.529
el 1837' (180 2) b
IRO 34 blue gray ribbon banded ls + dol
burrowed limestone and massive gray
dolomite blocks and pavement exposed
on both sides of knob along pipeline
no Rome lithologies beyond IRO-
632. WP 129 N 37 12.163 W 80° 15.769
el 2043 bedding in blue gray dol ls N45W30NE

IRO 635 2' thick bioturbated dol lg.
N 18 E 14 SE on dip slope
dipping SE under steep knob
shown on MJB map WP
N 37° 12.147 W 80° 15.627 el 1260

IRO 636 N 32 W 60 SW bedding massive
in gray dolomite w/ algal structures
whispy

IRO 637 Thin bedded platy ylw weath
dolomite pod of breccia (2')
in pipeline cut N 38 W 40 NE

IRO 397 maroon slaty argillite
and ochreous yellow orange laminated
argilline ocs on ridge in VDH
'corner' N 10 E 72 SE OT?
WP 131 N 37° 12.691 W 080 15.416 el 1970

Photo of fine sand bed in ocher
laminite showing ot scour geom

IRO 398 Lam maroon arg w/
thin white sandstone layers
drapes + ripples ot

Photo
taken

N 10 E 45 SE WP 132 N 37 12.391 W 80 15.417

IRO 361 grn arg/slaty clear
N25E 60SE WP133 N37 3.058 W8015.319
el 1877 1860b Jan 28 2010
ESN610 N8E 60SE platy
y'w grey dol ledge along
pipeline WP134 N37 13057
Sgt sin W80 15317
ESN611 2 sinks in elbrock
to N of Pipe line N most
is WP135 N37 12.450 W 80 14 937
el 1892 - qtzite bldrs & old river rock
IRO638 WP 135 N37 12.388 W 80 15.016
el 1839 Water Filled doline 75 yds
long red grn sh chips on pipeline
IRO 639 Knob on pipeline held up
by bm grn and rd arg in lower
elbrook near Flatlying N30W 18NE
platy arg dol or pavement on pipeline
IRO 6310 100' dia 15-20' deep sink
just S of pipeline at WP137
N37 12 385 W 80 15 201 el 1853
grn argillaceous dol N 50W 40 NE
IRO 6311 Red and grn slaty argillite Oc
on pipeline N46W 50 NE at WP138
N 37 12 418 W 80 15 235

IRB610 ctd WP158 1810b

N37 13.553 W80 15.420 el 1707

IRO3611 WP159 N37 13.586 W80 15.379

el 1630 1660 gray algal bl

N20E 26SE

IRO3612 top bench blk sh chips

~salem flt N37 13.611

el 1632 W80 15.358 1620

ls scarp facing NW

IRO3613 above Bowers barn

tn bedded 55 - 54 N80E 40SE

WP161 N37°13.798 W80°15.262'

el 1322 06

IRO3613 about 50' of gray and brown sand crossing drain here at WP 293 N37°10.147 el 1698

N W80°21.140 (1650b

IRO3

IRO-432 el 26006

IRO-433 Fine grained ss w abundant O O liguloid brachs + gastropod shells? 4" dia spheroids weathed Fmo ledge N80E 20SE el 25756

IRO-434 el 2410 beyond saddle there is a 75-100' dia doline with white sandy soil and qtz ose sandstone clasts (base of Devonian Helderberg ss? Ridgely? or sink hole Fill on old erosion surface small snaggle horn buck!

IRO-435 yellow ochèrous clay shale chips on skid road below at el 23406 some qtz ss blocks in talus chute that drains to east

IRO-436 N 60E 25 SE nigly weath calc cemented? qtz ss beds exposed in skid road at property boundary el 24406

IRO-437 white qtz ss blks and

aparently interlayered olive gray lithic ss persistal along narrow strike ridge at el 24056

IRO-438 blks of white fg qtz ss and gray to olive lithic ss, NO pebb cgl 6" qtz ss just above saddle N50E 60SE cross bedded. el 2280

IRO-439 ochorous yellow gry to olive siltsn and mudsn chips on nose at el 22756

IRO-4310 white qtz ss v 6' thk blocks on steep slop above break inslope at top of spur ridge

IRO-4311 N25E 24SE thin bedded olive to yellow brown weathered Mudsn w/ bpc el 20806

IRO-421 at break in slope on flat spur el 18206 Fine tan shale chips, block of black sh (oil?)

IRO-422 break in slope

begin dusky reddish chips
th pink silty sorl
some ochreous weathed sandstone
w/ Feldpar and qtz grans
el 1800 b (Ob.)
IRO-423 el 1750 b N50E 45SE
skid road bank exposed
dusky red and yellow green bur.
mudsn. (Ob)
IRO-424 el 1720 b N50 45SE
olive to yellowish weathed
clay sh and silt-Fine
sand exposed in road
bank (Omb
IRO-425 air strike on Bays cliff
across river N 30 E 34 SE
~ 200 - 300' wide
IRO-426 ledges of Oth
band argillite N80E40SE
bedding Cleavage N60E60SE
IRO-427 N-S 22E thk argillite
argillaceous ls beds above river
Oth
IRO-428 N34E 30SE
black slaty arg and banded
gray and black arg ls

IRO 185 N3E 20 SE fnk
to massive bed of dk
argillaceous Liberty hall
15 near Pence line along
North Fork Poanoka River

3122 | 09 IRO 487 WP 281
road WP N37°10.644 e/1677
W80°21.188'

IRO 488 ledges of brecciated gry dolomite just above saddle at WP 282 N37°10.133 W80°21.129

IRO 489 lt gry fract. xbne dol ledges on road N30E 60

IRO 4810 N45E 29SE gray dolomite ledges w/ wht fracture fills @ pipeline WP 283 N3710.521 e/1810 W8020.991

IRO 4811 N35E 45SE thn bdded to laminated gry dolomite WP 284 N37°10.410' W80°20.944' e/1940

IRO 491 N62E 66SE ledges of lt gry - dk laminated dolosn some massive/brecciated WP 285 N37°10.382' W80°20.752' e/1913 red clay soils cedar

IRO 492 N70E 40SE gry-lt gry aphanitic thn bedded dol ls WP 286 37°10.428 W80°20.599' e/1962 Ecr?

IRO 493 thk bedded laminite dol med-lite grey N 20W 60SW ledge across trail WP 287.
N 37° 10.563 W 80° 20.558 el 1942
Polymictic breccia in pavement above

IRO 494 massive thk bedded C.Xline grey-cream colored dolomine ledges on trail N20W 10NE WP 288
N 37° 10.616' W 80° 20.516' el 1984

IRO 495 creme colored dol and gray qtz ss Float and spoil in 2 pits ~ 10' diam 5' deep on ridgeline at WP N37 10 632
W 80 20 464

IRO 496 N10W 50 NE thn bedded bioclasted blk dol on pipeline at WP 290
N 37° 10.636 W 80° 20.598

IRO 497 N26E 74SE thin bedded algal laminite lt gy in trail sh Comb 30' to W WP 291
N 37° 10.635 W 80° 20.701' el 1935

IRO 498 N 40 W 60 NE
long sect grn phyllite then
platy dol in trail = tol (lower)

IRO 4812 plunge pool in green
argillite w/ slaty cleavage
at WP 212 N 37 10.613 W 80° 21.028
el 1700 16706
N 60 E 40 N W

IRO 4813 N80E 35SE
green argillite w/ slaty cleavage

IR 4814 about 50' ss N80W 40SW
IRO 452 grn slaty arg w/ thin
ss N 72 E 60 NW in strm
at Power line (OWL)
IRO 952 dol/phy N80E60SE
294 N37 07 44 W80 21.141
IRO 921 WP 295 3/23/80
N 37 09.322 W 80 16.613
el 1618 - red clay silt in Flood
plain.
IRO 922 N 30 E 10 SE
red slaty argillite and orange
weath dol WP 298
N 37 09 482 1800
W 80 16 626 16806

WP 497

IRO 923 N 54 E 40 SE

gry thk bedd dol w/ tan slaty
bnds tel at Spring
N 37 09 293 W 80 16 431 el 1145

WP 498 N 37 09 095 IRO 924

Travertine, W 80 16 286 Spring

IRO 953 WP 299 N 37 08 864 W 80 16 353

Elbrook ledges N 40 E 30 SE
travertine upstream

IRO 941 N 60 E 20 SE
massive ledge of gry
dol / marl in meadow
WP 300 N 37 08 925 W 80 16 701
1530 15006

IRO 942 N 58 W 16 SW
Elbrook, lgods/ide across Stn
WP 301 N 37 08 760 W 80 16 717
1557

IRO 943 platy dol N 30 E 20
WP 302 N 37 08 718 W 80 16 705
el 1582

IRO WP 303 N 37 11 460 80 14 925
1308. ledge N 45 W 10° NE
coarse calcite cemented breccia

10126 / 11
IRO-4710 el 2090 ft
overturned tree exposed
pink sand soil Fine qtz
SS clasts in loamy soil
at N 37° 10.565 W 80° 22.062
Bays Fm on top above 2050
red mudstone chips
IRO 4711 N-14 E 30 SE
4' qtz SS ledge
above SS bench 30' below
el 2040 N 37° 10.602 W80 22.070
IRO-4712 coarse gr qtz SS
blocks on nose of ridge
at el 2100 ft N 37° 10.513 W 80° 22.105
Walker Mtn SS
IRO-4713 calcareous slate dk
gry weath light gray
N 76E 30SE slaty clear
el 1810 ft N 37° 15.487
W 80° 21.720
IRO-4714 on Ipsea SS
across ravine from UT
Smart road Turn Around
gray weathed black slate
cleavage N 70E 70 SE
el 1700 N 37° 10.250 W80°

10/26/11

IRO 4715 Lipsey Rd adjacent to Smart Road el 1680'

N 37° 10.295 W 86° 22.202

N 20 E 40SE bedding?

IRO5154 High top / Lipsey Farm N80E 22 SE clear in thin bedded slaty mudrock (Ort) grades down into medium bedded burrowed fossiliferous bracciopod rich SS & mudst, olive green - gray

IRO-5155 75' dia doline in saddle developed in upper Ort ~ 2' closure at el 2400'

IRO 431 olive gray fine grained calcareous SS or sandy lime sap rock on top with abundant zones of finely ribbed brachs olive - ochreous yellow



el 2500'

IRO-432 Fine grained brown sand

N35E 36SE, SW side of Knob

Oct 26 breezy cool sunny

IRO 476 at el 18806?

N 40E 20 SE ls, dk gray argillaceous interbed in black slate. Och at N 37° 10.240 W 80° 21.915'

IRO 477 Pipeline trends N 60E at N 37 10.228 W 80° 21.847'

argillaceous ds ledges N40E 20SE just NW of Pipeline, must be Salem Fit

IRO 4825 qtz pebble cgl float on ridge at el 20006 N 37° 10.787' W 80° 21.550' SDr (Fagg cgl?) Photo

IRO 4826 tan weath gray slate N 60E 50SE clear just beyond fence el 2030 N 37° 10.875' Och or Ort W 80° 21.500'

IRO-457 Flaggy bedded dark gray argillite w/slaty cleavage on beak slope at el 18330, 50 yds SW of N 37° 11.125' W 80° 21.465'

IRO-458 White sandy Top fragments, F White med gr ss

OCT 26 2011 IRO-458 /
sandstone, porous because
of leaching cement
el 1780 6 N37°11.143
Walker Mtss W 80°21.362 O bays
IRO-459 N 78 W 60 NE
tan to dusky red sh
and mudrock ledges
on slope above clear
cut at el 1765 b
N 37° 11.142 W 80° 21.288'
IRO 4510 N 10 E 30 SE
sandsn ledge in tan sh
tight folds below el 1750
on road at N37° 11.233 W 80° 21.337
IRO-4511 stone pile white
weath qtz SS OC
just to W of tan
slate N 5E 34 NW clear
N 37° 11.125 W 80° 21.500
Baro correction 100'

IRO -478 qtz ss 6/dks + 6/lts
on nose at el 2000' N 37° 10.478'
W 80° 21.780'
IRO-479 on top of hill yellow gry
clay sh (Meta bentonitic?) el 2110 b
N 37° 10.487 W 80° 21.713

Slaty cleavage E W 28N bed
N80E 85SE clev
IRO 497 N14E 40SE fan
to 6n dol ledge ; new wk
Eco
IRO 4816 up 507 N 3710 346
W 80° 21, 324 el 1624
rounded dug out
spring w/ dol blocks
travertine drapes drain
below
IRO 4817 N70W 60NE N37 10 343
W 80 21 345
N76W 50NE thk bedded gray
dol w/ butcher block text
IRO 4818 by pond (dog)
E W 12S ledge
of gray brecciated dolomite
Travertine falls within pond
IRO 4819 N65E 40SE
greenish gray phyllite, gray
argillaceous dol and gray
polymictic breccia
IRO 4820 N54, 40 SW
brecciated + veined thk bedded dol
exposed in borrow pit by dam

4122/10

WP 508 N37 10 143 W80 21 832

el 1614

IRO 482 S40W 30 dextral fold in slaty laminated dol.

IRO 7216 badly cut over karst. Wetland, large spring Flow across 4 wheel trail old spring at wp 509 el 1594 N3709.969 W80°21.471.

IRO 7120 wetland, spring above Phone Line Trail at WP 510 N37 09 943 W80 21.678 el 1768

IRO 7121 8' tufa bank, water Fall Karst wetland area above WP 511 N37°09 913 W80°21.723 el 1757

IRO 7216 WP 512 N37°09.615 W80.21.730 el 2190 beige to lt gray massive fg dolomite (Ecol) N 90E 49°

IRO 7218 WP 513 N10E 28 NW ledge of creme colored Fg lam dol (Cco Just at Intersection John Lipseys lane N3709.630 W80 21.592 el 2085

3117/00 IRO 5515 WP

ANTICLINE N 70 W 40 NE WP 245
N 50 E 60 SE below N 37 11.255
W 80 19.041

IRO 5516 WP 246 N 37 11 273 W 80 18 988
Central point in Karst Field
sinkholes 20 50' deep ~100' dia
New fields cleared to SE
Coarse strom chert heads to top of
Knob at WP

IRO 5517 WP 247 N 68 E 50 SE
gray thn to med bedded crackle
brecciated dolomite el 1823
N 37 11.213 W 80 18 969

IRO 5518 WP 248 N 37° 11. 282
W 80° 18. 714
grey med-thk bedded xline dol
with breccia zones (crackel)
N 84 W 60 NE in Karst Field
W 4 sink entrances

IRO 5519 dusky red argillite w/
slatycleavage, thn orange red
weathy dol beds on road WP 249
N 37° 11. 205' W 80° 18. 666' Knob
above el 1865

IRO 5520 dol ledge nearly flat
lt gry finely xline N 84 E 18 SE
WP 250 N 37 11. 125 W 80° 18. 614 el 1851

Outcrops of Obcys 55 above kiln

IRO 5510 WP 239 N37 11 409 W 80 19.116'
grg gr. slaty argillite/interlayers of mcg. bm 55
lineation S 30°E 18 SE
Join N16W 75 SW Clear N30E 20 SE
beds N76E 22 SE

IRO 5511 grn + red wrath slaty
argillite. slaty cleavage N68°E 74 SE
WP 240 N 37° 11.506 W 80° 19.166
el 1611

IRO 5512 WP 241 el 1665 N37°11.626' W80° 19.218'
ledge of lithic cgl overlain by
white quartz arenite - steps
on Trail N60E 20 NW Top of Cgl
limonitic, silicified cgl = Oriskany / Helt

IRO 5513 WP 242 N37 11 358 W80 19 089
El 1704 Dolostone overlying tuFa
N70E 50SE thin bedded

IRO 5514 WP 243 N 37 11 226
el 1580 Flow ~ 50 gpm W80 19074
spring emerges from cavern
on side of hill mass—bedded
grg ylsh limestone.

IRO 5515 WP 244 N37° 11.228 W80 19.2[illegible]
N10E 32SE Siliceous banded
fnk bedded dolostn ledges

3/17/09

IRO 546

N 24 W 40 SW slaty tan weath dolomitic crenulation folds

N 26° W re NW WP 255

N 37 11 335 W 80° 14.175

el 1599

IRO 547 at bend thin bedded gray fractured dol N 30 W 20 NE



dextral folds

el 1616 N 24 W 2° NW

WP 256 N 37 11 354 W 80 19 813

IRO 548 above road in bend ledges outcrop above 20' cirque el 1607 old cave/spring opening at WP 257

N 37° 11.378 W 80° 19.248 STD N 50 W 65 W

IRO 549 above Road in bed (NW end)

WP 258 N 37 11 406 W 80 19 268

el 1699 ledge of dol breccia above ylw weath sh/slate chips in soil - ls or chute below carb bench

IRO 5410 brn/gm gry slaty wrs oc in bank at WP 259 el 1644

N 24 E 24 SE clean joints. N 78 W 80 NE

N 37° 11.440 W 80 19 236

IRO 541

N 50 W 50 NE grn-olive fg ss
in dk tch N 37 11 593 W 80 19.341
el 1357 WP 260 Ort

3/22/09 IRO 451 Omb grn sh/slst
N 72 E 74 SE clean N 08 E (07)
IRO 482 N 08 E 30 SE beds upright
dipping away from bys. Cleavage
N 70 E 80 SE strong, photos
WP 277 N 37 D 660 W 80° 21.723
WP 278 N 37 10.617 W 80° 21.208
IRO 483 Fault N 82 W 70 NE photo
IRO 483 cleavage in mass carg silt
on embankment — N 50 E 70 SE
WP 279 N 37 10 712 W 80. 21.278
el 1517 2'-3' travertine bank
in stream grn org on embankment
IRO 484 N 70 E 20 NW grn ss
beg interbedded w/ thin ss
+ org (Top of ss to ss
WP 280 N 37 10 757 W 80 21 310
2' trav bank in Front of
cabin IRO 485
IRO 486 Salem Fault fw
10' dolomite
IRO 487 Fossil bed in grn gry
yfw brn weath org on logging

IR0 7417

Strat. calc. sand dolomite on ridge N80W 75SW

NO Trespassing
Fred Beasely

IR7418 cut at Milepost N288

N72E 70SE

Itra Folia Folds Of?

thin bedded laminated dolostone w/ thin argillite layers

hing plunging S64E 50SE

Looks transitional to ed brook

Good flat pebble cgl beds on N side W algal strats that are rsv



IR0 7419: N86W 48SW Strat. dol

IRO 7420 N88E 8° SE strat. dolomite ledge in field
IRO 7421 N74E 45 SE complex slop made up of pinnicles of gray saccharoidal elbrook dolomite with deep terra rosa soil between - pinnicles 20-30' apart - Iron mine?
N86E 20 SE
IRO 711 N82E 60 SE frac and brecciated dol ledge along trail - Elbrook? Breccia blocks on knob

IRO7422 N15E 60 NW thin bedded dolomite with massive beds of cataclasite and breccia
IRO7423 N50W 15 SW thin bedded phylonnitic lower El.
IRO 7424 N80E 20 NW stratiaulate blue gray dol looks like FIO
BBG 96 16 gry stratiaulate dol w/ X beds and pebble sized rip up cgl layer looks of truncated by fault to NW
NzoW 80W

IRO 746 thk blue gray algal ls above creek then ledges of straticulate ls (ribbon rock) interbedded w/ gray butcher blk dol. N60E 40SE (Oca)

WP 494 N37 08 634 el 2031
W80 22 341

IRO 747 Ledges of thk bedded butcher block weath gray dol along fence N80E 80NW

WP 495 N37 08 653 el 2042
W80 22 230

IRO 748 ledges of straticulate dolomite with argillite beds N80E 80NW N80E 80SE algal chert heads in soil

WP 496 N37 08 642 W80 22 070 el 2106

IRO 749 old Cem. not cared for oldest marker Richard Snow 4-1-1901.

IRO 7410 Road crosses gray straticulate-dol. ledge E-W 50s

IRO 7411 dolomite chert and 1' ss ledge forms small nose E-W 80N (dol) ss E-W 80N dol. gray thk bedded butcher block tex sand fine lam

IRO 741E Straticulate dol w flat pebble cgl bed seq may be OT
EW 50S IRO 741B → Large block blue gray ls w/ algal fingers

below sed pond for Walnut Ck subdivision oc of dol in spillway
N80W 60SW
IRO 741C N80E 84NW Straticulate dol ocs abve 4wheel trail, ls o- algal dol. blocks below
IRO 741D thk bedded crse-ltgry dol ledges, spring below pond
N80W 66SW nsd
IRO 741E 2nd spring on left
N80W 84SE algal matted med bedded gry dol
Still site, Fire circle (brick) barrels in creek below spring small travertine falls then 100' wide alluvial flat meander belt
IRO 741G old Ls quarry along road Spls blue gray micrite with possible sulfide minerals
N80E 80SE Strat dol in upper bench
N80E 54SE thk beds

IRO 461 dol ledge thk bedded gray w/ regular jointing or space cleavage. Beds N80W 30 NE cleavage N30E 80 SE WP 544 N37° 10.860' W80° 20.566' el 1946

IRO 462 Martins bury, ⊙ ranges to yellow-weathered argillite chips in soil, brn qtz ss + qtzite as cobble sized float at fault Brecciated gray dol to SE N10E 60SE - ledges of gray brecciated dol - Flow struct? breccia zone ~ 10' wide

IRO 4917 brn weath butcher block dol ledge N10W 30 NE on E side of 200' sink ~20' deep at WP 545 N37° 10.812' el 1974 W80° 20.137'

IRO 463 250' dia ribbon Sink 30' deep Mass layered dol on E side N10W 20NE WP 546 N37° 10.879' W80° 20.144' el 1942

IRO 464 N 80 E 25 NW
med bedded dol overlies
massive algal ls fel WP 549
N 37 10.939 W 80 20 098 el 2020
(2000+)

IRO 465 N 10W 20 NE mass
thk bedded gray dol breccia tl
chert breccia flt
WP 548 N 37° 10.988' W 80° 20.145
el 2020 1930 b

IRO 466 N 50E 15 SE WP 549
mass - thk bedded dol
blue gray algal bands ls
in synclinal trough ontop
N 37 11 075 W 80 20 174
el 1968 1960 b

IRO 467 brn y/w sh f ss
Float on trail Fault line at
WP 550 N 37° 11.153 W 80° 20.192
el 1786

IRO 468 lt gry weathered s/slt
N 60 E 45 SE cleavage
WP 551 N 37 11 302 W 80 20 305
1487 50 SE Fossil casts
WP 552 N 37 11 342 W 80 20 234

April 20 2010 clear
Lipsey Fam cool

IRO 475 N65E 70SE
thick bedded brown weathered gray xline dolomite with thin platy interbeds

IRO 476 dakk gray algal rboundstone/wackestone grading up into ribbon magnesian dolomite/short Elbrook cycles in ledges along road just below gas line

IRO 711 thin bedded algal lamite overlying thick algal stromb throbolite beds N dip E-W strike fel

IRO 712 Alternating thin bedded algal laminite beds and thick algal Stromal boundstone/wackestone beds gentle fold plunges N 70E at 6° with ~~~ spaced cleavage



N70E vertical, healed w/ Vein dol

4/20/10

IRO 713 N 40 W 60 NE
light gray, tan to biege weathered platy dolomite laminite beds w rounded thick stromatolitic ls beds
IRO 714 laminite beds kink folded hinge N50E 80°W ribbon rock in thin cycles along trail
IRO 715 Massive bedded Fine grained, light gray to creme colored microx fine dolomite CEcol outcrops on trail N 70 E 42 SE on siliceous silt/fine sand laminae that weather in positive relief also 2of 5S cobbles and pebbles in colluvial soils w/ cross bedding N50W 10 SW rsd laminite beds above show ripple marks in cross Sect

IRO #64

cg gs bed (Ot. N60E)
Fossil zone (Christiana?
IRO 4610 dk gray argillite interbedded
with thin ls beds
N70E 20 SE dextral Fold
N76E 5 NE Photos
Oe?, WP 553 N37°11.461
el 1424 W80 20 1.59

IRO 4611 photo of cobbles
in brown terrace WP 554 N37 11.508 W80 20.002
el 1437

4/29/10 WP 555 IRO 5424
20-30' of wh. to
brown fine grained
quartz sandstone
on cliff face below
WP555 el 1499 N 37 11.569
W 80 19.672
E-W 18° N

WP 556 N37°11.552 W80°19.657
el 1500. Qtz ss beds turn
up at end of ledge
E-W 65 NW photo of
hematite bed looks
like Heldeburg?

WP 557 N80E 70 NW 1½'
limonite bed at base of
SS section above Martinsburg
N 37 11 549 W 80 19 647 el 1548
IRO 5425 WP 558 N 37° 11.387
W80° 19.448
el 1770 SS and chert Float
on knob - Obs?
IRO 5426 brn weathered
butcher block dol ledges
on SE side of road crossing
in Saddle ledges N 30 E 20SE
WP 559 N 37 11 363 W80 19 473
el 1785
IRO 5427 WP 560 N 37° 11.334
W80 19.459
el 1759 Fossiferous grn -
orange Eel shale float
on road in head of drain Maroon
layers (Photo)
IRO 5428 island of dol Ocs
in middle of hollow N70E 20SE
IRO 5429 E-W 20
med bedded g-y dol
ledges on SE nose WP 561
N 37 11 192 W80 19 204 el 1976

IRO 5318 top of cht Knob
photo of chrtfss
green shale below ~20-30'
to top Keefer WP 206 N37 11.940'
1757' - 1760 b W 80° 17.676'
1690 b top SS = 70' sh?
Wed March 10' 2010
IRO 511 SK
N 84 E 22 NW base of
cgl section in Keefer.
10' ledge above 10' Med bedded
white qtz arenite below
WP 207 N37° 11.644 W 80° 19.357
el 1465
IRO 541 N60E 30NW olive gry
arg, lite to SS (omb?) WP 208
N37 11.637 W 80 19.300 el 1551
IRO 512 sk white pebbl
cgl blocks or in place
residual N 44 W 10 SW on
SW slope Omb below WP 209
N37°11.664' W 080° 19.241'
el 1677
IRO 513 on table rock (photo)
WP 210 N37° 11.704 W 80° 11.704 el 1666
N 80 E 20 NW sight on dip slope

3/10/10

IRO 513 to NW 2 big ledges with great base of Upper Quartzarenite blocks across hollow in Pines

IRO 541 on Conservancy Trail at WP 211 olive green SS + argillite F/T Forms ridge line to SE of SK N 37° 11.647 W 80° 19.179 el 1734 (16806)

IRO 551 at WP 212 on NC trail N 37 11 534 W80 19.075 el 1743 ft. shale chips 0 rts all te way Photos of Mill Knob show no. ftate ledges on top

IRO 552 at WP 213 el 18206, GPS 1780 N 37° 11.487 W 80° 19.051 2' ledge of brown and red ochreous weathering SS forms bump on trail dolosn OC's 20' above Photo of "bump" and dolosn ledges above breccia zone (few blders of MMG on trail NS 14° E hanging wall

IRO 553 N 30E 20 SE dolosn ledge on trail el 1880 b WP 214 N37° 11.457 el 1778 W 80 19.017

3/10/10

IRO 527 Big blocks in Landslide below Keefer beach along NS RR WP 229 N 37° 12.120 W 080° 18.627 el 1402

IRO 528 Millboro shale bank N 66 E 68 SE WP 230 N 37° 12.081 W 80° 18.710 ss blks coming down ridge at switch Fugg

IRO 529 N80E 40 S OT ledges of Keefer crossing hollow at WP 231 N37° 12.017 W 80° 18.836 el 1346

IRO 5210 N80E 40 SE OT qtzite ledge w/ shale beneath



IRO 5211 elongate ls deposit below Keefer ledge

IRO 5212 Millboro black shale in cut variable slumps N30E 81NW el 1460 WP 232 N 37 11 952 W 80 19.032

IRO 5213 upper ledge comes down hollow acr N80E 20 NW blocks below at WP 233 el 1423 N 37 11 .871 W 80° 19.161

IRO 521 photo of Ort shale/arg chips in roots of Ot tree on nose of SW knob. WP 220
N 37° 11.703 W 80° 18.734 el 2084
2020 Topo adjust boro 30' down

IRO 522 Float of coarse brachiopod (linguloid dom) breccia bed on top of SW knop - Orthrycula zone
WP 221 N37° 11.705 W080° 18.823
el 2124

IRO 523 qtz arenite, gry med-fg * Float along trail, with grn olive argillite chips below. Outlyers of Skh? WP 222 N37° 11.740
el 1931 1990's W80° 18.874'

IRO 524 Many piles of med gry green and red stained qtz ss in woods along gentle terrace like slope = Obz el 1998
WP 223 N37° 11.713 W80° 18 601
1960's

IRO 525 N44E 20 NW gry to reddish brn. medium grained thk bedded ss ledges in hollow
N 37 11.799 W 80 18.416 WP 224
el 1974 1940's

March 9 2010 ERO 533
Milboro sh w/ cleavage lgbx
1' concretion zone bedding
E-W 30S cleavage
Photos of Grinder Train and
shale Outcrops
N37 12.248 W80 17.951
el 1405
photo of fold and fault
ERO 534 Section between base
of Milboro and base of
Keefer cgl
Bedding Strikes EW dip 42
at base cgl width on road 60'
top is 2' of black chert
(Huntersville) then brown
weathed ss w/ thin sh partings
then 20 wide on road white
cgl qtz arenite beds.
Martinsburg (Reedsville sh
not exposed. Photo includes
1' dk green and white striped
"leopard bed". Martinsburg
ledges in River
ERO 535 40' wide grn
qtz arenite ledge on hillside

IRO 535 WP 192 N 37° 12 025
E 1353 W 80 17 812
N62E 74 NW underlain
by dark gry to brown weath
banded fossil bearing calc
mdst - massive bedded
40' measured ⊥ strike on road
bed
IRO 536 Qtz grain over grnish
brn sh sap N5GE GO SE - qtz
visible up the hill side
8' brn thk bedded mdst at top
of Reedsville overlain by fractury
Sand sh / white massive Qa
N 37° 11.879' W 80° 17.729 el 1358
WP 193 Photo of base of SS sect
meas W tape 73' wide S 56 E
Photo of Slickensided surface
clear N64E 80 SE 1m

plunge S 56° W 64 SW
asperity is up to NW

IRO 537 dark brn weath argillite
gray thk bedded fos. S6

May 4, 2011 IRO 5328
White qtz ss N70W 65
NE on river, black
shale overlies to NE
shale cleavage at
driveway SW
ss at corner N60W
50SW (IRO 5329
IRO 5330 N80E 60SE
8' OT qtz ss ledge
just on SE side of
point about 50' above
river = Top of Ridgely

IRO5331 OT qtz ss ledge
16 paces wide overlies
(structurally under)
reddish brn ss
and sltsn in upper
OMb on river N80E 70SE
IRO 5332 N80E 65SE
15-20' qtzite ledge
~50' high on slope
(OT) 100' above river
broken ledges on slope above

Sh chips above ~ 0m6

IRO5333 rounded and angular qtz as float on ridge road to new house

IRO5334 qtzite ledge crops out on ridge top above trailer house to E ledge trends N76W 70SW

IRO5335 N70W 45SW 10-15' qtzite cgl ledge ok by powerline just behind house on ridge

IRO 5336 chert and qtzite ledge forms hog back ridge above house - ledge form trends N60W to outcrop on road to SE

IRO5337 N60W 60SW Sh sap on drive 55 oc bcbu w/cht @ top (bottom) above new construction job

N 50 E 28 SE at WP 55 1.5'

WP 194 N 37 11.881 W 80 17.762

IRO 538 N 70E 36 SE WP 195
N 37 11 815' W 80 17 674
WP 195 el 1424 brn sh 6" lgw

WP 196 IRO 539 N 37 11 85
first blackish oc W 80 17 654 el 1440

IRO 5310 WP 197 N 37° 11.848 W 80° 17.621
el 1407 S10E shot at 15° to base of Salem Thrust Fault

IRO 5311 WP 198 N 37 11 840 W 80 17 562 el 1394
first ls/dol oc - karst above house blocks at Thicketler Lane. Massive gray dol and breccia/shly layers Fault angle must be steepened to fit in valley

IRO 641 N 60E 3 NW or horizontal crinkly thin bedded dolomite in Elbrook? at WP 199 el 1543
N 37° 11.634 W 80° 16.973

IRO 6215 MMb (P) on hillslope ledge above gray breccia N40 W 26SW
WP 200 N 37 11.737 W 80 16.294
el 1714

IRO 5312 N 85E 65 SE 10-15'
qtzite ledge ends on hill side
at WP 201 N 37 12.051 W 80 17.764
el 1549 chert float above sh pit
then cgl qtzite float
IRO 5313 olive lithic ss w abundant
brachiopod molds at WP 202
N 37° 12.023 W 80° 17.735 el 1645
N 20W 24NE bedding thk prec.
IRO 5314 olive to light grn sltstn/
fine ss beneath 10' qtz arenite
ledge N 10W 10NE WP 210
N 37° 12.012 W 080° 17 714'
el 1696
IRO 5315 blk to ltgy chert
med thk bedded, holds
hill top above ledge at 14
WP 204 N 37 12 016 W80 17.646
IRO 5316 WP 205 N37 11 992
W 80° 17.625' el 1739 karst
depression between chert knob
and dolosn ridge
IRO 5317 N 30E 14 SE ledges
ltgy thn to laminated dol WP 206
N 37° 11 982 W 80 17.592 1819

talus slope below el 8606
Ecol 4/21/10
IRO 5413 Med - thk bedded gray dol N 85W 22 NE
IRO 5414 breccia and phyllite chips on gentler slope below wash dol. OC
IRO 5415 spring 30 gal/min N65E 60 NW thk bedded gray dol Frac N20E 80 NW
IRO 5416 N70E 10° OMG covered above in travertine
IRO 5417 50' ledge of Silurian SS N70E 30SE
IRO5412
N54E 25SE Mass dol (Ecol?)
10' Days beneath Fault
IRO 5525 NS plunging assym. Fold plunges 5 at S

4/22/10 SPRING HOLLOW SPH 1

N82E 60 NW photo

of Right abutment hinges

interbedded dol and red arg

N70E 5NE

WP

SPH 2 photo of qtzite blders working way down slope from old Fan - very round

SPH 3 photo of fold with in road cut

dextral kaust pipe

hinge N80W plunges 2° NE

fault plane beds w/por in HW N80E vert



truncating developed in bed

4/28/10

IRO 5417

N 65 E 16 NW thin mid bedded ss

IRO 5418 N 80 W 46 SW QT

Fg ss in Martinsburg clear

N 80 W 76 SW WP

Travertine dam ~3' high @

N37 11 440 W80 19.686

IRO 5419 property corner stake

at WP 521 N37° 11.248' W80 19.610

el 771 at stm intersection

~20' falls in 100' from

Left Fork

IRO 5419 WP530 N37° 11.232 W80° 19.622

el 1591 ~50' travertine cascade

below large dol ledge E W 60 S

IRO 5420 Thin bedded platy

dol w/ dk gry sh or

argillite N 65 E 20 N 40 W 54 SW

just up hill at drainage

IRO 5421 WP 531 N37° 11.271 W80° 19.710

el 1604. N 56 W 85 NE Thk beds

of ribbon laminated gray dol

burrow struct is rsk } = tel (a)

road washed out expose a

4/28/10 IRO 5422 WP 531
Massive - thk bedded gry dol beds in strm N40W 60NE thin mantle of algae and wet tufa below
WP N 37° 10.890' W80° 19.831' el 1662
IRO 5710 Irreg laminated blue grey algal limestone, micritic N24W 66 NE at WP 032, N37° 10.765 W80° 19.408 el 2042 al is 100' wide stream is subsurface above gas line
IRO 5711 N20W 40NE thk bedded gray dol ledges on point al on both sides at WP 533
N37° 10.614 W80° 19.835' 1846 el 1900 T
IRO 5712 N20W 60NE thk/med bedded gray dol. some algal Chert masses up to 1.5' dia on ridge line WP 534
N37° 10.460 W80° 19.789' 1970
IRO 5713 N50E 40SE thin blue algal ls bed w/ thk bedded butcher block dol. WP 535
N37 10 415. W80 19 852

May 13 '10 IRO 5523
WP sec 32 dol on trail before
sh Ocs on trail just beyond
drainage
IRO 5524 olive drab to
lt brown argillite
lag w/ fine ss above
N 72 E 205
N 37 11.675
W 8 C 18.874

elv 1957

WP 591

© 2000. Day Runner, Inc. All Rights Reserved.

© 2000. Day Runner, Inc. All Rights Reserved.

IRO 5430 N 14 W 12 NE
massive decalcified dol ls
breccia ledge at WP
head of steep hollow
WP 562 N37° 11.123' W80° 19.238
el 1901

IRO 5431 100' dia sink
-20' deep at WP 563
N37° 11.064 W80° 19.211
el 1927

IRO 5432 ledge of blue gray
thin bedded algal ls
E-W 38 N WP 564 N37° 10.942'
el 1859 1860 W80° 19.206'

IRO 5718 ledge of breccia
or coarse dol cgl clast
line E-W 46 N
WP 566 N37° 10.839 W80° 19.317' el 1954

IRO 5719 Thn bded blue gray
algal limestone w/ stron
an thin cgl beds rsy
N 60 W 60 NE WP 566
N37° 10.808 W80° 19.552 el 1996
calcite healed cross fract
N20E 75 NW

IRO 5720 possible cave entrance beneath ledges of blue gray algal matte banded Elbrook limestone at WP 567 N37 10.628 W80 19.968 el 1856 N20W 30NE photos

IRO 4918 Cave entrance trends S74E From shallow sink el 1886 thin / mass algal ls + dol WP 568 N 37° 10.719' W 80° 20.005 N10W 20 NE

IRO4919 Blue gray ls beds exposed on pipeline, Sink hole 10'x40' crevasse in ls and dol just over hill from pipeline at 1845 WP 569 N37° 10.511 W 80° 20.064 N4W 40 NE

IRO 4612 Kink in thk gry dol beds E-W 5W photo N 37 10.919 W80 20.012 el 2043

IRO 5433 Thk gray dol bed N50E 20 NW cross Frac N6W 72 NE WP 571 N37 10° 963 W 80° 19 990 el 1982

IRO 5434 N80W 30 NE thk gry dol WP572 N 37° 10.945' W 80° 19.954' el 1929

IRO 5714 · N 40 W 50 SW blue gray and brown banded algal ls on trail at WP 536 N37 10.468 W80 19.673 el 1532

IRO 5715 N 60 E 80 NW gently undulose fg gray dol lgst massive xline (algal) dol on nose

IRO 5716 N 60 W 60 NE thin bedded blue gray algal ls on trail at WP 537 N37° 10.557' W80° 19.669' el 1977 Polymictic dol/arg breccia on knob

IRO 5717 N 20 W 30 NE thin bedded algal ls and platy dol. in short Eel cycles (photos at WP 538 N37° 10.482 W80° 19.879 el 1961

IRO 4910 N 10 W 30 NE dk gry microxine dol w/ brn weath butcher block text. ON SW side of 200' dia sink ~ 50' deep

IRO 4911 N 26 W 34 NE photo of platy argillaceous dol beds with algal stromatolites indicated used WP 539 N37 10.603 W80° 20.042 el 2010

IRO 4912 N20W 24 NE
lam dol at top of fenestella
cycle that contains blue gray ls
micrite near base
elbrook 5'
cycle
at edge of
cleared area
WP 540 N37 10.606' W80° 20.081 el 1965



IRO 4913 WP 541 N37°10.46 W80°20.132 1829
Shaly chips in soil then lt pinkish gray to creme colored fine xl lmst dol float
IRO 4914 WP cleaved massive gray dol N54W 20NE clean. N70E 70NW
WP 542 N37° 10.741' W80° 20.243 el 1876
Elbrook above pipeline
IRO 4915 N26W 30 NE thin bedded to med bedded blu gray algal ls + dol on trail at WP 543
N37°10.784 W80°20.329 el 1925
IRO 4916 N72°W 26 NE thk bedded dol ledge on trail WP

3/10/0

IRO 554 thinbedded gray to tan layered shly dol ledges on trail at WP215 N37 11424 W80 18758 el 1898 N26E. 80 SE clevage gentler than bedding

IRO 555 N 74 W 44 NE thin bedded gry to tan laminite with cren folds plunging N80W N40W 36°NW WP216 N37°11.483 W80°18.827 1909 (1880) Photo of folds

IRO 556 N 60E 44 SE thin bedded laminate dol WP217 N37°11.52 W80° 18.827' el 1929

IRO 557 N 80W 5°NE

IRO 558 N 60W 60S v crinkly lam gray dolomn ledge at trail split WP 218 N 37° 11.600' W 80° 18.785' el 1972

IRO 559 hematite +Mn CO_3 ? ? cemented breccia pile next to trail at el 2000' WP 219 el 2033 N37°11.656 W80°18.749 photo of breccia

3/10/10

IRO 5319 air strike across Ginger Hollow - Poloson cliff blocks EW 17 N 50' high

IRO 5320 N 30-20 E 20 SE dk gry and white ss w/ SEP text fg qtz, micro fold coy

WP 225 N 37° 11.930 W 80° 18.270 el 1981 photos across river show fold hinge / off set

IRO 5321 el 1868 WP 226 N 37° 12.012 W 080 18 299 el 1737 angular white qtzite on slope above steep slope exposes ocherous shale chips, argillite and olive silt fine sand stone chips

IRO 5322 el 16806 N 60E 46SE white qtz arenite w/inv. cross beds 6' thk Cross N 46E 30SE

WP 227 N 37 12 073 W 80 18.322 1590

IRO 5526 gray sh + creme ls in Millboro N 80E 25 SE WP 228 N 37° 12. 145' W 80° 18 457' 1393

3/17/10

IRO 545 thn/slaty ø dk gry WP 256 N 50 W 60 SW N 37 11 310 W 80 19 146 el 1644

4/20/12 IRO 716



12
18
p18
48"
5'
15"
2.6"

beds N 72 W 10 SW

IRO 717 photos of cave in Ecol straticulate dolomite beds dip gently SW 620 W dip strike N70E @ 14°SW Sink is 100' dia 20' deep

IRO 718 pits and board end pile at old saw mill site sandy soil creme colored dol blocks on site

IRO 719 straticulate dol forms dip slope, ledges strike N70E dipping 10 SE Ecol

IRO 728 very light gray to white weathered microxline dolomite bed forms a small pavement along old logging road N 70E 20SE @ 1860 ft

IRO 7210 light gray - creme colored thk bedded stratiform dol N70E 40SE ledges on trail

IRO 7211 light gray - creme colored dolomite w Flat pebble cgl beds on erosive base developed on algal laminite beds at top of previous cycle indicate NW Facing N60E 80SE

IRO 7212 Blue gray algal boundstone/wackestone Float a 1850 b long trail Trail switch back to SW N80E 60SE shly or platy elbrook dol arg above

IRO 7213 N72E 65SE sheared ribb on banded blue gray dol 150c by fallen oak at cl 2010 on trail

IRO 7214 E-W 40S thk beds of gray brown weath dolomite with some shaly beds yellow orange chips in soil el ~1000

April 12 2010 IRONTO IRO 8515
N 10E 55 NW thk - thin bedded
grey - brn weath dol on trail
at WP 472 N37 08.550 W80 19.6
el 2728

IRO 8516 N 10E 20 SE
IRO 8517 round qtzite cobbles
at house

IRO 8716 WP 473 N37 08.214
W80 19.509
N 65E 30 SE el 2723
ribbon lam ls/dol + Fg
gray weath ss ledges
in cut 117

IRO 760 Mixed al w/ old maroon
qtz ribbon mylonite, coarse qtzite
in back of new house

IRO 767 Angular Eco ss
resid up tz 2'

IRO 7514 Chert residuum
along ridge

IRO 7515 qtz gravel along road
in cut ~ 10' above grade
WP 474 N37 08.444 W80 21.546 el 2740

IRO 743 6' gray clay (pipe clay exposed in base of al at Industrial park includes round qtz pebbles & cobbles grades up in to yellow orang mottled clay loam - pebbles and cobbles thr WP 475 N37 08 .465 W80 21 .651 el 2159

IRO 7516 E-W 30s Gray thk bedded buture block dol beds with flat chert nodules along beddeng Core WP 476 N37 08 540 2129 W80 21 617

IRO 744 20' highwall in uncons mtl many round cobbles WP 476 N37 08 54 W80 21 88

IRO 781 N78E 56SE dk gray mottled crystalline dolomite WP 477 N37 07 640 El 2169 W80 21 622 thin rubble of algal bedd large blocks of dolomitized ribbon rock.

IRO 7215 el 1990 below barn N80W 80 SW ribbony dol bed interlayered with med bed of algal dol. oolitic chert float on trail. Much SS Float Ecol

IRO 7422 EW - 74 SE striaticulate creme colored siliceous dol OC in Stream Cl 1900 6

IRO 7423 EW 60 S massive bedded gray dol el 1850 6

IRO 7424 EW 60 S White weath striaticulate dol at el 1820

IRO 7110 N80E 54 SE Massive gray butcher block weathered brown dol

IRO 7111 N60W 10 SW gray, fg, butcher block dolomite in stream - Noal

IRO 7112 N50W 70NE cascade of dk gray thin bedded el brook dol. in Attidion

Fore limb, brittle cross fracture.
IRO 7113 N20W 24NE end of
completly exposed section of Upper
elbrook ribbon dolomite, algal dol ls
thin bedded ls & sh (dark gray)
IRO 7114 N60W 80SW Massive dol
beds, gray Fg xline w butcherblock
photo of travertine Cg lined
IRO 7115 N70E 40 SE mass gray
brecciated dol above dry
section of stream bed poss.
cave entrance
IRO 7116 N8E 44SE lt gray to white Straticulate
dol, interbedded with Fg
gray dolomicrite ECol?
IRO 7117 thin black arg bed
separates thick sequence
of cream colored straticulite
dol from massive gray cherty
dol/cdgc. Base of CCol?
E-W 20N
IRO 7118 N20W 40NE shiny
. strat. dol. lt gr (Ecol)
IRO 7119 silic. lt gry-
trat dol and 1" thk SS layer

4/22/10 EL 1975
N 37°09.67'
IRO 7219 WP 514 W80 21 329
black chert float tan chips
of platy dol along trav
IRO 7220 N 20W 30 SW ledges
of massive to thick bedded gray
dolomite prospect pit in
mineralized pyrite? silicified
breccia at WP 515 N 37°09 591
W80 21 297
el 1919 17506 1800T
T model Ford gas tank
and cowling
IRO 7221 Iron mine adit
developed along 2-3' thick
argillaceous dol with layers
of hematite, now foliate
N 40 W 34 SW photos of
adit - timbers visible dump
suggest less than 50' back
WP 516 N 37 09 621 W80° 21.170
el 2004 17506
IRO 7222 Spring flow emerges
from beneath dol. ledge
N55W 25SW WP 517
N37 09 800 W80 21 050 el 1852
1C49 6

IRO 7323 begin karst wetland spring flow below travertine dam at WP 518 N37°10.037 W80°20.745 el 1520

IRO 4823 Spring on 20' travertine mound WP N 37 10 120 el 1660 W 80 20 907

IRO 736 N80W 75SW gray fg Staticulate dol w/ siliceous silty parting at N 37 09.785 W 80 20.765

IRO 737 N60E 70SE yell orange weath shly dol beds in road bed - Cq

IRO 738 N 20 W 60 SW Foliation in cataclastic breccia (green) Weathered yellow orange N37 09.850 W80 20.609 el 1852'

IRO 739 Photos of Travertine in stream valley at N 37 09.725 W80 20.606 el 1740 6c. 1660 +

IRO 7310 Photo of debris flow massive dol E-W to N80W dip 40S stream full of angular 2' blocks possibly upper elbrook / Big Spring Sta N37 09 670 W 80 20 586' photo of Flat pebble cgl block in dry stream bed stream appears at ledge dry above on Cq

IRO 7311 Partly dolomitized ribbon rock (photo) E-W 20 S1 blocks choke stream (debris flo N37°09.618 W80°20.491

IRO 7312 N66E 12 SE ltgry
dol with siliceous partings (
Oco) highly deformed cleaved
red clay mtx in stream = old debris
flo (Photo) N37 09 518 W 80 20 492
IRO 7313 Massive bedded sandy dol
w/ siliceous parting E-W 505 atel 1800b
N37° 09.438' W 80° 20.515'
IRO 7314 Massive bedded sand dol
N60E 60NW accross | cross bedded
Synclinal axis | Photo
N 37° 09.394 W 80° 20.470 el 1800b
IRO 7315 N60E 20SE beds Flip
into fault zone
IRO 7316 100' Flood plain ends
in bedrock gorge. Massive ltgry
dol beds in stream N66E 20° on
water line N37° 09.351 W80° 20.347
Oco
IRO 7317 photo of big
spring and wetland valley
at N 37 09 274 W 80 20 381
9/15/10 IRONTO QUAD
IRO 7329 Tgp Oco dol w/
sil partings Strat. cuts beds
N80W 40SW ON NEW 25TO Road

IRO 732 N 70E 20 SE axial plane of 100' wide anticline in slaty argillaceous Cambrian Elbrook dol Sink hole to s along fault

IRO 733 N 80 E 60 NW slaty cleavage in argillaceous dolomite photo of orange weathered phyllite-breccia ledge N 37° 09.143 W 80° 20.798

IRO 721 N 76E 40 SE med gray thk bedded sacharoidal weathered dolomite photo of organic rich wetland soil in flat bottomed Forest Valley for Nan

IRO 722 cherty lam lt & dk gray dol E-W 85 N N 37° 09.289 W 80° 20.971 Meadow lands ~ 200' wide

IRO 723 cement posts mark house site dol ledges N60W 50 SW photo of cacté and dol ledge N 37 09 315 W 80 21 012

IRO 724 Photo of yellow orange Weatered gray grn argillite w slaty deav interbedded w/ Laminated dol and dolomitized cgl zones that

IRO 724 cont'd can be used to delineate typical elbrook 'short cycles N37°09.411 W80 21007

IRO 725 thk bedded dk gry fg xline dol at N37 09.446 N54W 40SW. stratiolate W80 21.941' leached white sandy soil on top No cobbl

IRO726 N80E 25 NW fine grained xl g'y dolomite. on road bed N37 09.512 W80 21.004 el 1880 1900 + Cor.

IRO 727 N76W 20SW ledge OF fine grained orange weathered sandy dolomite (Oc lower)? el 1990 N37 09 611 W80°20.964

IRO 728 sink w/mass dol bods in botton (Photo at N37°09.631' el 2020 rim W80°20.923' N50W 20 SW el 2000 at bottom Dia 100' upper elbrook? or Oco

IRO 734 N40W 24SW stratiwavy gray dol w sandy partings

IRO 735 N 30W 44 SW thk bedded gray sach dol w/ butcher block N37 09 733 W80 20 787 el 1980

BBG 9617 E-W 50 S rubbly weathering lt gray ls w/thin dol partings ⊂⊃Σ abdt algal features

BBG 9618 transported algal chert heads size of basketball also cobbles of Chilhowee derived from old Sheiar River Terrace 4114/10

IRO 731 N37 09.288 W82 20.204 d Isaac Walton N 20 W 5 SW thk bdd brecciated dol w/sharp intervals

IRO 769 EW 15 S massive crame— lt gray (Big Springs Sta Ds)

IRO 7610 N 37 09.114 W 80 20.485 Massive crams to lt gry dolomite in cut small cave opening dol w/thin brn sandy bds N74E 62 SE photo of cut, close up of bds W facing criterion indicating OT bed

IRO 7611 N 37.08 982 W 80 20 544 thk bedded gray dol w/ hatchmarks N85E 26 SE

IRO 7612 N 76E 36 SE thk bedded gray xline dol interbedded w/ blue gray and brn-tan ribbon rock or dolomitic limestone Facies w/ flat pebble cgl beds.

IRO 7613 N 74E 54 SE photo of algal strom ribbon rock boundary showing agal 1cm "ladders" between strom



N 37° 08.911
W 80 26.501 ± 17'

IRO 7614 N 64 E 56 SE thin bedded tan weath supertidal laminate at N 37° 08.890 Mass an cgl beds above W 80 20 506 at beginning of VDOT Fill fold hinge 5 09 W 65 W (photo)

IRO 7615 big cut N 74 E 60 SE Massive and brown-tan banded silic dolomite. Occ steep fault N 40 E 80 NW brecciated zone

IRO 774 N 37°07.594 W80°22.08
dolomite platy dolomite and dusky red argillite in ditch line on access road el 2160 ft.

IRO 788 massive to thk bedded algal laminated upper Elbrook ledges N70E 50SE el 2050

IRO 789 Big spring under old power line at N37 07 671 W80°21 270 Thick bedded gray dolomite w/ algal mottles E-W 60S

PLT 123 ledge of decalcified lam lst dol overlies yellow orange polymictic breccia N76W 50 SW

IRO 7910 big laminated dol argillite ledge in lower Elbrook 2 photos, one photo of original travertine dam modified by land owner - Karst wetland N37 07 511 W80°20.940 el 1920

IRO 7811 thk dol ledge w/ thn platy argillite zones N50W10°

IRO 7812 photo of broken cobbles in plowed garden

IRO 794 at corner of lot 9/5
6" dia white qtzite cobs
in silty clay matrix.
IRO 795 clean N 37 08 036
White qtz soil W 80° 20' 351
BSSD N 60E 30SE
IRO 775 Old quarry / borrow pit
N89E 14SE @ N37°08.04
white and grey w/ W 80 22 204
& cherty nodules (photo) behind GO RACE
IRO 776 Several large blocks in
front yard of newer home
White - lt grey sandy
dolomite @ co
IRO 777 White sandstone
boulder pitted but well
rounded, round sand
grains, recemented w qtz
and iron N 37 07 947
W 80 22 252
IRO 789 lot between BP
and Knights N 15' orange
silty clay to white
round quartz cobbles
N 37°08.188' W 80°2 1.570'
Photo

IRO 782 N 65 E 36 SE
thin to med bedded
ribbon rock facies dol w
staticulate banding

IRO 783 N 85 E Base thin
bedded laminated dol overlies
light gray - creme weathered
gray microcrystalline dol

IRO 782 quartzite cobbles along
drive at 228 Glade Dr Coy

IRO 784 qtzite cobble pebbles
at new house much as (3" chunk
float at end of Cullen Court

IRO 786 N 75 E 20 SE cut at
edge of Yard at WP 478 0/2161
Lomoor St. N 37 08 024 W80 21 198
Staticulate light gray tan
weathered dolomite beds

IRO 787 sink hole behind Fairfield
In with 3 drains dwelled
large deep water to drain
Chert and ss float in silty
loamy soil

IRO 788 INTERSTATE QUEENITE PARK
original grade dropped ~ 6' below
house and flood tanks for trailer
park
IRO 789 Straticulate dol / flat
pebble cgl block in WP 479
church yard behind ITD dealer
N 37 08 373 W 80 21 007 el 1215 a
IRO 7810 graded land w/some
cht some Ecoss chips and
several exotic BR gr to cobbles
at WP 481 N 37 08 860 W 80 21 115
el 2157
IBB6 964 WP 482 Dark gray
thin bedded to wavy laminated
limestone w thin partings
White veins WP 482 N 37 08 4?
Beds E-W 54S el 2094 W 80 22 900
Veins N 10 W, 80 E, delicate (subtle)
karst next to road
BB6 965 small quarry opening
dark gray dol w/ chert
lenses thin sock parting
could be Knox or Beekmantown
deformed beds W 30 E 70 SE
EW 80 N N 60 E 30 SE

IRO 7218 N 60W 18° SW
straticulate layered dol
(Oco Big Springs Station Member)
IRO 7219 piles of oolitic chT
below rope trail and blocks of dolomite

IRO 7220 Massive ledge of
straticulate dol w/ siliceous
silt and sand ribbing
N72E W 60 NE ⊖ Co ☒M
IRO 8125 Gray siliceous
straticulate dol, thin sandy
soil on ridge top N 76E 32SW
IRO 7221 Thick bedded brn
weath siliceous dol N 70W
44 SW on top of ridge
topo forms indicate SW dipping
beds
IRO 7222 dark gray xline
dol, thk bedded alternating
with thin shaley arg lt.
dol. N 76 W 50 SW
Air Strike N 76W 38 SW in valley
below
IRO 8126 el 1850 ft
Massive brn weath
dol ledge 3-4' thk overlain by ribbon dol N60E 80SE

IRO 8126 contd this ribbon dol is below sandy ledges ; Cel P.

IRO 8127 massive bedded lt. gray sandy dol N46W 18SW l.c/s above dk and light gray dol with brown-yellow ribbon banding disposed in short upward fining "Elbrook Cycles" Big Spring Station Member Conococheague

IRO 8128 Massive stratiform lite dol on hose N 60W 20 SW oolitic chert w/flat pebble beds litters crest



PLT 121 N70E 20SE lam dol Cel

PLT 122 platy lam tan argillaceous dol N70E 80NW

PLT 123 platy lam dol N60E 30NW

IRO 773 photo of yellow soil profile w/ gry and red motts and white bleached gte cobbles and pebbles N 37° 07.583 W 80° 22.145'

IRO 7810 photos of cobbles and pebbles in silty clay mtx along I81 off ramp at Bypass in Christiansburg N37 07925 W80° 22.254'

BBG 981 massive gray xline dol. w/ butcher block weathering, chert replacement structures in quarry N36W 40SW @ N 37° 08.151' W 80° 23.913'

BBG 951 blocks of ollite and sandstone in fill from cut to South at turn around

BBG 952 Photos of folds in brecciated green and dusky red phyllite

fold hinge 250W 20SW

axial surface?

high angle Fault N20E 75SE

N37° 08.584' W 80° 23.398'

cherty soil along old road

BBG 991 creme to yellow orange dolomite, fine xline w/ much chert debris

BBG 992 chert debris on the reached soil. No bedrock here

N 37° 08.312 W 80° 23.172

PLT 111 WP 006
terrace gravel in new cut
N 37 27 189
W 80 22 363 2160

Bill Henika

6/11 IRO 419 N4°E 14SE
massive gray fg dol - el 1770
N 37 12 .515 W80 22.288'

IRO 410
N 30 W 10 SE burrowed y/w
and gray dol ls el 1660
N 37° 12, 358 W 80° 22 .182

IRO 411 N20E 10SE
burrow mottled dol
& upper 0 be el 1640
N 37 12.290 W 80° 22 .182

IRO 412 Massive fossil/glau
gray wacke sh, w burrow mottles ls
N36E 20SE, 01n
N 37 12 .157 W 80° 22 .040
N?

IRO 413 el 1960 6
med gray dol ledges
on road bank and driveway
N 10 W 16 NE

IRO 414 massive light
gray massive dol N5W 12SE
by culvert ~K 1830

10/7/11 IRO-14 11
N 14 W 20 NE 2' rubbly
weath white chert bed
comes down to ck.
Stream disappears above
In rubble at el 1630b
N 37° 13.978 W 80° 22.442
IRO-1412 el 1620b
thk bedded, rounded weath
blue gray wackestn is
fizzes at N 37° 13.977
4 sats W 80° 22.407
N 20 E 20 NE
IRO-1413 ~ 2' thick bedded
grst wackestn fizzes at
el 1580b N37 13.957 W 80 22.295
heavy chert/dol above
N 10 W 14 NE
IRO-1414 30' dol section
as stream bends to SE
N 8 E 14 SE N 37° 13.947
Some ~~~ W 80 22.172
laminated algal matts
overlain by thk gs beds
Some lime beds

Bill Henrikes

NOTES Nov 4 Hickory Hills

IRO 1515 at toe of Hdr Flow photo of large bldrs on upper edinburg surface
N37 13 483 W 80 21.252

IRO1516 el 1800 b photo of yellow silty clay w/ quartzite bldrs typical of alluvial valley fill N 37° 13.590
W 80° 20.946

strike and dip across creek
N 8 W 20 NE ochraus - olive weathered arg w 2' 15 layers
LOH

IRO-1514 on Road bearing N20E slope 1-2° to SW Bays section is 80 steps wide beds dip gently NE 10° strike N 40W photos N37°13.583 W80°20.833

IRO-1612 N26W 20 NE Top of Bays is 6" red bed (photo beneath olive silt arg ~~hills~~ of Martinsburg, El 1900b
N37°13 670 W 80°20.727

IRO-1517 Mottled yellowish orange - white qtz SS Sag in bottom of 5' hole dip on road bank
dip 207S 6

IRO-1518 dusk red brown clay stone Sag in Gant coy Pheasant trap
N 60 W 22 NE
N 37°13.743 W 80° 20.852

Day Runner®

NOTES

IRO-1613 olive to yellow ocn weathered silty argillite w/ 4" ls interbeds on skid road at el 2020 N37°13.505' W80° 20.688'

bedding N10W 20NE
fold plunge N80E 12NE

[illegible] s has cleaving pattern

IRO-1614 debris flow fills this draw interbedded ls el 2010 + 2ft ocean N37 13 377 W80 20 708 N10W 20NE photo of interbedded ls facing

Sample at N37°13 393' W80°20 138 2-3'

IRO-1515 Blocks and slabs on debris fan behind barn at N37° 13.570 W80° 21.157

IRO-1520 4' block of cgl in debris flow el. 1542. N 37 13 613 W 80 21 355

IRO-1521 Radius extends 20' SW from N37° 13.628 W80° 21.463 el 1510 Bds. N10W 20° NE

IRO-1416 gray Mississippian by River at N37 13 032 W80 21.097 DIP 20SE

Item # 033-3

NOTES Lipsey Farm

dk gry v/f inc shales n
just above Flood plain
strike N, creek dip
15-20 SE O/n

IRO 1 519 Photo of

Blacksburg from
SW end of Catawba
syncline (Hickory Hill)

Taylor Hollow Nov 7, 2011

IRO- N 60E 20 SE argillaceous
ls/slaty argillite

IRO 4 29 thin bedded w/slaty
cleavage

IRO 4 210 Gray slaty argillite
some more massive
N 60E 30SE Fasts
Driveway 1297 THR

IRO-193 N 50W 20 NE
N 37° 12.645 W 80° 20.438'
Massive argillite w/slaty
cleavage

IRO-271 el 1738 b brown weath
punk calc argillite OC
in switch back
N 37° 12.628 W 80 19.897
beds N 70 E 30 SE

IRO 272 el 1830 gray arg w/
slaty cleav, white str
SS float from above N 60 E 20 SE
N 37° 12.700 W 80° 19.781

IRO 273 el 1860 N 39 E 20 SE Ink bull ls
contact on road N 37 12.697
W 80 19.770

Day Runners

NOTES

IRO 274 el 1930 b red & grn dusky red mdsn Float and resid in road on point at N37 12 685 W80 19 702

IRO-275 el 2050 b in cut on spur of Hightop Mtn N37 12.532 W80 19.750 Olive shale + slty sap N80E 40SE bedding plane cleavage

IRO-276 on Rt 606 at el 2000 b brown ss fft conc white qtz arenite chips N37 12.668 W80 19 725

IRO-277 E-W 60N el 1610 b gray argillite w/ slaty cleavage N37 12.760 W80°19.897

Nov 28 IRO 129 6elow New house
corse blders of SS From Dec
above form a Fan like debris
deposit on SW side of stream
black shaly limestone ledge
on N S. dr N 30 E 20 SE
thin bedded blk argillite

IRO 1210 N 20E 20 SE dk grey
argillite grades upwards into
yelow grweathered argillite
at at
IRO 1211 10' white/lt grey
quartz SS N 40 E 20SE at
el ot
IRO-1212 el 10 6 reddish
brn to dusky red mudstone
silts on top of SS
N 10E 10SE
IRO 1137 10' below edge of dusky
red mdsn on fenceline trail
N 30 E 12 SE el 1900 Topo

IRO 1213 el 1990 oc 6' of
coarse brwn wcath gtz SS
cross beds Sample and Photo
N 37°14.444' W 80°20.889'
N 10E 12 IRO - 1214
House el 1660 el 1600
N40E 20 SE thin bedded arg, blk
Address 2618, 2614 Winston's
Gate

IRO-1215 cht gravel td level above cl.

IRO-3216 N29E 10SE dk fry blocky carb ss/slaty clay

Nov 29 2010 Kaknis cemetery IRO 139 green shale overlying red mdstn 106

IRO 1350 N 24E 10SE bleached brn sh at cl 1975-25' above cem on old road

IRO 1311 cl 1980 green slaty ss OM6 N 36E 18 SE

IRO 1312 stream filled w/ debris flow - coarse cgl ftz ss from above cl 1900b red mdstn float in road embankment OC N 24E 18 SE @ 1850 b

IRO-1313 N 12E 10SE 10-15' w/ 4' exposed Walker Mtn ss @ 1790b coarse cgl blks debris from D/S def bench on NE side of drainage.

is formed on SS

IRO 1314 at edge of Field old fenceline el 1780 ± (reset cor ~30' cor

IRO 1315 at farm lane below Kaknis house el 1720± N 30 E 24 SE ocher weathd calc mdstn w/ slaty cleav,

IRO 1316 walker mt SS OCg in stream ~30' wide 20' high el 18706
N 37° 14.550 W 20.572
N 20 E 20 SE.

IRO 1317 N 22 E 20 SE 6' ledge maroon mdstn el 1850 ±

IRO 1318 el 2020 ± on road next to Field ~50' blow saddle orange ochre ls sap N 40 E 22 SE Omb trenton ! Top of maroon Mudstn ~25' below on road at N 37 14 477 W 80 20 543

IRO-1319 N 40 E 22 SE maroon dk brn mdstn in road bank below cabinsite el 19506 N 37° 14 493 W 80° 20 522

Hawk Siting — baby Hawk Playing?

IRO 1216

N68E 20 SE thin bedded dk gray argillite and graptolaceous ls in deep entrenched stream cut through debris flow (photo)



IRO 1217 old spring house (Willow Spring) built under VDOT roadway
N 37° 14.937 W 80 21.293'

IRO-117 N36E 22SE coarse grain stone (Murat facies) above Agnew Quarry
N 37

IRO 118 in Agnew Quarry
N45W 22 NE coarse gs bed w/abundant brac valves trilobite spines en echelon Fracs
N37°19.725
W80°21.902
N80E 81NW
N80E 18SE
in CK
Black chert preserves brachs
N34E 12°E on bench

Agnew Farm O/h

IRO-119 N26E 10SE Graes on bedding plane fine ribs wackestn dk gray thick bedded



- N 37° 14.798 W 80 22.013. sink hole partly filled w/ quarry overburden

IRO-1110 N32E 20SE 48 steps wide dk gray micrite in fence corner behind new house across from chapel (old church) N37 14.758 W 80° 22.043 Beekmantown Chert on hill above oc along fence line

N 37°14.763 W 80 22 005 Fault on contact O w/ OLl

N 37 14.787 W 80 22 013 Fault less than 20 on visible

IRO-1111 contact between beekmantown Dolomite and New Market? Med then bedded grey lime. above dk grey fan weathered dolomite Jufa in stream

N 37 14 735 W 80 22 077 N20E 20SE at Fence

IRO-1112 N5 10E
Massive ledges of gray laminated & silicoous dol large chert blocks down stream
N37 14 .775 W80 22 095

IRO-1113 40' thick blue gray micrite ∞
N30W 6° NE
N37° 14.820 W 80° 22. 115'

IRO-1114 N6E 10SE
thin bedded - lam sil. gray dol. ledge at el 1510b
N37° 14.805' W 22. 205'

IRO-1115 N10E 6SE 2'
mass gray sil dol ledge
at N 37° 14 : 873'
W 80 22. 282' el 1580b

IRO-1116 N32E 10SE
pavement on SE side of
Indian Run N37° 14 898 W80 22.305

IRO-1117 at Listers Mill
heavy Tufa ~ 15' above
pinacled dol in crk total
fall ~ 40'. dol ledge above
N10E 15SE N37 14 975 W80 22.353

IRO-1118 Plunge pool below tufa ledge N18E 18SE 30' dia 6' deep pool N 37 14.965 W80 22 498

IRO-1119 N65W 20NE thk bedded grey dol N 37° 14.937 W 80° 22.600 dry stream bed separated from main stream by elevate road (not Wilderness Rd) possibly Lusters Gate Mill run? in corner of quad map as tufa along Flat terrace Wilderness Road is on higher terrace level cut into slope and with obvious fills dominated by weathered Beekmantown chert blocks and boulders Returned to Lusters Gate by way of Wilderness Road which is hard to trace through the Back Yards of Gate Way Baptist School

NOTES Dec 2

IRO 1120 gray massive micrite (On N 20 E 22 SE bedding w/ rillenstein Fluted surface



IRO 1121 gray micrite becomes coarse dol packestone w chert clasts at base dolomite below N 50 E 30 SE basal cgl layer

IRO 1122 N S 20 SE lam gray dol w/ cht debris (Ole behind garage

IRO 1123 el 1635-40 Tufa in stream bed, large X dol blocks 6' x 1' x 4' beds N 20 E 15 SE Obc thk bedded gray dol

IRO 1124 Angular fracturing / strike Vert N 88 W - 8 SW el 1650 ft N 10 W 12 NE waterline strikes on grooved beds

IRO 1125 el 1680 N S 10 E thk bedded gray xline dol large blocks on slope to NE. New House on ridge line to NE

Day Runners

NOTES DEC 3 Field Trip w/ Radford and Kent State

IRO-6218 Sample of green breccia matrix from I81 climbing lane cut gray ish green coarse crystalline dolomite matrix
N 37° 11.962'
W 80° 16.116'

Dec 5 - 11

IRO-1126



dk gray wackestn silicified fossils many shell fragments

Tension veins
N 50 W 85 SW calc filled N/P

IRO 1127 dk gry wackestone w/ bio grains abundant, brach and silic cephalopod fragments Neither Lincolnshire nor Newmarket on NW side of 200' dia 30' deep conical doline w/ drain to sub about 300' along fence line from IRO 1110

IRO-1128 gray wackstn abdt brach and ceph fossils silicified, tension + shear fractures N 14 W 16 SW fluting and weathering is veins transitional to Qy

Item # 033-3

NOTES 12/05/11

IRO-1128 contd cavity veins offset



6y/ato veins

MCM 771
N40E 16SE light gray weathered gray wackes on edge of 200' wide sink another just to NE definately Lincolnshire - rounded black chert in gry ls ledges along SE rim of doline

MCM 772 N46E 10NW near flat layered tan-gray weathered fine xline dol (Obe) just above road mach chert in woods

IRO 1129 N80W 60SW
el 1660 crossed contact
b Obe \ Oln at ~1700'
basal ls is gry grainstone (with dark fossil fragments grades upards into dk gray fg wackestone with some dk grg Micrite

IRO N30 in sink - cave ent. across dock to SE N40E 80

MCM 773 N70E 60SE gray xline dol, thk bedded, laminated

NOTES

MCM773	on nose at el 7006 contact 20' below dol is w/ dol + cht pebble sized ± clasts Oln/Obe
MCM-774	thk bedded gray x line dol LS at el 7000 N44E FROM OLD BLOCK House at LUSTERS GATE MILL (Oln N80E 20 NW
MCM-775	on nose above lusters gate mill at el 17201 2' thk Lher + bed N60E 60SE
IRO 1131	N24E 10 mass gray ls Sln at 17120 in cedar field across old fence line from MCM 775
Dec 8, 2011	
MCM 781	ocs 6 C coarse grag gainstone in front of Barn N40W 16 NE
MCM 782	N30W 16 NE Thk bedded gray. fine grained sn
IRO 3317	N60E 16 SE coarse g.ay gs weathers brn
MCM 783	dk gray gs / wackestn weathed redish brn N80W 60 NE on N side of 100' dia 20' deep doline (Photo)

NOTES

MCM 184 black slaty arg
IRO 3318 N10E 18SE in
borrow pit by pond
IRO 3319 gental dipping along
fence line fault trace?
IRO 3320 chips in brn clay
soil + very wet olive
clay
IRO 3321 black slate N10E 10SE
outcrop in small drainage
MCM 191 Sutky in Farm
boulders in alluvial
terrace at house
OCs of gray sh in
bank to SE N12E 24SE
MCM 192 el 1640 ft on Sutpin
coarse SS bldrs up to
2' on roadside and
in stream bed
IRO 1B21 N10E 24SE on
pencil cleaved argillite
exposed in embankment
cut through boulder slope
deposit. el 1700 ft
IRO 1B22 el 1800 ft prom
bench on green shale
and siltsn (Ob) white
qtz arenite bldrs w/ qtz
xls
IRO 1B23 el 1970 ft on nose
dusky red mudstone
chips in overturned
tree roots (Ob) 200' gorge
w/ falls below

Day Runner®

NOTES

IRO 1324 large block slide el 2020-50 on gentle slope

IRO 1325 el 2160 b SE dippin bench at top of C20' below bays Ome green shale chips in roots of trees

IRO 1326 el 2040 b bays top red + grn slsn oc above stream N80W dONE big qtzite cgl blks in stream at 2020

IRO 1327 el 1920 N80W 30 S massive green SS ledges oc on steep slope

IRO 1328 2 2' SS ledges brn to reddish N70E 22SE el 1830

MCM 93 N50E 30° SE 6' qtz SS ledge crossing stream and holding up ridge to NW

MCM 94 N80 20 NE massive to thin bedded arg ls. blk

IRO 1181 thin bedded gray wackestone ocs in eroded spot where fence bends

Dec 9 EW 80N NEL 650

IRO 194 Slate Lick Fm slate + thin ls

IRO 195 N80E 80NW gray calc slate + arg in road bed el 1560

Item # 033-3

NOTES Dec 8' 11

IR0196	N80E 80SE slaty clean in OC bed N44W 18 NE in stream bank across from House el 1700 b
IR0197	sandstone ledge holds up steep ridge (el 1750 b in creek) ledge Form on surface N30W 20 NE
IR0198	green calc siltn, slate and ss, abdt linguloid brach shells N30W 10 Ort
IR0199	on old power line row at el 2000' large (5') < blocks of white cross bedded ss fan like surface
IR0190	el 2030 b - steep slope w/ gren-orange sh + slt chips - end block Field
IR0191	N85E 18 NW black ls w/ sulfate on surface boudins or cobbles in slaty mtx Ort el 1860
IR0192	el 1920 75' by 15' trench in hillside w. road leading up to ridge Shale pit?
IR0193 IR	N72W 34 NE greenish gry ls and argillite w/ slaty cleavage OCs on road at el 2000 b at hedge of Clearing
IR0194	N50W 18 NE bench on qtz ss ~ 2' thick

Day Runner

NOTES

cap 20 rock for ridge line at el

IRO 1915 el 18906 cut road OC in curve N 38 W 18 NE slaty cleavage in dusky red and green mudsn

IRO 1916 Walker Mtn qtz SS about 6' thick on road bank n 52 W 19 NE el 18606

IRO 1917 el 1750 ocher shale or slate pavement on road above studio

IRO 1918 el 17006 - qtz cgl OF Silu - Dev in slope deposits

Dec 11 " Taylor Hollow

IRO 277 Bays N 40 E 55 SE grn grg sh overlain by SS ledge el 17406

IRO 278 Bays grn sh + SS 17806 red mdsn N 40 E 20 SE at east to house

IRO 279 Bays SS in Crk ~2' ledge N 70 E 20 NW el 17206

IRO 2710 grn red mudsn Ocs in road at el 17006 E-W 65 N

IRO 4211 on creek bank el 1520 just below Fork, grn slaty ls + Silt, arg N 70 E 10 NW bedding N 70 E 70 SE cleavage

Item # 033-3

NOTES Inferred Fault

short dashed 1.5 mm
thick .375 mm .75 mm

In Ferred Contacts

.15 mm thk

C. 425 pt

4.25 2.13 pt
pt

Short dashed contact
0.425
miter limit 4
1.42 2.13
dash gap

12/19/11
Ellen Gilliland 405 4706826
VIRGIA CENTER COAL & ENERGY
460 Turner St
Suite 304

Dennis Estes Estes Motors
Dec 20, 2011 Cell Tower Property
IRO 4212 on NS tracks 16'
15 ledges, gray-brn weath
slaty argillite N40E 40SE

N 37° 12.047 W 80 21.477'
strong jointing N30E 50NW IRO4213
N 37° 11.980 W 80 21.363
IRO 4214 N 02E BRL to High Top
N37° 11.783 W 80 21.436'
orange weath slate chips

Day Runner

NOTES Dec 22 '11

IRO 42 15 Just below summit in road bank yellow orange-gray weathered slaty argillite N 40 E 50 SE slaty cleavage. N37 11.892' W 80 21.555'

IRO 42 16 N 40 E 45 SE thinly bedded calc-argillite w/ slaty cleavage el 1706 N 37° 11.700 W 80° 21.598'

IRO 45 12 slaty argillite lite gr on fresh roadcut at el 1650 N 37 11.597 W 80 21.470 N 20 E 20 SE

IRO 45 13 white qtz ss blks on knob above grn sh turn in road el 1620 ft N 37° 11.537 W 80 21.428

I Walker Mtn SS / 06 may be offset across road to S

IRO 45 14 el 1700 ss gravel in tree roots N 37° 11.500 W 80 21.423

IRO 45 15 listvenite ledge form crosses nose at el 1640 ft N 37 11 492 W 80 21 352 red mudsn + qtz sand

IRO 45 16 red mudstone soil and float on slope el 1570 N 37 11.445 W 80 21 332

IRO 45 17 joint N 76 E 56 SE or N 20 W 12 NE Rcd mdsn ledge on point, N 37° 11.48 W 80° 21.300

Item # 033-3

NOTES Dec 20 '11

IRO 45 18 N 40 E 36 SE
rd mdm+ tan thk bedded
ss 06 at turn 40' borrow
pit N 37 11 390 W 80 21 208

IRO 45 19 N 4E 20 SE
gently undulose
argillite / calc arg
beds 0 MR6 N 37° 11.470
el 1500 W 80 21.185
Folds and pencil cleavage
plunging N 80 E 20 NE
Flts N 60 E 64 SE
down to SE



IRO 45 20 N 10 E 40 SE rd and
grn argillite N/ slaty
cleav
N 37° 11.600 W 80° 21.180'
spheroidal weathered
fine SS

Dec 21 2011
IRO N 30 W 30 NE Mass ledge
4 ledges tuff in stm
1716 100 m from yellow
frame house el 1650'
N 37 13 185 W 80 22.477

IRO
1717 NS 16 E thk blk
1600' Micrite ledges
N 37 13 097 W 80° 22 185'

Day Runner

NOTES

NOTES 1-12-12

IRO 17 17 black slaty argillite
OC N 50 W Dip 50 NE
N37° 12.680 min W80° 21.860'

IRO 17 19 N37° 12.742' W 80° 21.985'
Dark Gr mass bedded limestone
N30W 20NE

IRO 123 (redo) N 26 W 42 NE
Grooving lineation on folds
N60E 40NE
limestone pebble cgl
white cal veins 1set N 30W
dip 40 SW
interset view N 44 E
dip 70 NW
GPS N 37 12.820'
W 80° 21.995'

Photo IRO 174 Cherty ow at N 37° 12.950
N37° 12.950
W 80° 21.987'
IRO 175 cave opening active sinkhole
N 37° 12.988' W 80° 21.998'
picture

IRO 1720 Top of limestone
Bed N 26° W 20 NE
Long N 37° 12.997',
W 80° 21.915'

IRO 1721 GPS N 37 13.150' W 80° 21.857'
Landslide slump scarp on top
of LS contact
photo across Rd

IRO 1722 lime LS Ledge
N 36 W 20 NE
N37 13.139' W 80 21.877'

1723 IRO 1723 N 10 W 16 NE
Th bedded cobbly weather dr gr
LS N37 13.240 W 80 21.980

NOTES 1-12-12

1224 N 56 E Dip 8 SE

1-13-12 IRO 17 ZS
Cg gray wacke lsn, yellow bands
N 37 12 820 W 80 21 960
WP 101 N 20E 16 SE

IRO 1726 I 02
N 37 13 042 W 080 22 1[illegible]
Dark gray wack on w/ banded
Text large fossil
Exposde folding Co 276 637
N 30 W 16 NE 3361

IRO 1 I 32 Ellenbogen Farm Contact
01/0c 19 Ck N37 14.228
air N6E 22 SE W80 21.983

IRO 1 I 33 thk bedded LS
N5 16 E N37° 14.232 W80 22.05

IRO 1 I 34 Massive dove gray
micrite ledges at corner
On N 37°14.252 W 80 22.130'
N8E 14SE

IRO 1417 chips in rusty Grn
soil = 8E
N 37° 14.128 W 80 21.922

IRO 1418 photo of bk ss arg
ledge w/ clean-bed. el.
B N 20W 18 NE
C N80E 80SE
R F 20E 1cm

IRO 1419 dk gr wacke sh
massive bded N20E 20SE

Item # 033-3
N37 13 787 W 80 21 942

NOTES Jan 20 '2012 BBG

Buchanan, William T.

The Trigg Site, City of Radford
Richmond, Arch Soc VA 1984

E178.V7 B83 1984

BBG 325 - Advance stone lam thk bedded gray dol (eel)
N 37° 14.185 W 80 25.260
N56 E 50 SE

Jan 24 '12
IRO-7716 ledge of dk gry micrite ~100 from road
N37 10.270 W 80 22.677'
Photos of Joseph Bridge
IRO-7717 pebbly grainstone w/ cht dol pebbles Fossil debris ~Histon facies - Maysat
N37 10.310 W 80 22.620
Bedding N40E 24 SE (Photo)

IRO-7718 N 30 E 26 SE
dark gray arg wackestn lumpy bedded surface
spring source
N 37° 16 283 W 80 22 5 73

IRO 7719 Ol dk gry arg wackestn N40E 26SE
N37 10.177 W 80 22 620
Photo OC S/O Smart Rd

IRO 7720 On dk gry micrite ledges just above copse of cedar 3/4 up slope From CK
N37 10.175 W 80 22 765

NOTES rudely layered

OC3 N 22 E 24 SE ~100'
From Rad 65 paces

BBG 10 dk gry micrite mottled w/ tan dolomitic burrows, porous chert prob tgb
N 37 10.158 W 80 22 757
Chert layers (photos) of chrt and pure micrite
N 28 E 12 SE probably a grade 2 10-15° diff algs

IRO T5 21 bays SS (gt 2ft) Float on roadbank just past house
N 37 11.390 W 80 21 385
Green bays SS
N 5 40 E

IRO 17 30 chert gravel in soil

IRO 17 31 massive ls ledge
N 10 E 18 SE coarse gray wackestn w/ prominent
N 37 12 612 W 80 21 935
el 1580 6

IRO 17 32 N 10 E 18 SE el 1590 6
N 37 12 602 W 80 22 023
Massive Gray micrite w/ some dol mottling and silc brgazoa

Item # 033-3

NOTES N 37 12 . 588 W 80 22 . 100'

IRO 1733 N 4 W 12 NE bottom mottled dol ls spring @ 1600 ϕ

IRO 1734 butcher block dolomite crops out in stream bottom N 20 E 20 SE N 37° 12.605 W 80° 22.217 el 1620

IRO 1734A sp/ of dk gy blk xline ls (marble) w/ chert clasts at base of On 1st display of dolom led ~~form N hillside solution depression below ledge~~ poss cave below

Jan 25

IRO 4410 ls dk gr micrite N 37 11 120 W 80 22.210 lite gry weath / brown chert N 5 15° E

N 37

IRO 4411 ls dk gry micrite N 20 E 20 SE no chert

IRO-4412 white blocky chert masses across nose of hill (Upper dol) N 37° 11 · 213 W 80° 22.398

IRO-4413 el 1780 lite gry crystalline dol N 30 W 10 NE N 37 11 187 W 80° 22 · 460

Obs ls just below N 20 E 10 gray massive bedded micritic

Obs1

NOTES

IRO4414 N 20E 18SE ledges of light gra – blue gray micritic ls in upper Beekmantown el 1680ft
N37° 11.125 W80° 22.465

IRO4415 blue gray - lite gray ls blocks in woods just below ROW Fence el 1590ft, Sink, conical ~ 6-8' deep 50' dia
a N 37° 11.028
W 80° 22.380

IRO4416 N20E 22 10' thk Massive micrite bedd'd bluish gray ls in cut at el 1580 N37, 11.018 W80° 22.482

IRO-4

Item # 033-3

NOTES Honda Packas G 1909

19.69	Mirror R 1989695-001 19.69
6.29	C9p 33mm Black NH1 132355-001
19.69	Bulb 12V 35/35W 17413S7-001
	1-888-339-3888 Bike Bandit
	E.B. Knopf, 1927, Some results of recent work in the southern Taconic area: Am. Journ. Sci., 5th Series Vol 14 pp. 457-458, 1927.
P36	Kyanite in Va The old explanation of the change from east to west in Pennsylvania of the highly metamorphosed rocks to albite chlorite schists and other rocks of low-rank metamorphism is that the metamorphism died out to the NW In central Virginia where there is an alternation of zones of high rank and low rank metamorphism the explanation was not applicable and rocks
	Knopf, E. B., 1931, Retrogressive Metamorphism and Phyllitization Amer Journ. Sci 5th Ser Vol. 21 pp 1-27
	Jonas, A. I., Metamorphic belt of the Appalachians: Geol. Soc. of America Bull., Vol 40, pp. 507-10, 1929

Day Runner

NOTES IRONTO QUAD 10/19/09

IRD 981 N 37° 08.207 W 80 15 .979

IRD 982 WP 001 N37 08 335 W80 15 993
red brown shale arg
oc on road bank
coarse blders along field
bndry

IRD 951 N 37 08 635 W80 074
near Vertical ledge
along road bank
N14E 78°NW gray grn
thin bedded argillite WP

IRD 983 Red and gray grn slaty clay
argillite
WP 02 N37 08 199 W80 16.053
el 1373 Bedding N 34° E 60SE

IRD 984 Massive dol, gray fg-xline some iron
N42W 60NE

IRD 985 massive bedded gry dol, thin
thin bedded fg dol w chert
N10E 60SE

IRD 986 Small quarry in dk gry
WP004 rexine iron stained dol
N 37°08.064 N82W 60NE sicks
W 80°15.909 ON Fract Strike N70E 50NW
plunging 18° W

IRD 999 N 20° W 50SW bioturb red laminated
WP05 argillite W BPC, 75° burrow dol
el 1441 N 37 08 085 W 80 15 .715
above on road

IRD 910 N 20 E 65 SE Rd + grn slaty
WP 06 argillite above mass dol sect
Forms ridge line N 37 08 .715
W 80 15 .783

Item # 013-200
el 1666

IRONTO Project 10/19/09

NOTES Make New Layer

* Select all
x Copy to New layer
x Save old layer
x Pathfinder Reride new layer
x select a fill for all (No stroke)

IR0991 N26E 60SE grn-gry slaty argillite then dolomite, w/ Red clay
WP007 soil above at powerline dk gry bands
1856 N 37 08.200 W 80° 15.305'
dol with m n white veins

IR0992 Grn-Gry slaty argillite on ridge
WP008 trail N18E 80SE
el 1896 N 37° 08.304 W 80° 15.717 min

IR0993 Grn-Gry y/w grn slaty argillite
WP ledge in road N08W 45NE
el 1935 N 37 08.314 W 80 15.617

IR0961 N24E 67NW lt gry slaty-argillite
WP009 N 37° 08.395 W 080° 15.548'
el 2143 Red argillite below in woods

IR0962 N6E 50NW N 37° 08.556 W 80° 15.364
WP010 el 2231

IR0963 N 20E 72NW Red+Grn slaty argillite
WP11 in saddle along ridge
el 2095 N 37 08.714' W 80° 15.34'

IR0964 N10E 82 SE thin cleaved paper
WP 13 slate, lt gry-grn
el 2248 N 37° 08.808' W 80 15.298'

Day Runner

NOTES

IRO965 N10E 66 SE N 37 08, [illegible] W 80 15.274
WP14 ledge of paper thin slaty
el 2114 argillite. lt gray-grn

IRO966 N 10E 80 NW silty argillite
WP 15 grn gray + maroon, burrows
2146 fine sericite sheen on BPC
ledge beneath tower N 37 08.998
W 80° 15.277

IRO967 N 85 W 50 S W thn dol bed
WP016 with gentle Z folds ~ plunge
S 85 W at 5° or less
2129 N 37° 08.791 W 80 15.741

IRO969 Red and green argillite w/BPC
WP17 holds up ridge close spaced
joints N 85 W 70 SW
1745 N 37° 08.520 W 80° 15.177
BPC N10E 77 NW close spaced
joints break up OC into
blocks possible cross struct-
10/20/09
IRO987
WP018 N 37° 08.213' W 80° 15.346'
el 1712 Greenish gray thin bedded
argillite w/ slaty cleav // to
bedding 044 30° SE w/
coarse qtz rite boulder fd
above along old rd

WP019 N5W 60NE cleav in rd cut
IRO988 Slaty arg. N 30E 36SE bdg
el 1783 N 37 08 111' N 80 16.345
el 1974 N.

NOTES Coles Hill 5/19/07

WP20	IRO 100m up from trailer
el 1560	9 much chert fg dol blocks
IRO980	in valley N 37 07.826 W 080 16.582
IRO981	N62E 42 NW coarse sach dol ats
WP21	deeply weathered to orange gray
el 1659	mass N 37 07.764 W 80 16.641
IRO981	N 60 E 50 SE on log road 60'
WP22	above valley Red laminated
el 1804	argillite - bedding
	N 37° 07.688 W 80 16.690
IRO971	Red argillite ledge N 35 E 40 NW
WP23	on nose of Hill
el 2001	N 37 07.568 W 80° 16.683'
IRO972	in saddle w/ low relief
WP024	angular blocks and bldrs of med gr
el 1994	impure ss or meta graywacke
	Er ? N 37° 07.544 W80° 16.920
	tan mica/clay mtx Fine - med
	rounded qtz
IRO973	Tan sltsn/argillite beds
WP	w/BPC N 60W 20 NE
2079	N 37 07 646 W 80 16.938
	(on ridge to N ~ 100m)
IRO 974	N45 E 70 NW Red + grn Slaty
WP26	org, thin bedded ledges
	on nose of hill
	N 37° 07.682 W 80° 16.884 el 2042
IRO975	N 20 W 20 SW 1'-2' thick
1783	argillite bed slaty
	cleavage N 30 E vert. cal. drop
	road to valley
	N 37° 07.725' 80° 16.818'

Day Runner

NOTES

IRO976 Massive cry dol, dk gry
WP 28 float in saddle
1828 N 37 07 760 W 80 16.723

IRO977 Gray x'ln dol w/cht
above saddle N 40 E 30 SE
WP 29 thin bedded gray argillite
1713 below N 37 07 684 W 80 16.685

IRO978 Thin bedded tan siliceous arg
WP 030 N 10 E 56 SE N 37 08.091'
el 1763 W 80 16.557'

IRO9814 Massive gry carbonate w
WP 31 complex stylolitic beds
1760 N 37 08 180 W 80 16.619
Bed N 15 E 66 SE
Joint N 84 W 70 NE
Joint N 50 W 60 SW

IRO978 Lam to med bedded dk gry arg
WP 032 tan weath dol and argillite
el 1756 N 39 E 40 SE w interfolial folds
dol bounds
2 folds plunge S 20 W 18 SW
N 37° 08' 109" W 80° 16.717

IRO979 Massive mottled dk gy dol w
1556 disc. vuggy zones beds N 39 E 41 SE
Fract. w/ gash veins N 50 E 45 NW
N 28 E N 37 08 071 W 80 16 750 down to NW
40 SE
bed at overlain by mylonitic grn and
top of rd phyllonite with intricate
80 p folds plunge S 36 E at 40
N 16 W foliation N 84 E 50 SE
1 ine Oc then thk beds of rd and grn

Item # 013-200

NOTES

IR09710 New housesite exposes massive
WP034 burrowed dol ls photo N38E 20 NW
el 1551 N37° 07.868 W 60° 16.745'

IR09711 N52E 57SE gray dol, grn arg
WP035 w tan argillite beds offset
1553 by cleavage N 37° 07.783 W 80° 16.054

IR09712 Slide or Rock Fall area where
WP036 slaty argillite cleav dips NW mas
el 1607 dol beneath beds dip
N 37° 07.658 W 80° 17.236

IR09713
T N50E 66 NW at W end of cut
thk layers of grn and red
slaty argillite, ylw weathed
arg dol. w/mudcracks
33 paces from west end of cut
is karstic dol - road shows
WP037 Subsidence Photos c N 37° 07.696
1763 W 80 17.352
IR09714 Rome fm slaty gry grn arg
WP038 syncline N606 3° photo
N 37° 07.763 W 80° 17.489
IR0 891 N46E 80 SE massive 20' dol offset
WP039 by fault (photo) N5 30° W
orn metcd with sulfate or gyp
sublimnate N37° 07.764 W 80° 17.536'
IR0892 dk gry-blk burrow mottled dol.
WP040 N26E 60 NW N37° 07.751' W 80° 17.547
el 1694 crest of antiform in dol ledges
WP041 at N 37° 07.790 W 80° 17.539 1677
bed N42W 6°SW
IR0893 N20W 30 SW red bedded dol ledges
WP042 on rt/ side at N37° 07.839 W80 17651
2013 el red slaty arg. road cut N50W 30°SW

Ray Ryngar

NOTES

OCT 21 '09

IRO894 N 50E 30 NW dk gry and grn
WP43 thin bedded to laminated argillite in roadbank 15' high N 37 07 866 W 80 17.709

IRO895
WP44 INTENSELY BUCKLED F1
2003 HINGE IN F2
Hanging Valley below MAIN AXIS N60E 6 ANTIFORM
F1 axis (hinge) S60W 10°
SE LIMB N45E 40 SE N45E 70SE
N 37° 07.887 W 80° 17.780

IRO896 blue gray thin bedded arg.
N56E72SE kink axes N26W 12NE S56W 7SW

IRO897 S60W 5SE
open antiform

IRO898 in gray argillaceous ls or dol
ledge of lt tan wea mass dol

WP047 N80E 15 SE N 37 08.031 W 80° 17.932°

IRO899 lt gry xline dol w/ calcite
WP46 veins N 76 E 40 SE thk bed
1963 in road bank at
N 37 08 169 W 80 17.006

IRO900 thin platy tan wea dol w/ thk
WP 46 N 37 08 208 W 80 18 020
N 80 W 40 SW (Eel?
karst in massive bed 60'W

IRO901 Massive gry and pnk
WP 49 breccia (Eel) in road bank

S 18 E 14 SE
of 1804 boudin or hinge line
in brecciated dol
N 37 08 249 W 80 18.067

Item # 013-200

NOTES

OCT 21 09

IR0 8912 Thin bedded gray dolomite
WP50 outcrops along roadside
el 1868 for 300 m N 37° 08.262 W 80 18.278
N 60 E 24 SE Photo
IR0 8913 Thk bedded to ribbon layered
WP51 peritidal carbonate (dol)
beds N 5 E 24 SE
N 37 08 280 W 080 18.474
OCT 22 '09 Photo

PLT 231 Brn weat maroon argillite w/grn
WP52 N 37 06 .812 W 80 17. 897
el 1584 arsillite layers along Elliot Cr.
1487 N 34 E 60 NW

PLT 232 dk gry tBrn weath arg +
arsillite c dolomite N 60 E 80 NW
1682 el N 37 07 275 W 80 18.036

IR0 8914 N 50 E 60 NW
WP53 N 37 07 525 W 80 17.973
el 1663 old house foundation
black - dk gry thk bedded
Rome dolomite beds
IR0 8916 N 10 W 20 SW Tan weath gry
WP055 - grn thn - thk bedded arg
N 37 07.550 W 80 18. 232
1791 N 30 W 30 SW slaty arg dc
above new bridge and gate to
"enchanted crack" contortd
Folds plunging S 50 W at 20 ≤
IR0 8915 N 50 E 70 NW thk - med
el 1813 bed dk gry arg dol in Stn
N 37 07 585 W 80 .094

Day Runner

NOTES Oct 22 '09

IR0 89 17 Plate dol
WP 056 37 07 776 W 80 18 110

IR0881 dk gry slaty argillite
WP 057 in bank N 60 E 80 SE
1823 N 37 07 642 W 80 18 380

IR0 882 Lt gry slaty dol argillite
in new at SR 742/734 INT
WP 058 N 80 E 80 NW
N 37° 07.687' W 80° 18.409

IR0883 N 80 E 60 SE 4' gray dol
WP059 ledge stands out in cut
1845 N 37 07 713 W 80 18 416

IR0 884 18 Slaty argillite in log landing
WP060 cut N 80 E 20 SE good exposure
1841 of valley Fill in cut
N 37° 07.629 W 80° 18.323

IR0884 el 1206 Elbrook dol lt gry
WP 61 N 37° 08.875 W 80° 18.936
thin bedded to thick bedded
chert - thin clay partings -
brecciated w/white carb veins
several ledges in 100' cut

IR0 885 Orange ocher sh Chips
WP 062 N 37° 07.764 W 80 18.393
el 1451 in residual soil above
new drive way

IR0886 N 70 E 425 E lite gray
WP 63 platy dol in old
1871 drive way N 37 07 694 W 80 18 582

clear, cool, breezy 1 27 11

IRO52 14 18" thick lt gry white-pink conglomeratic qtzite ledge at Lyons qte N55E 20SE

IRO 517 N80E 28SE 6'

pebbly qtzite ledge crosses drain at el 1600 6 blders

10 v slope & drain below

N70E 30SE sight - dip slope above

4 IRO 518 el 1800 6 hematite red brn qtz ss ledge on road bed N55E 28SE

red clay soil deep brn rod ss float in road above point capping w/ 2' qtzite beds

IRO 519 el 1925 6

passed though leached soil w/ qtzite then black shale chips on road — erratic

IRO 5110 el 1960 6 big block strikes N60E 40SE

3-4' qtz pebble cgl ledge

Switch back at 1980 6

IRO 5111 el 2040 b
1' thick ferruginous cgl
float on dip slope N60E 35SE
could be Fagg cgl photo
IRO 5112 el 2130 b at ridge
and road curve N30E 30SE
on brown rippled pebbly (ang qtz)
ss ledge
IRO 5116 redux 2190 b N10W
80SW

Ot? xbedded qtz ss
ledge on ridge el 2300 ocherous Gly silt (corb sap)
IRO 5113 el 2340 b road Poplar covers
turns up hill in
large blocks of qtz ss +
qtzite ~ 3-4' thk
IRO 5114 el 2480 b thk tan
pink weathered qtzite ledge
many blocks on nose
N30W 20 NE
IRO 5115 el 2540 qtzite
blks on nose in saw
IRO 5116 bed on road brnk 2200
weath ss micaceous N55E 26SE

May 10 2010

IRO 8130 Orange arg dol/ and grn phy dol N80W, 80 SW
N37 09 414
at WP 586 W80 14 487 2042

IRO 8130 N 50 W 80 NE thk to thn bedded fractured dol

IRO 8418 N50E 46 SE Massive bedded, closely cleaved Fine gray dolomite Clean EW 60N

IRO 8419 Wedge block collapse from Karst tunnel exposed 30' above grade (Photos) Fracture N10W 80 NE Bedding in massive gry argillaceous dol N 80 E 20 SE Begin cream colored silceous dol W/ cross bedded qtz silt layers, straticulate layering (Big Springs Sta) RSU

IRO 8420 EW 35 S photo of upside down cycles W/ strom and thom. text elevation 2114

WP 587 N 37° 09 W 080° 14.8'

photos of 2 meter to 3 meter Eco cyc.



IRO 8421 WP588 el 2110
WP N 37 09 038 W 80 19.901
Photos of 1 m cave ent.
in blue gray ribbon
banded ls. Eco Op.
blue HTI sign N 20E 24SE
IRO8422 upside down algal
strom photo in 1994
guide at WP Mile post
120
IRO7616 EW 40S air strike
at MP 119.7 N 37 06 884 1907
WP 589 W 80 20 195

IRO 7417 EW 60 S gray
dolomite
IRO 7418 N74E 80SE
beek dol cross Frac
gry
IRO7419 EW - N80E 40S
algal ls - Stone hinge

NOTES

IRO887 Platy dol, lt gray fg. W thick x line
WP887 dol beds N 60E 70SE Ocs
064 on embankment
1888 N37°07.719' W80°18.576'
pod of breccia above (10')

IRO 888 Platy weath argill. fe dk grnish
gray w/ slaty cleavage N60E 70S
bedding N 70E 30SE

IRO889 Fg dk gry thk-thn bedded
WP65 X line dol N 60E 60SE
1906 N 37 07 726 W 80 18 705

IRO8810 Tightly folded blu gray clay shale
WP ✓ and light gray-tan platy dol.
S50W 8°SW 5 Fold hinge ✓

IRO791 Quarry in thick bedded
WP66 gray re x line dolomite
e/1868 N20W 40NE joint N70E 70NW
N20W 80NW
N37° 07.505 W80°20.481

PLT132 Breccia along falling branch
at base of Hamiltons Ridge S of the
WP067 ~100 yds long to spring
PLT133 N37 07 458 W80 20 626 pnt to
WP068 N37 07.429 W80 20.733'
1889 large spring along fault
at Ginger Hill

PLT 134 N60E 60SE Massive brec.
069 dolomite along creek just
WP stream From Bridge
1900 N37 07 404 W80 20 850

Day Runner

NOTES Oct 26 '2009

IRO 88 N 70 E 44 SE lt gry
WP 070 tan weath. med grd
fine grained dolomite, thin to
thick beds N 37 07.903 W 80 19.84
IRO 88 12 Light gray - tan weath.
WP 071 shale or shly dol in
Eel brk slaty cleav dips
N 74E 40 SE N 37 08.162 W 80 20.170
IRO 88 13 N 84 E 36 SE thick bedded
WP 072 tan weath dolomite
1962 N 37 08.097' W 80 19.091'

IRO 88 14 N 34 E 60 SE cleav / transposed
WP 073 bedding N 20 E 4° NE N folds
2068 gray dol, slaty cleav
Eel N 37 07 952 W 80 18 412

PLJ 251 N 40 E 80 SE rd
Rome slaty argillite ledges
on hill nose CWP
N 37 06.636 W 80 18.453

IRO 87 11 At pump station on John Lemeley Lane
WP 75 N 80 E 42 SE thick bedded
Ecr? gray dolomite, creme to
very light gray weathered
sandy zones large stromatolites
N 37 08 141 W 80 19 958
IRO 87 12 alternating lt and dark gry
Eel thin to thick bedded dol
WP 76 W rounded blk chert nodules
1916 up to pumpkin sized laminated
dol w/ yellow weathering
zones N 62 E 42 SE
N 37 08.075 W 80 19.989
Ca. at 14 Stn.

May 13' 2006

IRO 691 Site of Ft Jause Excavation

Gave copy of Shawsville 100K map to Gregory Adams - contract archy w/ University of Kentucky Group

no more funds today

3/29/09 Ironto, cool cloudy

IRO 6215 N20E 40 SE breccia below on I81 NBL coarse thick bedded gray dolomite beds above at WP NP 324 N37 11 747 W80 K. 109 1942 ~ 1800 Topo

IRO 6216 N22E 60SE, dol gray massive thick bedded, some burrowed beds some ribbon banded gray limestone beds WP 325 N37°11.70 photo 1806b el 1834 ft W80° 15.788

IRO 6217 yellow-orange stained thin bedded gray dol EW 70N WP 326 N37 11.820 W80 15.895 el 1861

IRO 6219 N50W 30 NE thk bedded gry dol in old quarry face? W327 N37 11 884 W80 15' 784" el 1575

IRO 6218 wp 328 N37 11.710 W80 15.769 el 1860 1806 120' dia sinkhole on ridge. Obvious drain in ctr.

IRO 667 very shallow doline form on ridge at WP 329
N37 11.664 W 80 15.922
el 1857 2000'

IRO 651 Thick bedded gray dol ledge on ridge N50W4
WP 330 N37° 11.655 W80° 15.91.
el 1991 (930 r (6)

IRO 652 WP 331 N37°11.658
el 1943 W 80°15.968
very shallow karst depression in saddle ~ 1' closed area
w/ drain to NE

IRO 653 ridge top w scattered blocks of coarse pink "marble of siliceous/calcareous sinter (spring deposit?) WP 332 sp IRO 653
N37 11 649 W 80° 15 023 el 1976

IRO 654 200' by 40' deep sink
at WP 333 N37° 11.595' W 80 16.04
el 1935 N12E to SE thin bedded gray ls, massive bedded ls to West of sinkhole shows tan burrow mottles ~ 0bed

IRO 655 extraordinary ridge top pavement formed on massive

bedded burrow mottled dolomite
in trough of syncline V14E
S-10 SE at WP 333 E1 1871
N 37 11 563 W 80 16 067
Fire ring, Neat Fractures
trend N8E N 36 E N74W vert
IRO 656 near middle of big
pit blue gray ls w/ mottled shly
parting N 20 W 10 NE on gentle
slope above highwall of WP 334
N 37°11.435 W 80°16.069 el 1793
IRO 657 at S end of pit
N22W 29 NE lt grey-tan
thin bedded to platy dolosn
WP 335 N37 11.333 W80 16.091
el 1731
IRO 658 unsort cgl
cobbles on ridge
between quarry
an sm WP 336 N
N37 11 487 W80 16 121
1775 elev
IRO 659 N70W 38SW
shaly to ribbon banded
elbrook in NW end of pit
N37 11.570 W80 16 190 el 1653

3/30/10 N 37 11 565

IRO 693 wp 337 W 80 16.141

massive dol. breccia dk gry w/ light gry recive intr coarse dolomite rhombs terraced ledges N80W 60 NE rusty red soil w/ chips of. argillite breccia

IRO 695 redux wp 332 N 37 10 396 W 80 15.787 el 1573 yellow orange weathering dol breccia w/ crudely laminar N60W 10 NE

IRO 694 laminated - platy thin bedded gry dol breccia N 80 E 34 SE in cut wp 339 N 37° 10 316 W 80 15 643 el 1573

IRO 695 massive gry to lt gry thinbedded platy dol N8W 12 NE at WP 340 N 37° 10. 212 W 80 15.545 el 1514 photo of clay plug karst, bedding and joint N58E 85 SE N8E 85NW

IRO 696 N 60 E 50 NW Thk bedded gry dol / w ylw sdy beds at WP 341 N 37 10 153 W 80 15 46 el 1503

3/30/10

IRO 681 Folded gray thin bedded dol w/ thin calc seams N80W 80 NE fold N 37 10.422 E-W 20 W WP 342 W 15 9 92

IRO 682 ribbon banded blue gray ls w/ dol burrow mottles (photo) N 74 E 70 NW WP 343 N 37 10.549 W 80 16.09 el 1558 (upper elbrook ls) less than 20' is exposed here

IRO 683 burrow mottled ls bed is repeated across synclinal axis N 74 E 44 SE WP 344 N 37 10.647 W 80 16 145 el 1525

IRO 684 gray breccia dol N60W 60NE ledges along road at WP 345 N 37 10.665 W 80 16 145 el 1538 10 6510 W 76 W 20 NE thin bedded gry dol ledges below breccia OC (photo) WP 346 N 37 10 768 W 80 16 609

IRO 642 N40E 70NW thinbed blue gry algal ls N 37 11 15 W 80 16 764 WP 347 el 1497

IRO 642 upper el N40E 60 NW ribbony gry ls @ WP 348 N 37 11.114' W 80. 16. 861' el 1683

3/30/10

IRO 685 N20E 60SE 30' blue grey ribbon banded lime sandwiched between dolomites - breccia toF WP 351 N37 10 415 W80 16 200 el 1592

IRO 686 E-W 15N contact between lt grey dol and ylow-orange argillaceous dol. Faint truncated beds and breccia N50W 40SW at "Arthur" WP 353 N37 10 384 el 1573 W80 16.406

recumbant Fold

hinge plunging N74W at 5 nw

IRO 687 N80W 50 SW mass bed of dol in cut at WP 354 N37 10 361 W80 16.574 el 1553

IRO671 5 blue burrowed ls hinge N10E plunging 5 NE at WP 355 N37 10 296 W 80 16 855 el 1592 Folded breccia layer

IRO 672 Massive burrowed dol alt w/ ylw orange arg dol and argilite N20W 35SW

5/30/10

IRO 673 thin bedded gray lam argillaceous dol E W 60 N on road in Skillet Hollow at WP 356 N37 10.181 W80 17.146 el 1613

IRO 674 N 68 E 40 SE Blue gray LS

3131/10

IRO 944 3' dol ledge N 20 W 52 SW WP 357 N37 10 182 W80 17 150 el

IRO 945 3' dol ledg N 68 W 62 NE of WP 358 N37 08 352 W80 17 334 el 1605

IRO 9715 slabby tan-gry dol ledge N 10 E 60 SE WP 357 N37 08 324 W80 17 317 2063

IRO 946 thk gry dol bed w/ butcher block weathering on road N54E vert JY jointing? WP 360 N37 08.415 W80 17.457 el 2164

IRO 861 ylw gy weath slty dol interbedded w thk bdd gry dol

3/31/10 thk bded N 12 E 60 SE slaty cleavage N8W 79 NE

IRO 861 = rs u @ WP 361 N 37 08 459 W 80 17.501

IRO 862 Massive bedded gray to light tan Fractured dol ledges N 5W 70 NE @ WP 362 N 37 08 581 W 80 17 757 2057

IRO 863 burrowed gry dol ls N50E 20 SE undulose beds on ridge side near old basement cf barn to N

IRO 947 N5 46 E laminated tan slaty dol on trail above PL cl 2044 WP 363 N 37° 08.501' W 80 17.475 White qtz Float on nose

IRO 949 N 12 E 64 SE lam tan slaty dol chips on knob (948) oc on road embankment @ WP 364 N 37 08 572 W 80 17.394 El 2086 (949)

IRO 9410 N10W vert slaty cleav in y/w weath slaty dol (oc

10 ctdp 365 N 37 08 540 W80 17.204'
el 2109

IRO 9411 N10W 5° NE th 6 decl
gy dol @ WP 366 el 2073
Turkey below N37 08 523 W80 17.203

IRO 9412 red and yellow
ocher colored argillite
chips in soil at WP 367
N37° 08.557 W 80 17 132 el 2165
N76W 22 NE slaty arg in
road bank at saddle

IRO 9413 N 14 W 70 NE
grg grn ylw and some dusky
red slaty argillite in
Fence line cut at WP 368
N37 08 474 W 80 16 958 el 1950

IRO 9414 N 55 W 20 SW thk
bded gray dol on ridge ledge
at WP 369 N37 08.345 W80 16.955 2087
algal chert in saddle

IRO 9415 arg, ocs on road N55W 50SW
red-grag WP 370 N37° 08.375
hard arg. 2064 W80 17 038

IRO 9916 N 20E 70 SE
ledges of dk gray slaty
argillite w/ sheen on chips
OCS in stream at WP 371
~100' above road 371 N 37 08 300
el 1896 W 80 17 051

IRO 9917 Spring in argillite sap
at roadside WP 372 el 1883
N 37 08 .280 W 80 17.094
ledge on road N 20E 60SE
rd brn weathered argillite w/ slaty cleav

IRO 9918 N 20E 60SE sap of slaty
argillite at WP N 37 08 264
con W 80 17 207

IRO 9919 Concrete spring house
@ 374 N 37 08 291 W 80 17 235
Dol ledges above barn

IRO 9919 slaty dol ledge
N 34 E 60 SE ridge below stn con
WP 375 N 37 09 157 W 80 17 078
el 1624

IRO 9920 N 20 E 60 SE ledge
dk gry weath future block
dark WP 376 N 37 09 259 W 80 17 038
el 1604 Property Parcels

411/10 Ironto Quad Clear

IRO834 WP 377 N37°07.953 W80°17.639
N36E 44SE bedding Clear
in dark gry limestone bed
sandwiched between gray thin
dolomite layers, algal matting
deep brn resid.

IRO832 WP378 Springhouse between
thbded lam dol ledges WP 378
37°09.695 W80°17.791 el 1666
N62E 20NW

IRO 833 Broken dolomite ledge el 1790
massive bedded gry w/ X Fracs
N34E 30SE WP 379 N37°09.546 W80°17.747
clear N56E 60SE

IRO 834 laminated yellow-orange gry
dolomite beds N62E 30NW
WP 379 N37.09.436 W80 17.696

IRO 835 lt grey lam dol ledges in
team bank WP 380 N37.09.926 W80.17.641
el 1879 N80E 36SE

IRO 836 ledge exposed on canyon wall
at WP 381 N37°09.220 W80°17.633 el 1935
[illegible] on ledges [illegible]

IRO 864 thbbled dk gry/lite gry weath
dolosn N30E 20SE WP 382 N37°08.986
el 1875' W80°17.687

IRO 865 N10E 40SE gray thn bded
to laminated gray dol. WP 383
N 37 08 947 W 80 17 1731

IRO 866 N8°E 45NW thn bedded gy dolomite
N37 08 792 W80 17 603 el 2024 ledge

IRO 821 WP 385 N 37° 09.292 W 80° 18.361
N 80 E 20NW Massive bedded
Flaggy dolomite ledges

IRO866 Med-thk bded gray dol N37 09 195
N 20 E 20SE at WP 386 W80 18 296
el 1737

IRO 867 old abandoned dol quarry ✓
at WP 387 N37° 09.077 W80°.18.305
el 1753, S+D mass beds N80E 20SE
Clearage N65E 80 NW

IRO 851 gray massive bedded dol
ledges along roadside
and in quarry now used
as waste transfer site N37 08 74
N34E 30SE WP 388 W8018 521
el 1866 Photos

IRO 852 N 40 E 30SE Massive
bedded gry dol, Fracture
system breaks OC N 12 W 80 SW
WP 389 N37 08 556 W 80 18 620 1734

4/1/10

IRO 853 ledge above road dol thk bedded gray N72E 20SE at WP 390
N37° 08 478 W80 78

IRO 854 Massive tan-gray qtz sandstone bed outcrop in curve Bedding N78E 30SE cross beds top side down
Photo tco WP 391 N37 08.410 W80 78.083 W
el 2197



IRO 837 Leibrook w/ massive breccia beds Photos F side WP NOSE TOWN
N37 09 439 W80 17 534 El 1626.



N37 09 437 W80 17 352 Steep ductile fault zone cuts recumbent folds N30W 74 SW

N40W to NE steep faults
cutting recumbent structures
WP 393 N37 09 941 W 80 17 587 1624
Brittle faults at NE END OF Window?

IRO 638



anti-formal hinge surrounded
by breccia hinge plunging
S20W 30 SW hinge Massive blue
gray dol WP 394 N37 09 892 el 1672
W80 17 731



IRO 639 WP 395
N37 09 880 W80 17.768 el 1650
N50W 40 SW thrust

IRO 8310



Blue gray
algal ls
of Sett by Fault

45 N30E 60NW
Fault N70W 60SW

IRO 8311 blue gry ls N40E base underlain by gry dol grading downward into brecciated thn laminated dol (tidal lower)
WO 396 N37 09 915 W80 11 911

IRO 8312 N 43E 60NW algal ls/gry overlain by light gry platy brecciated dol WP 397 N 37 09 748 W80 11 662
Photo of quarry N 80° W, 126

IRO 8313 N40W 20SW massive blue gray algal ls above brecciated slaty dol sect WP 398 N37 01, 724 W80 19 250 1609

IRO 8314 N20W 30SW thk bedded dol section overlies brecciated platy zone (photo from RR)



IRO 8315 Photo of Fold hinge just W of (11) multiple vs bed parallel

plunges 55OW/10 SW N 30E

✓

IRO868 wp324
N 37 09 725 W 80 18 .25E
big spring from dol
along road

IRO 869 N18W 20 NE
Creme colored to light
gray massive, sandy
dolomite w/ fine qtz
sand grains weathered in
relief as rust colored
ribs on joint faces
WP 400 N 37 08 .982 el 1807
W 80 18 .25E

IRO 8610 N 20E 20 SE dk
gry fine grained dol (slaty
to thin bedded w/ arg
partings (upper Eco)2

wp 401 N 37 09 107 W80 18 [illegible]
el 1946

IRO 8315 N60E 40SE oolitic
chert, Fg Fe10 ss Float
and Oc ON W slope

IRO 8316 N10E 5St gray compact
crystalline dol w fine pnty

WP 402 N37 09 241 W80 18 20
el 1978

IRO 8317 N76E 20NE ribbon laminated lt gray dolomitized limestone typical Ccc bwt dol. WP 402 N37 09 279 W80 18 326 el 1780

IRO 8318 Massive, Fractured lt gry - creme dol N48E 47NW bedding? through going surface WP 484 Photo N42E 20E N37 09 276 W 80 18 369 el 1700

4/05/10 IRO 8319 air strike from NS rr N34W 8NE Mass bedded light gray dol w/ dark gray inter beds in quarry highwall

IRO 822 breccia layer exposed on 4wheele trail, thin bedded to ribbon laminated gray dol over lain by massive dol. Is above along old fence (E-W 50°NE) (E.l) WP 405 N37 09 719 W80 18 498 el 1894

IRO 823 N80W 30-35 NE.
thin bedded - lam dol
w/ thick breccia whale
back exposures along
4 Wheeler trail large
black snake, imitated
Actor by shaking his tail
in leaves - he was scared!
WP 406 N 37° 08.754 W 80° 18.635
el 1972

IRO 824 slaty argillite and
dolomite chips in thin.
silty soil on knob @ WP 407
N 37° 09.857 W80° 18.857 el 2043

IRO 581 air strike from NBL
N80E 20 NW thk brecciated
dol beds, small Fault or
fold hinge N66W 40 SW el 1867
N68W 20 SW at WP 408 on NBL
thin bedded ribbon lam dol N 37° 10.087 W80° 18.907

IRO 811 2 N46W 20NE thk bded gry dol sits above breccia section in cut WP 409 N37 09' 830 W 80 19 206 el 1687

IRO 8113 N50W 40 NE highly fracked gray thk to thn bedded dol at WP 410 el 1806 N37 09 613 W 80° 19.259

IRO 8114 N 30 E 50 SE at least 10' blue gry ls interlayed w/ dol just beyond sacboat WP 411 N3709548 W80 19 25

IRO 825 N 60 W 40 NE thk bedded gray dol at E tunnel portal

IRO 842 Thk bedded dol N60E 20 SE looks like CCo

160 E 40 SE ribbon burrowed blue gry ls facies

IRO 843 N60E 30 SE ledge of ribbon banded gray dol onto

IRO 844 N60E 40SE dk gray Fine grained laminated dolomite WP 412 N 37 W 80 19 506 el 1760

IRO 855 Laminated to thin bedded gray dolomite (Eco) photos of typ Conocoheague ribbon rock strat
N 50E 29 SE WP 413 N 37° 08.685'
el 213' W 80° 19.052

IRO 856 laminated to thin bedded gray dolomite with Conococheague like Fabric
WP 414 N37 08.816 W 80 18.847
el 2073

IRO 857 WP 415 N 37° 08.892
el 2102 N 40E 18SE W 80° 18.810
Creme colored thin layered dol (Eco)

IRO 858 photos of Eco fabrics of peritidal origin in gray dolomite
Facies N 30E 20 SE WP 416
N 37° 08.904' W 80° 18.876 el 2058

IRO 859 slickensides on joint indicate right lateral movement N 25E 88 SE
plunge 52 0W 3° SW N 30E° 75 SE
dk gy dol is w/ tan dol
WP 417 N 37 08 911 W 80° 18.815 el 1963

IRO 8510 · lt gray sandy dol · weathers friable brn SS at WP
WP 418 N 37 09 066 W 80 18.75°
cl 1918

IRO 8511 N30W 26NE Photos of tan sandy dol beds in very light gray weathered microxline dolomite, peritidal bedding features above including rip ups, channel scours sandy beds, upside down?

IRO 8319 N80W 16NE lam dol pavement in junk yard
N 37 ° a. 186' W 80 18 56 8" E 1794
IRO 8512 Soil Pipe on 11-460 SBL
at WP 420 N 37 08 968 cl 1994
at Farm access W 80 18 641
road ½ way up Cburg mtn

April 6 2010 WP 421 1870
IRO 761 N72E 28 SE N 37 09 169 W 80 20. 2
6' tan to white weathered sandy dol or "Sandstone" ledge in embankment and along RR tracks to NE where cross bedding may be inverted

IRO 781 Massive gray laminated butcher block dolomite overlying thin bedded (slaty) orange to tan-gray dolomite N76W 50NE at WP 422, N 37 09 229 W 80 20.063 el 1868 Eel?

IRO 8115 Thin bedded - slaty gray to yellow weathering argillite or argillaceous dolomite N80W 40 NE with punky tectonic breccia in top of cap rock breccia ft at WP 423 N 37 09 234 W 80 20.062 el 1872 Eel (?)

IRO 8116 ✓ assymetric syn Fold in thin bedded platy dol or argillite plunging S20E ✓ 9ft 20, much breccia at WP 424 N 37 09.243 W 80 19.915

IRO 8117 highly cleaved light gray to tan massive dolomite beds N 80W to SW at WP 425 N 37 09.786 W 80 19.763 cl 1818 Ecl?

IRO 8118 Very light gray crystalline dolomite ledges massive ~ 2m thk N20E 36 NW. Eco? big Spring Station member

IRO 8119 Section of lowelbrook



10' blue gray mgls bed is repeted as mega boudins or fold cores in tectonic melange Mapped SW contact as Fault as massive blue gray ls beds are truncated N 80E 80NW at UP 426 N37 09 365 cl 1851 W80 4.641

IRO 8120 N60W80SW 20' gray - blue gray ls in platy dol Sect

stromatolites in blue gray dol/ls are facing SW, coarse breccia (P) at N end of cut or base of section

IRO 81 21 N 80E 80 SE long section of lower Elbrook facies standing on end NW of I 81 Bridge includes ribbon banded blue gray ls to dol to platy dolomite, orange weathered slaty argillite (20' see) thick bedded massive dol and breccia layers beneath bridge where dip is down to 76°

at WP 427 N 37 09 462 W80 19.397

IRO 8122 WP 428 N 37° 09.479 W80° 19.577

Thick bedded blue gray laminated ls overlain by thick and thin bedded gray dol N 40W dipping 20 NE

IRO 8123 spring on IKE property WP 429

N 37 09 522 W 80 19 604 el 1677

IRO 8124 thin bedded slaty dolomite alternating w massive algal dol and blue gray limestone

WP 430 N 37 09 408
N10E 40 W 80 19 660 el 1837
IRO 8125 E-W 70 N thk good
dk gry ls interbedded w/
thin platy dolomite.
WP 431 N37 09 388
W 80 19 694
IRO 8126 N 37 09.283 el 1685
site of W 80° 19.784
big spring at IKE Park

IRO 751 mostly ∅ chert some
round cobbles on this old el 2045
strath WP 432 N 37 08 493
W 080 21 587
IRO 752 N 84E 64 NW dk tan
to gray butcherblock text.
dolomite ledges in woods
dk gray micrite float WP 434
N 37°08.741 W 80° 21 511 el 2161
IRO 753 N 60E 80 SE Vertical
cross beds in white to tan
weathered sandy dolomite w/ sandy
fringers Eco at WP 435
N 37 08 863 W 80 21.519

IRO 754 DK gray laminated on weathered light gray microcrystalline, thin siliceous partings (Cco?) Beds E-W 80N at Walknut Creek Pump Sta

IRO 755 Massive thick bedded med gray butcher block dolomite in creek at WP 436 (Photo N37 08 [illegible] W 80 21 612 el 2009 N 86E 80N

IRO 756 Massive gray butcher block dol ledges N60-80W 30N above dam dam at WP 437 N37 08 902 W80 21 593 el 2011 on dam 20' above stm

IRO 757 ledges in creek, below dam N74E 60SE at WP 438 N37 08 820 W80 21 579 el 1975

IRO 758 thin bedded ribbon laminated dolomite ledges in creek grade downward into thick bedded laminated ls + dol. Photo WP [illegible] N 37 09 029 W80 21 554 el 1941 E W 65 N photo of lam - Thin bedded is Ribbon Rock

IRO 759 WP 440 thick blue gry ribbon-banded limestone
photos in creek N37 09.063
CO el 915 E-W 805 W80 21.568

IRO 7510 WP 441 N37 09 095
el 1925 E-W 655 W80 21 592
Photos of field of alt ls
+ dol.

IRO 7511 Massive lt gry creme dol w/ oolitic cht over lies platy dol along RD
WP 442 N 37 09 132 W80 21 487
el 1906 N 80W 78 S

IRO 7512 E-W 78N white lt gy creme dol w thn silicic partings WP 443
N 37 09 066 W80 21 676 2047

IRO 7513 lt gry Sandy dol ledge CS pl WP 444
N 37 09 068 W80 21 621 el 1972
E-W 80S

IRO 7514 N 80W 30 SW
Mass dol ledge in front yard

IRO 844 N35E 30SE
lam irreg layered ribbon dol

IRO 826 N38E 30 SE
Massive crenulated laminatio
dol ; rusty brn, light
gray

IRO 827 thick bedded gry
wp dolomite ledge w/ white fracture
filling silicic ribbing laminae
N 70E 20 NW

IRO 828 crenulated
gray laminated dolomite
crenulations plunge N 30 W 18 nm

IRO 829 platy dolomite
(Cel. very deformed crenulated
ledges trend N60W 74°SW
cleav EW 90 N fold hinges
plunge S 30E 14 SE

IRO 851B N60E 20SE thk bedded
creme to gray dol, oolite Flt
above sink hole

IRO 85 14 several cobbles and bldrs on stone pile appear to be local. Some egg size rounded qtz, fe in soil (Photos)

IRO 761 mass is lodge burrow mottled dolomite

N70E 40SE just before "Blake Forest Sink

IRO 762 30' deep 100' wide sink at end of Wood ridge angular white chert float

IRO 763 Massive gray dol ledges w/ butcher block fabric, lamination weathered in relief (Eco E-W 36 S

IRO 764 N80W 30 SW thg bed of dol in front yard

RO 765 N80E 60 SE lam gray dol on sink wall

April 9/10

IRO 845 Massive bedded gray Fine grained dolomite w/ butcher block weathering creme color w brn mottles = thrombolite

N 37 08 740 W 80 19 737 N 52E 105E el 2050. Brown to lite gry burrow mottles

IRO 846 along ridge line gray dol ledges N 62 E 40SE w/ WP 446 N37 08 821 W80 19 700 el 2117 el 2

IRO 847 300' dia sink 20' closure active subsidence (photo) WP 446 el 2054 N37 08 901 W80 19 657 Course brecciated dolomite ledges dk-med gray cherty reg. ledge on Rim N72E 70SE

IRO 848 mass gray butcher block dol N60E 20SE el 2024 WP 448 N 37° 08.996 W80° 19.568 interbedded w dk gry ribbon layered micritic ls w purple reddish and white calcite partings at least one short (.5m cycle)

seems inverted ~.5m

IRO 849 Massive bedded gray dolomite ledges in creek

W80E 40 SE @ WP 448

Brown algal coating, butcher block texturis on weathered surface

look like Obeek N37 04 142 W80 19 537

IRO 8410 WP 449 large spring flow from talus covered e| 1985 cave entrance ~ 1000 gpm

Photo @ N37 09 160 W80 19 546

deep red terra rosa soils on slopes above ~ Obeek

IRO 8411 photo of 4' burrow el 1815 banded ls section in creek

at WP 450 N37°09,065' W80° 19,501'

N80 W 25 SE

IRO 8412 photo of inverted ripple banded silty ls beds

thin brn silt ribbons lite gry dolls

WP 451 el 1964 N37 09 015 W80 19 502

more burrowed US, N70E 20SE

IRO8413 perched alluvium above nick-point on the massive dol sect in lower Knox / beck N70E 25SE WP 452. el 2007 N37°08.961' W80° 19'490'

IRO8414 Massive dol cliffs where ledges cross drainage at WP stream is dry from IRO8412 upstream. WP 452 el 1936 N 37°08 851 W80 19 514

IRO8415 massive dol in stream bed end of cliffs above dol, very light gray to white weathered micro crystalline gray dolomicrite N50 W 22 SW WP 453 el 1976 N37 08 817 W 80 19.550 round chert chert float

IRO8416 N70E 20SE 4. thick beds of ribbon laminate dolomite. WP 454 N 37°08.723 W80 19 601 el 1970

IRO8417 20' waterfall in Conkin Section of thk bedded. WP 455 gray dol N 37 08 575 W80 19 629 el 1975 beds strike N60E 28SE con fracs = N20E 80SE N10W 70SW

IRO 8417 6' bed of cherty laminite blue ls ordol is wave lamination typical of Eco photo at WP 456 N 37 08 601 W 80 19 627 el 2040

IRO 8418 6' ledge of lam dol w/ silicoas parting covered w. th rounded chert "heads" From soil residua WP 457 N 37 08 641 W 80 19 667 el 2019

IRO 771 new house site in yellow gray residual clay

IRO 772 angular chert blocks along fence line

BBG 961 dk grey lam, thin bedded backestone to grainstone ledges on knob N 80E 80SE bedding WP 458 N3708485 W80 22 664 el 2173 Lincolnshire? or Conacacheague (stone henge)

BBG 962 Sinkhole in ls at
WP 459 N37 05 576 W 80 22 749
el 1493. ledge of typical
fco ribbon banded ls w/bx
N60E 80SE

IRO 661 WP 304 el 1431
N 37 11.416 W 80 15 104 1320 b

large ledg above 15' fall

IRO 662
N 70W 5 sw blk + wh dol breccia ledge 3'd

WP 305 N 37 11 325 W 80 15 326
el 1494

IRO 663 el 1427
N 37 11.350 W 80 15 341
6' travertine dam el 1360 b

IRO 664 N 20 W 05 NE 3' dol ledge on slope
N 37 11 305 W 80 15 444 el 1529
dark gry burrowed ls w/ old quarry site.

IRO 665 spring at WP 307
N 37 11 259 W 080 15 585
1520 old foundation

IRO 666 med bedded gray lm dol WP 308
N 37 11 404 W 80 15.645 el 1634
Spring heads up on other prop

IRO
WP 309 N 37 11 301 W 80 15 502 el 1493
Big dam

WP 310 N37 11.534 W80 14.813

NS 69 E 1356

spring

IRONTO Clear, cool

March 1 IRO 621

Ocs in cut at N end of bridge gray fractured dol. then coarse brecciated dol w thin bedded interval 30' above road EW 30N

IRO 622 thin bedded argillaceous dol w/ribbon ls banding disrupted by slaty cleavage in argillaceous beds N 30 E 60 SE WP 163 N 37° 11.816' much tan to el 1858 W 80° 16.209' pink argillaceous chippy float on slope below strong NW joint set N 68 W 80 SW

IRO 623 N 50 E 70 SE thin bedded argillaceous dolomite ledge WP 164 in old field Fold plunges S N 37° 11.863' 70 Fold at 70° W 80 16.220 el 1916

IRO 624 just S E of gas line ledge of thn bedded dol N 30 E 70 SE WP 165 on gasline N 37° 11.969' W 80° 16.254' el 1969 cell tower on top 100' NW

IRO 625 thk bedded gry dol w/ lamination N 30 E 50 SE OC in road

IRD626 March 1 2010

WP166 N37 12 044 W80 16 261

IRD 627 gently undulose gray dolomite ledge w/ 6" thin block N80E 10dE

WP 16 N37 12.315 W80 16 230

IRD 628 N36E 70NW 6-14 cm gry ribbon banded arg dol

WP 16 N37 11 800 W80 16 254

1753

IRD 621 ctd at road level tension veins E W 80N phot other veins N20W 80 SW gray thinlayered dol cleavage N80E 40 NW

IRD 6210 N 27E 62 SE med thin bedded gray dol white lets veins N45W 70 SW EW 80NE WP173 N 37 11 916 1775 W80 16 103

IRD 6211 N5E 88NW thk sed dol gry dol coarse granular weath strongly jointed N80W 20NE N54W 3/2W WP 175 N 37 12.075 W 80 16 051 1774el

2 march / 10

IRO 6212

photo of green breccia intrusion N 42W 60 SW

lg, Thk bedded dol N 36 W 60 NE

N 57° 12. 207'

W 80 16. 013'

1775



IRO 6213 N 28 W 10 NE

beds near flat after GBC intrusion

IRO 6214 Photo of Fault NBL W roll over to gn breccia intrusion opposite sink



green breccia = carbonatite ??

N 37 12 293 W 80 15 371 el 1762

Fault trends through sink

N 30 E 52 NW

IRO 3911 dk gry thin bedded crinkly N22E 15NW laminated dol overlies massive gy dol w white veins

N26E 76SE

N 37° 12.622' W 80 15 645' el 1683

big plug of breccia below intersect

IRD 626 thin argillaceous dol
ledges w/ thk N 30E 28 SE
much chert Float on hill
WP167 N 37 12 233 W 80°10.224
el 1934. ~~7~~ 6 large cht blocks in float
IRD 627 dk orange ylw clay soils
precipitated gry dol w/
White veins, 1' thk ledge
N 68 W 30 NE on road
at WP 169 N37° 12 371
el 1969. W 80° 16.185
IRD 628 200' dia 30' deep doline
at WP 170 N37 12.461
W 80 16.187
IRD 629 ribony layered argillaceous
dol, Fractured N 40E 60SE
N 37 11.895 W 80° 6.300
IRD 3912 3/2/10 VDOT Pump
area at WP 179 N 37 12 781
W 080° 15 654
IRD 3913 N60W BONE 2' ledge
dk gy cherty dol w sily (ylw)
Float on nose aboe
at WP 180 N 37° 12.842
W 80° 15.673

March 2 '10

IRO 3914 dk gy meath dol ledge ~2' thk N20E 40 NW gentle slope below mantled with cellular chert and platy dol chips
WP 181 N37°12.926 W80°15.743 21496
IRO 3915 top of knob covered w/ blks of dk gry argillite, slaty dol and greenish gry meta silt w fine sandy laminations up to 1cm 1sm N20W //// 80SW may not be in place chanal scours may be. ripple x lam

IRO 381 gry, massive bdd, arg stic dolomite N30E 40SE ledge (bedding) front at head of steep hollow Great view of Iron Valley
IRO 382 N28E 24 NW dk gy-blk podded flaggy dol 50 above N
N30E 40 SE Flaggy arg. SS cobbles in soil above
WP N37 12 871 W80 16 02
Shoulder! IRO 383 clinch ledge face top N40W 40 E photo WP 132
N37° 12.834 W80 16.00 el 2106

thin bedded ls and dol
N24W 30 NE on SW face
= OMo?

IRO 384 very bedded gray thin beds
ls or dol N30W 40NE
in saddle are blocks
of dark ls + dol in deep
brn resid. Just SW of
Boundary at WP 183
N 37° 12 635 W 80 16 057
el 2006
IRO 384 N30W 40NE Thin
bedded gry ls/dol in saddle

3/3/10 IRO 3613 photo, airstrike on
massive dolomite beds along Salem
thrust N80E 20 SE Joints N60W 70 NE
N10E 80NW Fault in photo N45W 72SW

3/3/10/ IRO 3614 photo of ledges above Roanoke River apparent strike E 2-5°S

IRO 352 dk gry tan weath shale w/ 2" sltsn bed EW 80S sinstral fold hinges plung North East N 65E 25 NE cleavage N76E 30SE joints N50E 70 NW covered w/red Fe$_2$O$_3$ N60W 50SW - closely spaced could be millboro on SE side of tracks

IRO 353 dk gry sh w fine ss or sltsn layers N70E 50NW WP 184 N 37°12.635' W80°16.058' e11 SS greenish gry qtz epi ch/mica graywacke w/ grains up to 1.5mm

IRO 354 WP185 N37°B.501' W80°16.284' e11315 2' unicon cgl bldrs in the air strike of blk shale along river bank (0m) N70E 15SE strong joint or faults N50W 80 SW hummocky deposit above erosive strath ~15' above floodplain photo.

IRO 378 black nodular weathering chert bed outcrops in farm road bed just N of Ford N 45E 25SE

tan weath qtzite ledge outcrops in RR cut to NW ~ 50'

WP187 N 37° 12.614' W 80° 17.083

el 1298

IRO 399 - photo of qtzite ledge below Italian Kitchen

3/3/10 spl IRO 379

pblg white qtzite overlying
black chert (below on river)
WP 190 N 37° 12.616 W80° 17.109
1308 ledge ~ 3' thk ogl dtg

3/31/80 Ironto

IRO 386 exposure of thin qtzite Pd over sh/ chips view across fault N 30W 30° NE air strike on ledge above river

IRO 371 N 30W 50 NE paper fiss cleavage 11 beds in dk gy blk sh bank

IRO 372 N 8 0W 34 NE photos of dk gry sh w/ ls concretions or boudined beds and new lazer facility @ Ironto

IRO 393 N 70E 20SE air strike on cleavage in stream bank From RR -

IRO 394 N38E 20SE 3' thk black chert and red limonitic SS ocher beds in rail cut blocks of qtzite in colluvium above - 186 WP N 37°12 650 WP017048

IRO 531 Cut w/ ls concretions / boudins N 45 E 20 SE bedding in Dm 1381 WP 88 N 37 12.351 W 80° 17.46'

IRO 611 Millboro beds in cut N40E 30SE // cleavage WP 189 N 37 12 442 W 80 17.318 1381

IRO 793 Photo of Med - thin bedded
WP 77 gray dolomite covered
.12081 with 2' tufa deposit
N 37°08.019' in stream below Fault
80°20.006' N78E 50SE

IRO 872 platy tan dolomite (thin bedded
WP 78 to laminated supra tidal facies
old concrete structure across creek
N 37°07.941 W 80°19.898' el 1997

IRO 873 platy tan dol (thin bedded
WP 79 to laminated w/ thk bedded
N37°07.879 Dol. 50 - 75' alluvial pocket on
W80°19.813 weathed shaley bedrock N80 20SE

IRO 874 thin bedded gray dolomite
w/ white calcite in x fractures
synclinal fold below (Photo
WP 80 N 3708834 W 80°19.771' 2046d
N78E 30 SE N60E 16 SW
Cross joints veins N80 W 80 NE
left lateral movement picture
(photos)

Brecciated dol in stream bed below

IRO 875 N20E 12 SE highly iron
WP 81 black slaty arg or dol inter
N37°07.772 beds in thick bded brn weath dol
W80°19.772

Cr IRO 876 N 50 E 70 NW
rd brn slaty argillite
along stream w/ massive dol (dk gy)
WP 082 N 37° 07.763' W 80° 19.737'
2028

IRO 877 N 60 E 60 SE gray grn, sl
N 37° 07.716 slaty arg. and fract.
W 80° 19.742 dolomite ~ 50 yds upstream
el 1789 from Mobile home

IRO 878 Ledges across stream and in
stream N 40 E 4° NW mass dol.
WP 084 el 1771 N 37° 07.655' W 080 19.672'

IRO 879 N 60 E 20 SE dk grey slaty
argillite ledges on stream across
from ruins of cabin. WP 085
N 37° 07.587' W 80° 19.528' el 1735
Joints N 80 W 80 NE N 20 W 72 NE

IRO 8710 N 66 E 60 SE dol ledges
in stream red brn soil on road
WP 086 el 1797 N 37° 07.621' W 80° 19.501'

IR 8711 N 76 E 70 SE thick dol beds
in strm grn slaty arg on road
[illegible] N 37° 07.790 W 80° 19.500 el 1907

IRO 8712 light tan charty soil
In cut along Farm Road
WP 88 N 3707969 W80 19, 391 el 1911
IRO 8713 lightan crev dol
FW 60 S WP 88 el 2159
N 37° 07, 985 W 80 19, 61'
IRO 8714 Otzite bldr terrace
below PL WP 90 N 37 08 012
Oct 27 2008 W80 19.684
IRO 8715 crinkly laminated
to medium gray dolomite with
yellow-orange weathered layers el 2180
N 80E 245E WP 91 N37°08.076' W80° 19.666'
IRO 841 round cobbles at end of
el 2179
road WP 92 N 37 08 427 W80 19.169