


COMMONWEALTH OF VIRGINIA
 DEPARTMENT OF MINES, MINERALS AND ENERGY
 DIVISION OF MINERAL RESOURCES

THIS PROJECT WAS PARTIALLY FUNDED BY THE
 UNITED STATES DEPARTMENT OF THE INTERIOR,
 GEOLOGICAL SURVEY, CONTRACT NUMBER
 14-08-0001-A-0076

SELECTED SLOPE CATEGORIES AND KARST FEATURES MAP OF GILES COUNTY, VIRGINIA

Elizabeth V. Miller and David A. Hubbard, Jr.

1986



PUBLICATION 70
 SELECTED SLOPE CATEGORIES AND
 KARST FEATURES MAP
 OF GILES COUNTY, VIRGINIA



EXPLANATION

Slope Categories

- > 35° (70%)
Steep to vertical slopes susceptible to rock fall.
- 15° to 35° (30% to 70%)
Moderate to steep slopes, large areas of colluvium, susceptible to rapid slope failure, creep failure common.
- 0° to 15° (0% to 30%)
Low to moderate slope, predominant slope failure by creep.

KEY

- ▲ Sinkholes. Size of triangles related to size of sinkholes.
- Area of subsidence.
- Cave openings.
- ||||| Landslide deposits: Large intact rock blocks, boulders, cobbles, sand, silt, and clay.

REFERENCES

Bollinger, G.A., Ehlers, E.G., Jr., Marx, R.E., and Alger, W.C., 1985. Estimation of earthquake effects on buildings, lifelines, and residents in Giles County, Virginia. Virginia Polytechnic Institute and State University, Seismological Observatory, Blacksburg, Virginia, 99 p.

Douglas, H.H., 1964. Caves of Virginia: Virginia Cave Survey, Falls Church, Virginia, 761 p.

Holinger, J.R., 1973. Descriptions of Virginia caves. Virginia Division of Mineral Resources Bulletin 65, 450 p.

Lucas, P.C., 1985. Written communication. Virginia Speleological Survey, 4411 Fallon Oak Drive, Chantilly, Virginia 22021.

Miller, E.V., 1985. Graphical and digital slope stability analysis for Giles County, Virginia: unpublished M.S. thesis, Virginia Polytechnic Institute and State University, Blacksburg, Virginia, 193 p.